Submit 1 Copy To Appropriate District State of New Mexico	Form C-103
Office District I – (575) 393-6161 Energy, Minerals and Natural Resource	Revised August 1, 2011
<u> </u>	WELL API NO.
District II – (575) 748-1283 OCD OIL CONSERVATION DIVISION  District III – (505) 334-6178 1220 South St. Francis Dr.	30-025-35450
811 S. First St., Artesia, NM 882 10 OIL COINSERVATION DIVISION	5. Indicate Type of Lease
District III - (505) 334-6178  1000 Rio Brozos Rd. Aztec, NM 87410 & 6 2014  1220 South St. Francis Dr.	STATE ⊠ FEE □
1000 Rio Brazos Rd., Aztec, NM 87410 2 6 2014  District IV – (505) 476-3460  District IV – (505) 476-3460  Santa Fe, NM 87505	6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM	
87505	
SUNDRY NOTICES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH	North Hobbs (G/SA) Unit
PROPOSALS.)	24
1. Type of Well: Oil Well  Gas Well  Other	8. Well Number
/	612
2. Name of Operator	9. OGRID Number: 157984
Occidental Permian Ltd.	
3. Address of Operator	10. Pool name or Wildcat
2611 State Hwy 214 Denver City, TX 79323	Hobbs (G/SA)
4. Well Location	
4. Well Location  Unit Letter E: 230 feet from the North line and40	6 feet from the West line
Section 24 C Township 18S Range 37E	NMPM Lea County
11. Elevation (Show whether DR, RKB, RT, GR 3676' KB	(, etc.)
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:	
·	
PERFORM REMEDIAL WORK ☑ PLUG AND ABANDON ☐ REMEDIAL WORK ☐ ALTERING CASING ☐	
TEMPORARILY ABANDON	
<u>_</u>	MENT JOB
DOWNHOLE COMMINGLE	
OTHER: OTHER:	
	ls and give pertinent dates, including estimated date
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of	
proposed completion or recompletion.	e Completions. Attach wendore diagram of
• • • •	
During this p	rocedure we plan to use
1. RUPU and POOH W/ESP equipment the closed-lo	op system with a steel
2. Treat if necessary for conditions found tank and hau	Il contents to the required
3. Run ESP equipment disposal per	ODC Rule 19.15.17
4. RDPU and clean location	
1. Table and clean location	
·	
Spud Date: Rig Release Date:	
I hereby certify that the information above is true and complete to the best of my know	wledge and belief.
SIGNATURE Stave Show TITLE Lift Specialist DATE 6/25/2014	
Type or print nameSteve Snead E-mail address: steve_snead@oxy.com_PHONE: 806-592-6312	
For State Use Only 11	
Waling Manager Distance of the second	
APPROVED BY: MULLY STOWN TITLE SUCCESSION DATE 6/30/2014	
Conditions of Approval (if any):	

JUL 0 1 2014