

HOBBS OCD

Submit One Copy To Appropriate District Office
District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

NOV 13 2013

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
Revised November 3, 2011

RECEIVED OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

WELL API NO. 30-025-40199
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. UB-971
7. Lease Name or Unit Agreement Name Murphy 35 State
8. Well Number 1
9. OGRID Number 16696
10. Pool name or Wildcat Wildcat Yeso

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: Oil Well Gas Well Other SWD

2. Name of Operator
OXY USA Inc.

3. Address of Operator
1502 W Commerce Dr., Carlsbad, NM 88220

4. Well Location
Unit Letter N: 950 feet from the **SOUTH** line and 1700 feet from the **WEST** line
Section 35 Township 16S Range 32E NMPM _____ County Lea

11. Elevation (Show whether DR, RKB, RT, GR, etc.)
4271' GR

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data


E-PERMITTING - CSNG _____ PERFORM P&A _____ TA _____ ON <input type="checkbox"/> TEMPORARY COMP _____ NEW WELL _____ <input type="checkbox"/> PULL OR LOC CHG _____ <input type="checkbox"/> OTHER: _____ <input type="checkbox"/>	SUBSEQUENT REPORT OF: REMEDIAL WORK <input type="checkbox"/> ALTERING CASING <input type="checkbox"/> COMMENCE DRILLING OPNS. <input type="checkbox"/> P AND A <input type="checkbox"/> CASING/CEMENT JOB <input type="checkbox"/> <input checked="" type="checkbox"/> Location is ready for OCD inspection after P&A
--	--

- All pits have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan.
- Rat hole and cellar have been filled and leveled. Cathodic protection holes have been properly abandoned.
- A steel marker at least 4" in diameter and at least 4' above ground level has been set in concrete. It shows the

OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUARTER/QUARTER LOCATION OR UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. ALL INFORMATION HAS BEEN WELDED OR PERMANENTLY STAMPED ON THE MARKER'S SURFACE.

- The location has been leveled as nearly as possible to original ground contour and has been cleared of all junk, trash, flow lines and other production equipment.
- Anchors, dead men, tie downs and risers have been cut off at least two feet below ground level.
- If this is a one-well lease or last remaining well on lease, the battery and pit location(s) have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, production equipment and junk have been removed from lease and well location.
- All metal bolts and other materials have been removed. Portable bases have been removed. (Poured onsite concrete bases do not have to be removed.)
- All other environmental concerns have been addressed as per OCD rules.
- Pipelines and flow lines have been abandoned in accordance with 19.15.35.10 NMAC. All fluids have been removed from non-retrieved flow lines and pipelines.
- If this is a one-well lease or last remaining well on lease: all electrical service poles and lines have been removed from lease and well location, except for utility's distribution infrastructure.

When all work has been completed, return this form to the appropriate District office to schedule an inspection. JUL 16 2014

SIGNATURE  TITLE HES SPECIALIST DATE 11-8-13

TYPE OR PRINT NAME Chris Jones E-MAIL: Christopher_Jones@oxy.com PHONE: 575-628-4121

For State Use Only
APPROVED BY: Neal Whitaker TITLE Compliance Officer DATE 7/15/2014