

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 5-27-2004

FILE IN TRIPLICATE

OIL CONSERVATION DIVISION

DISTRICT I
1625 N. French Dr., Hobbs, NM 88240

1220 South St. Francis Dr.
Santa Fe, NM 87505

DISTRICT II
1301 W. Grand Ave, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd, Aztec, NM 87410

WELL API NO. 30-025-41551	
5. Indicate Type of Lease STATE ☐ FEE ☒	
6. State Oil & Gas Lease No.	
7. Lease Name or Unit Agreement Name North Hobbs (G/SA) Unit Section 19	
8. Well No. 947	
9. OGRID No. 157984	
10. Pool name or Wildcat Hobbs (G/SA)	

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (Form C-101) for such proposals.)	
1. Type of Well: Oil Well ☒ Gas Well ☐ Other ☐	
2. Name of Operator Occidental Permian Ltd.	
3. Address of Operator HCR 1 Box 90 Denver City, TX 79323	
4. Well Location Unit Letter <u>A</u> : <u>278</u> Feet From The <u>North</u> Line and <u>1123</u> Feet From The <u>East</u> Line Section <u>19</u> Township <u>18-S</u> Range <u>38-E</u> NMPM <u>Lea</u> County	
11. Elevation (Show whether DF, RKB, RTGR, etc.) 3678' KB	
Pit or Below-grade Tank Application ☐ or Closure ☐ Pit Type _____ Depth of Ground Water _____ Distance from nearest fresh water well _____ Distance from nearest surface water _____ Pit Liner Thickness _____ mil Below-Grade Tank: Volume _____ bbls; Construction Material _____	

12. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐ TEMPORARILY ABANDON ☐ CHANGE PLANS ☐ PULL OR ALTER CASING ☐ Multiple Completion ☐ OTHER: _____ ☐	SUBSEQUENT REPORT OF: REMEDIAL WORK ☐ ALTERING CASING ☐ COMMENCE DRILLING OPNS. ☐ PLUG & ABANDONMENT ☐ CASING TEST AND CEMENT JOB ☐ OTHER: <u>OAP/Acid treat</u> ☒

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.
1. RUPU & RU.
 2. RU wire line & perforate tubing @4265'.
 3. ND wellhead/NU BOP.
 4. POOH & lay down ESP equipment.
 5. RIH w/bit. Tag @4626'. POOH w/bit.
 6. RU wire line and perforate casing at 4336-50', 4356-65' @4 JSPF. RD wire line.
 7. RIH w/treating packer set @4453'. RU Rising Star and acid treat perfs w/3000 gal of 15% NEFE acid in two settings. RU pump truck and pump scale squeeze with 100 bbl fresh water mixed with 60 gal of 6490 chemical. Flush w/200 bbl of 10# brine water. RD pump truck. POOH w/treating packer.
 8. RIH w/ESP equipment set on 131 jts of 2-7/8" tubing. Intake set @4320'.
 9. ND BOP/NU wellhead.
 10. RDPU & RU. Clean location and return well to production.
- RUPU 06/06/2014 RDPU 06/11/2014

I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been/will be constructed or closed according to NMOCD guidelines ☐ , a general permit ☐ or an (attached) alternative OCD-approved ☐ plan


SIGNATURE Mendy A. Johnson TITLE Administrative Associate DATE 07/28/2014
 TYPE OR PRINT NAME Mendy A. Johnson E-mail address: mendy.johnson@oxy.com TELEPHONE NO. 806-592-6280

For State Use Only
 APPROVED BY Mary Brown TITLE Dist Supervisor DATE 7/30/2014
 CONDITIONS OF APPROVAL IF ANY:

JUL 30 2014

July 28, 2014

Work Plan Report for Well:NHSAU 947-19



Survey Viewer