Submit I Copy To Appropriate District Office District I  HOBBS OCD State of New Mexico Energy, Minerals and Natural Resources	Form C-103 October 13, 2009
1625 N French Dr. Hobbs NM 88240	WELL API NO.
District II 1301 W. Grand Ave., Artesia, NM 88210  SEP 0 3.2014 CONSERVATION DIVISION	30-025-10539
District III 1220 South St. Francis Dr.	5. Indicate Type of Lease  STATE FEE
1000 Rio Brazos Rd., Aztec, NM 87410 District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505  RECEIVED Santa Fe, NM 87505	6. State Oil & Gas Lease No. 307841
SUNDRY NOTICES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	SKELLY PENROSE B UNIT
1. Type of Well: Oil Well Gas Well Other TA'd Injection	8. Well Number 014
2. Name of Operator PROVIDENCE ENERGY SERVICES, INC. dba KELTON OPERATING	9. OGRID Number 012444
3. Address of Operator P.O. BOX 928, ANDREWS, TEXAS 79714-0928	10. Pool name or Wildcat LANGLIE MATTIX (37240)
4. Well Location	
Unit Letter N : 990 feet from the SOUTH line and 2310 feet from the WEST line	
Section 32 Township 22S Range 37E NMPM LEA County  11. Elevation (Show whether DR, RKB, RT, GR, etc.)	
12. Charle Assuranciata Dan to Indianta Natura ak Nation Dansart on Other Date	
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:  PERFORM REMEDIAL WORK ☑ PLUG AND ABANDON ☑ REMEDIAL WORK ☑ ALTERING CASING ☑	
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRI	
PULL OR ALTER CASING   MULTIPLE COMPL   CASING/CEMEN	TJOB 🗆
DOWNHOLE COMMINGLE	
OTHER: OTHER:	
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.	
1. Move in and rig up pulling unit.	
2. Unset AD-1 packer and pull out of hole.	
<ul> <li>3. Run 5 ½" CIBP and set at 3600' +/</li> <li>4. Leave tubing in the hole ready to plug and abandon well upon approval and availability.</li> </ul>	
4. Leave tubing in the note-ready to plug and abandon wen upon approval and	availability.
START DATE: UPON APPROVAL L SUBMIT C-103 FOR PEA PRIOR TO STARTING JOB - WILL NEED APPROVAL. MUS	
TO STARTING I	DD - WILL NOED
APPROVAL.	ANNY
Spud Date: Rig Release Date:	
I hereby certify that the information above is true and complete to the best of my knowledge and belief.	
SIGNATURE	
Type or print name <u>C. Dale Kelton</u> E-mail address: <u>providenceenergy@suddenlink.net</u> PHONE: <u>432-661-1364</u>	
For State Use Only M 1 28 1	
APPROVED BY: Value Dist. Supervisor DATE 9/2/2014 Conditions of Approval (if any):	
	SEP 0 2 2014/

## Kelton Operating Corporation - WELL DIAGRAM

