Submit 1 Copy To Appropriate District	State - SNI M.	·		F C 100
Office Distance Minute and Network Distance Distance of Network Distance Di		Form C-103 Revised July 18, 2013		
District I – (575) 393-6161 Energy, Minerals and Natural Resources 1625 N. French Dr., Hobbs, NM 88240			WELL API NO.	sed July 18, 2013
District II - (575) 748-1283			30-025-00298	-
811 S. First St., Artesia, NM 88210 OIL CONSERVATION DIVISION District III – (505) 334-6178 1220 South St. Francis Dr.		÷ •	5. Indicate Type of Lease	i
1000 Rio Brazos Rd., Aztec, NM 87410 Sonto Ec. NIM 87505		Sec. 12.	STATE FE 6. State Oil & Gas Lease No	
District IV - (505) 476-3460 Salita FC, 1NIVI 87505 1220 S. St. Francis Dr., Santa Fe, NM			6. State OII & Gas Lease No).
87505	CEC AND DEPODETS ON WELLS		7.1	
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A			7. Lease Name or Unit Agree	sement Name
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR BUSIC			ROCK QUEEN UNIT	
PROPOSALS.) 1. Type of Well: Oil Well Gas Well Other			8. Well Number 77	
2. Name of Operator SEP 1 5 2014			9. OGRID Number	
LEGACY RESERVES OPERATING LP /			240974	
3. Address of Operator	8, MIDLAND, TX 79702	RECEIVED	10. Pool name or Wildcat CAPROCK; QUEEN	
4. Well Location			CAI KOCK, QUELIN	· · · · · · · · · · · · · · · · · · ·
4. Well Location Unit Letter <u>K</u> : 1980 feet from the <u>NORTH</u> line and 1980 feet from the <u>EAST</u> line				
Section 30	Township 13S	Range 32E		inty LEA
	11. Elevation (Show whether DR,	Y		
	4377' KB	,,,,		
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data				
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:				
PERFORM REMEDIAL WORK Z PLUG AND ABANDON REMEDIAL WORK				
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRIL				
PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMENT J			ГЈОВ 🗌	
		OTHER:		_
OTHER: 13 Describe proposed or compl	Leted operations. (Clearly state all p		give pertinent dates includir	
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of				
proposed completion or recompletion.				
POOH w/production tubing and pump.				
Clean out to TD at 3081' and log. Perforate 18' of main pay sand based on log.				
Acidize w/1500 gals 80/20 mixture of inhibited 7-1/2% NEFE HCL/toluene.				
Run production packer, tubing, gaslift and freshwater cap strings, and RWTP.				
Run production packer, tubing, gasint and neshwater cap strings, and Rwith.				
Spud Date:	Rig Release Da	ite:		
		<u> </u>		
I hereby certify that the information a	above is true and complete to the b	est of my knowledge	a and helief	<u>. </u>
Thereby certify that the information a	bove is true and complete to the of	est of my knowledge	e and bener.	
4.0-	,			
SIGNATURE LAWY ING	TITLE	REGULATORY	<u>FECH</u> DATE_ <u>09/11</u>	/2014
Type or print name LAURA P	PINA F-mail address:	lpina@legacylt	DECOM DHONE: 42	2 680 5200
For State Use Only			p.com PHONE: <u>432</u>	2-007-3200
	la ni	aloum Engineor	1 1	91.11.
APPROVED BY:				
Conditions of Approval (if any):				
			SEP 1 5 2014	

.

