

Submit 1 Copy To Appropriate District Office  
District I - (575) 393-6161  
1625 N. French Dr., Hobbs, NM 88240  
District II - (575) 748-1283  
811 S. First St., Artesia, NM 88210  
District III - (505) 334-6178  
1000 Rio Brazos Rd., Aztec, NM 87410  
District IV - (505) 476-3460  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy, Minerals and Natural Resources  
**HOBS OGD**  
**OIL CONSERVATION DIVISION**  
AUG 19 2014  
South St. Francis Dr.  
Santa Fe, NM 87505

Form C-103  
Revised July 18, 2013

<b>SUNDRY NOTICES AND REPORTS ON WELLS</b> (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		WELL API NO. 30-025-26713
1. Type of Well: Oil Well <input checked="" type="checkbox"/> Gas Well <input type="checkbox"/> Other <input type="checkbox"/>		5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
2. Name of Operator VANGUARD PERMIAN LLC		6. State Oil & Gas Lease No.
3. Address of Operator 5847 SAN FELIPE SUITE 3000, HOUSTON, TEXAS 77057		7. Lease Name or Unit Agreement Name GRIZZELL B
4. Well Location Unit Letter <u>FG</u> : 1838 feet from the North line and 1750 feet from the East line Section 8 Township 22S Range 37E NMPM Lea County		8. Well Number 4
11. Elevation (Show whether DR, RKB, RT, GR, etc.)		9. OGRID Number 258350
		10. Pool name or Wildcat PENROSE SKELLY GRAYBURG

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐  
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐  
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐  
DOWNHOLE COMMINGLE ☐  
CLOSED-LOOP SYSTEM ☐  
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☒ ALTERING CASING ☐  
COMMENCE DRILLING OPNS. ☐ P AND A ☐  
CASING/CEMENT JOB ☐  
OTHER: ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

11-21-13 - 12-25-13

RU and POOH with production equipment, make cleanout run with bit and casing scraper. Set composite bridge plug at 3865. Perforate squeeze holes at 3820-3821. RIH and set cement retainer at 3810, Pumped 360 sx class C w/2% CACL at 4 bpm @ 1487 psi. Wait 24hrs of cmt, Pu bit and drill out cmt retainer and cleanout well. Pressure test squeeze to 500 psi, good test. RU WL and ran cmt bond log from 3540-2480, good cmt to 2645, RIH with CBP and set at 3800. Perforate Grayburg 3660-3670, 3780-3790 with 2 spf, 120 phasing, 40 shots. Pump 4000 gals 15% NEFE acid to breakdown new perforations. Frac well with 89,260 lbs of propant. Put well back of production.

24 hrs test; Penrose Skelly Grayburg (50350) 33 BOPD, 88 MCF.

Spud Date:

Rig Release Date:

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Gaye Heard by Colleen Gernsey Agent DATE 3-19-14

Type or print name Gaye Heard E-mail address: gheard@oilreportsinc.com PHONE: 575-393-2727

For State Use Only

APPROVED BY: [Signature] TITLE Petroleum Engineer DATE 09/18/14

Conditions of Approval (if any):

SEP 19 2014

Zone Permanently Plugged (ZPP)  
Cunice San Andres SW