

Submit 3 Copies To Appropriate District Office
 District I
 1625 N. French Dr., Hobbs, NM 87240
 District II
 1301 W. Grand Ave., Artesia, NM 88210
 District III
 1000 Rio Brazos Rd., Aztec, NM 87410
 District IV
 1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
 Energy, Minerals and Natural Resources

Form C-103
 June 19, 2008

OIL CONSERVATION DIVISION
 1220 South St. Francis Dr.
 Santa Fe, NM 87505

WELL API NO. 30-025-27139
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name: North Hobbs G/SA Unit
8. Well Number 132
9. OGRID Number 157984
10. Pool name or Wildcat Hobbs; Grayburg-San Andres

SUNDRY NOTICES AND REPORTS ON WELLS
 (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:
 Oil Well Gas Well Other WIW **HOBBS OCD**

2. Name of Operator
 Occidental Permian Ltd. **OCT 03 2014**

3. Address of Operator
 P.O. Box 4294, Houston, TX 77210-4294

4. Well Location **RECEIVED**
 Unit Letter L; 1400 feet from the South line and 1300 feet from the West line
 Section 32 Township 18-S Range 38-E NMPM County Lea

11. Elevation (Show whether DR, RKB, RT, GR, etc.)
 3629' GR

12. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK PLUG AND ABANDON
 TEMPORARILY ABANDON CHANGE PLANS
 PULL OR ALTER CASING MULTIPLE COMPL
 DOWNHOLE COMMINGLE
 OTHER:

REMEDIAL WORK ALTERING CASING
 COMMENCE DRILLING OPNS. P AND A
 CASING/CEMENT JOB
 OTHER: Coiled Tubing Cleanout

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

9/29/14 - 9/30/14:

MI Coiled Tubing Unit. RU CTU x RIH w/perf cleaning tool to 4231'. Pull up to 4000' w/tool x water wash perfs from 4087' - 4185'. Pump 10 bbl gel sweep. Close backside x acid wash perfs w/2500 gal. 15% NEFE HCL. Let acid soak x pump second 10 bbl gel sweep x flow back returns. Circulate well clean. POOH with cleaning tool x RD CTU. Return well to injection.

Spud Date: RU - 9/29/14

Rig Release Date: RD - 9/30/14

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Mark Stephens TITLE Regulatory Compliance Analyst DATE 10/1/14
 Type or print name Mark Stephens E-mail address: Mark_Stephens@oxy.com PHONE (713) 366-5158

For State Use Only
 APPROVED BY Malay Brown TITLE Dist. Supervisor DATE 10/9/2014
 Conditions of Approval (if any):

OCT 09 2014

Handwritten initials