			HOBBS OCD			
Form 3160- 5 (August, 2007)	UNITED ST DEPARTMENT OF T BUREAU OF LAND M	THE INTERIOR	OCT 17 201		FORM APPROVED OMB No. 1004- 0137 Expires: July 31, 2010	- ·
	NDRY NOTICES AND R of use this form for proposa		LLS BEAFIVED	 Lease Seria If Indian, A 	I No. NMLC032096B Ilottee, or Tribe Name	
aband	oned well. Use Form 3160-3	(APD) for such prop	osals.			
	TRIPLICATE - Other Instru	uctions on page 2.		7. If Unit or C	A. Agreement Name and/o EBDU	r No.
1. Type of Well Image: Display the second	Other		-	8. Well Name		
2. Name of Operator				East B	linebry Drinkard U	nit #016
Apache Corporation 3a. Address		3b. Phone No. (inclus		9. API Well N	lo.	
303 Veterans Airpark Lane Suite Midland TX 79705	e 1000		18 1062	10. Field and 1	30-025-06526 Pool, or Exploratory Area	<u> </u>
4. Location of Well (Footage, Sec., T., R., M	A., or Survey Description)		Lat.		ce; B-T-D, North (2	22900)
330' FNL & 480' FEL UL A Sec 1	- <u></u>		Long.	11. County or Lea C		NM
12. CHECK APPROPRIATE BOX	(S) TO INDICATE NATURI	E OF NOTICE, REPO	RT, OR OTHER DA	TA	·····	
TYPE OF SUBMISSION		T	PE OF ACTION			
Notice of Intent	Acidize	Deepen	Production (Star	t/ Resume)	Water Shut-off	
	Altering Casing	Fracture Treat	Reclamation		Well Integrity	
X Subsequent Report	Casing Repair	New Construction	Recomplete		Other	
	Change Plans	Plug and abandon	X Temporarily Aba	ndon		
Final Abandonment Notice	Convert to Injection	Plug back	Water Disposal			
 Attach the Bond under which the w following completion of the involved testing has been completed. Final determined that the site is ready for final 	tionally or recomplete horizontally work will performed or provide the l operations. If the operation result Abandonment Notice shall be find	y, give subsurface locatio ne-Bond-Noon file with ults in a multiple comple	• the BLM/ BIA. Requi ion or recompletion in	rue vertical o red subsequen a new interv	depths or pertinent mar at reports shall be filed ral, a Form 3160-4 shal	cers and sau within 30 d be filed o
Attach the Bond under which the w following completion of the involved testing has been completed. Final	tionally or recomplete horizontally work will performed or provide the l operations. If the operation rest Abandonment Notice shall be fil inspection.)	y, give subsurface locatio ne-Bond-Noon file with ults in a multiple comple	ns and measured and t the BLM/ BIA. Requi ion or recompletion in	rue vertical o red subsequen a new interv	depths or pertinent mar at reports shall be filed ral, a Form 3160-4 shal	cers and san within 30 d be filed of
Attach the Bond under which the w following completion of the involved testing has been completed. Final determined that the site is ready for final Apache TA'd this wellbo 9/19/2014 MIRUSU PO 9/22/2014 POOH w/tbg 9/23/2014 RIH & set CIE 9/24/2014 Run MIT w/F	tionally or recomplete horizontally work will performed or provide the coperations. If the operation rest Abandonment Notice shall be fil inspection.) re, as follows: OH & LD rods & pump. g. WO BLM 3P @ 5694'; dump 35' c	y, give subsurface locatio ne Bond No. on file with ults in a multiple comple led only after all require ement on top of p	ns and measured and to the BLM/ BIA. Requi- ion or recompletion in ments, including reclam	rue vertical of red subsequen a new interv antion, have	depths or pertinent mar at reports shall be filed ral, a Form 3160-4 shal	cers and sau within 30 d be filed o
Attach the Bond under which the w following completion of the involved testing has been completed. Final determined that the site is ready for final Apache TA'd this wellbo 9/19/2014 MIRUSU PO 9/22/2014 POOH w/tbg 9/23/2014 RIH & set CIE	tionally or recomplete horizontally work will performed or provide the coperations. If the operation rest Abandonment Notice shall be fil inspection.) re, as follows: OH & LD rods & pump. g. WO BLM 3P @ 5694'; dump 35' c	y, give subsurface locatio ne Bond No. on file with ults in a multiple comple led only after all require ement on top of p	ns and measured and to the BLM/ BIA. Requi- ion or recompletion in ments, including reclam	rue vertical of red subsequen a new interv antion, have	depths or pertinent mar at reports shall be filed ral, a Form 3160-4 shal	cers and sa within 30 c be filed c
Attach the Bond under which the w following completion of the involved testing has been completed. Final determined that the site is ready for final Apache TA'd this wellbo 9/19/2014 MIRUSU PO 9/22/2014 POOH w/tbg 9/23/2014 RIH & set CIE 9/24/2014 Run MIT w/F E-PERMITTING	ionally or recomplete horizontally ork will performed or provide the loperations. If the operation rest Abandonment Notice shall be fil inspection.) re, as follows: OH & LD rods & pump. g. WO BLM BP @ 5694'; dump 35' c Paul Flowers, BLM to with P&A R 	y, give subsurface locatio ne Bond No. on file with ults in a multiple comple led only after all require ement on top of p	ns and measured and to the BLM/ BIA. Requi- ion or recompletion in ments, including reclam lug. Circ pkr fluid (copy of chart a OCD Col Accepted	d. ttached).	depths or pertinent mark treports shall be filed ral, a Form 3160-4 shal been completed, and th of Approval <u>CORD ONLY.</u>	kers and sa within ·30 · c b be filed c re operator
Attach the Bond under which the w following completion of the involved testing has been completed. Final determined that the site is ready for final Apache TA'd this wellbo 9/19/2014 MIRUSU PO 9/22/2014 POOH w/tbg 9/23/2014 RIH & set CIE 9/24/2014 Run MIT w/F E-PERMITTING P&A NR	tionally or recomplete horizontally work will performed or provide the operations. If the operation rest Abandonment Notice shall be fil inspection.) re, as follows: OH & LD rods & pump. g. WO BLM 3P @ 5694'; dump 35' c Paul Flowers, BLM to with P&A R COMP CHG LOC_	y, give subsurface locatio ne Bond No. on file with ults in a multiple comple led only after all require ement on top of p	ns and measured and to the BLM/ BIA. Requi- ion or recompletion in ments, including reclam lug. Circ pkr fluid (copy of chart a OCD Col Accepted	d. ttached).	depths or pertinent mark treports shall be filed ral, a Form 3160-4 shal been completed, and th of Approval	kers and sa within ·30 · c b be filed c re operator
Attach the Bond under which the w following completion of the involved testing has been completed. Final determined that the site is ready for final Apache TA'd this wellbo 9/19/2014 MIRUSU PO 9/22/2014 POOH w/tbg 9/23/2014 RIH & set CIE 9/24/2014 Run MIT w/F E-PERMITTING P&A NR INT TO P&A CSNG	ionally or recomplete horizontally ork will performed or provide the loperations. If the operation rest Abandonment Notice shall be fil inspection.) re, as follows: OH & LD rods & pump. g. WO BLM BP @ 5694'; dump 35' c Paul Flowers, BLM to with P&A R 	y, give subsurface locatio ne Bond No. on file with ults in a multiple comple led only after all require ement on top of p	ns and measured and to the BLM/ BIA. Requi- ion or recompletion in ments, including reclam lug. Circ pkr fluid (copy of chart a OCD Col Accepted	d. ttached).	depths or pertinent mark treports shall be filed ral, a Form 3160-4 shal been completed, and th of Approval <u>CORD ONLY.</u>	kers and sai within ·30 · ć i be filed c re operator
Attach the Bond under which the w following completion of the involved testing has been completed. Final determined that the site is ready for final Apache TA'd this wellbo 9/19/2014 MIRUSU PO 9/22/2014 POOH w/tbg 9/23/2014 RIH & set CIE 9/24/2014 Run MIT w/F E-PERMITTING P&A NR	tionally or recomplete horizontally work will performed or provide the operations. If the operation rest Abandonment Notice shall be fil inspection.) re, as follows: OH & LD rods & pump. g. WO BLM 3P @ 5694'; dump 35' c Paul Flowers, BLM to with P&A R COMP CHG LOC_	ement on top of p tness. MIT passed	ns and measured and to the BLM/ BIA. Requi- ion or recompletion in ments, including reclam lug. Circ pkr fluid (copy of chart a OCD Col Accepted	d. ttached).	depths or pertinent mark treports shall be filed ral, a Form 3160-4 shal been completed, and th of Approval <u>CORD ONLY.</u>	kers and sa within ·30 · c b be filed c re operator
Attach the Bond under which the w following completion of the involved testing has been completed. Final determined that the site is ready for final Apache TA'd this wellbo 9/19/2014 MIRUSU PO 9/22/2014 POOH w/tbg 9/23/2014 RIH & set CIE 9/24/2014 Run MIT w/F E-PERMITTING P&A NR INT TO P&A CSNG TA RE	tionally or recomplete horizontally work will performed or provide the operations. If the operation rest Abandonment Notice shall be fil inspection.) re, as follows: OH & LD rods & pump. g. WO BLM 3P @ 5694'; dump 35' c Paul Flowers, BLM to with P&A R COMP CHG LOC_	ement on top of p tness. MIT passec	ns and measured and to the BLM/ BIA. Requi- ion or recompletion in ments, including reclam lug. Circ pkr fluid (copy of chart a OCD Col Accepted	d. ttached). nditions for <u>RE(</u> quire <u>BL</u>	depths or pertinent mark treports shall be filed ral, a Form 3160-4 shal been completed, and th of Approval <u>CORD ONLY.</u>	kers and sa within ·30 · c b be filed c re operator
Attach the Bond under which the w following completion of the involved testing has been completed. Final determined that the site is ready for final Apache TA'd this wellbo 9/19/2014 MIRUSU PO 9/22/2014 POOH w/tbg 9/23/2014 RIH & set CIE 9/24/2014 Run MIT w/F E-PERMITTING P&A NR INT TO P&A CSNG TARE	tionally or recomplete horizontally vork will performed or provide the operations. If the operation rest Abandonment Notice shall be fil inspection.) re, as follows: OH & LD rods & pump. G. WO BLM 3P @ 5694'; dump 35' c Paul Flowers, BLM to with P&A R COMP CHG LOC BDMS CHART	ement on top of p tness. MIT passed	ns and measured and the BLM/ BIA. Requision or recompletion in ments, including reclams lug. Circ pkr fluid (copy of chart a OCD Con Accepted forms recompleted forms recomple	d. ttached). d. ttached). d. ttached). d for <u>RE(</u> quire <u>BL</u>	depths or pertinent mark treports shall be filed ral, a Form 3160-4 shal been completed, and th of Approval <u>CORD ONLY.</u>	kers and sai within ·30 · ć i be filed c re operator
Attach the Bond under which the w following completion of the involved testing has been completed. Final determined that the site is ready for final Apache TA'd this wellbo 9/19/2014 MIRUSU PO 9/22/2014 POOH w/tbg 9/23/2014 RIH & set CIE 9/24/2014 Run MIT w/F E-PERMITTING P&A NR INT TO P&A CSNG TA Reesa Fisher	tionally or recomplete horizontally vork will performed or provide the operations. If the operation rest Abandonment Notice shall be fil inspection.) re, as follows: OH & LD rods & pump. G. WO BLM 3P @ 5694'; dump 35' c Paul Flowers, BLM to with P&A R COMP CHG LOC BDMS CHART	ement on top of p tness. MIT passed	ns and measured and the BLM/ BIA. Requision or recompletion in ments, including reclams lug. Circ pkr fluid (copy of chart a OCD Con Accepted forms recompleted forms recomple	d. ttached). d. ttached). d. ttached). d for <u>RE(</u> quire <u>BL</u>	depths or pertinent mark treports shall be filed ral, a Form 3160-4 shal been completed, and th of Approval <u>CORD ONLY.</u>	kers and san within ·30 · d i be filed o he operator
Attach the Bond under which the w following completion of the involved testing has been completed. Final determined that the site is ready for final Apache TA'd this wellbo 9/19/2014 MIRUSU PO 9/22/2014 POOH w/tbg 9/23/2014 RIH & set CIE 9/24/2014 Run MIT w/F E-PERMITTING P&A NR INT TO P&A CSNG TA IA Name (Printed/ Typed) Reesa Fisher Signature: Kebsh Jisho	tionally or recomplete horizontally work will performed or provide the operations. If the operation rest Abandonment Notice shall be fil inspection.) re, as follows: OH & LD rods & pump. WO BLM 3P @ 5694'; dump 35' c Paul Flowers, BLM to with P&A R COMP CHG LOC BDMS CHART	ement on top of p tness. MIT passed Title: Date: 9/2: DR FEDERAL OR S Title:	ns and measured and the BLM/ BIA. Requision or recompletion in ments, including reclams lug. Circ pkr fluid (copy of chart a OCD Con Accepted forms recompleted forms recomple	d. ttached). d. ttached). d. ttached). d for <u>RE(</u> quire <u>BL</u>	depths or pertinent mark treports shall be filed ral, a Form 3160-4 shal been completed, and th of Approval <u>CORD ONLY.</u>	kers and sar within ·30 · d i be filed o he operator
Attach the Bond under which the w following completion of the involved testing has been completed. Final determined that the site is ready for final Apache TA'd this wellbo 9/19/2014 MIRUSU PO 9/22/2014 POOH w/tbg 9/23/2014 RIH & set CIE 9/24/2014 Run MIT w/F E-PERMITTING P&A NR INT TO P&A CSNG TA I4. Name (Printed/ Typed) Reesa Fisher Signature: Kebsh Jikho Approved by: Conditions of approval, if any are attach certify that the applicant holds legal or e which would entitle the apply	ionally or recomplete horizontally vork will performed or provide the operations. If the operation rest Abandonment Notice shall be fil inspection.) re, as follows: OH & LD rods & pump. WO BLM 3P @ 5694'; dump 35' c Paul Flowers, BLM to with P&A R COMP CHG LOC BDMS CHART THIS SPACE FC	ement on top of p tness. MIT passed Title: Date: 9/2: DR FEDERAL OR S Title: Date: 9/2: Date: 0 Date: 9/2: Date: DESA DESA DESA DESA DESA DESA DESA DESA	Ins and measured and the BLM/ BIA. Requision or recompletion in ments, including reclams lug. Circ pkr fluid (copy of chart a OCD Coll Accepted forms recompleted forms recompleted forms recompleted forms forms for the first of	d. ttached). nditions for <u>REC</u> quire <u>BL</u>	depths or pertinent mark treports shall be filed ral, a Form 3160-4 shall been completed, and th of Approval <u>CORD ONLY.</u> <u>M APPROVAL</u> Date:	All Fede
Attach the Bond under which the w following completion of the involved testing has been completed. Final determined that the site is ready for final Apache TA'd this wellbo 9/19/2014 MIRUSU PO 9/22/2014 POOH w/tbg 9/23/2014 RIH & set CIE 9/24/2014 Run MIT w/F E-PERMITTING P&A NR INT TO P&A TA Recesa Fisher Signature: Keesa Justo Approved by: Conditions of approval, if any are attach certify that the applicant holds legal or e	tionally or recomplete horizontally vork will performed or provide the operations. If the operation rest Abandonment Notice shall be fil inspection.) re, as follows: OH & LD rods & pump. WO BLM 3P @ 5694'; dump 35' cc Paul Flowers, BLM to with P&A R COMP CHG LOC BDMS CHART THIS SPACE FC ed. Approval of this notice does requitable title to those rights in the licant to conduct operation e 43 U.S.C. Section 1212, make	ement on top of p tness. MIT passed Title: Date: 9/2: DR FEDERAL OR S Title: not warrant or the subject lease on thereon. It a crime for any pers	Ins and measured and the BLM/ BIA. Requision or recompletion in ments, including reclams lug. Circ pkr fluid (copy of chart a OCD Coll Accepted forms recompleted forms recompleted forms recompleted forms forms for the first of	d. ttached). nditions for <u>REC</u> quire <u>BL</u>	depths or pertinent mark treports shall be filed ral, a Form 3160-4 shall been completed, and th of Approval <u>CORD ONLY.</u> <u>M APPROVAL</u> Date:	All Fede

.

