Submit 1 Copy To Appropriate District HOBBS OCD State of New Mexico Office	Form C-103
District I - (575) 393-6161 Energy, Minerals and Natural Resources 1625 N. French Dr., Hobbs, NM 88249 EC 07 2012 CONSERNATION DIVISION	Revised August 1, 2011 WELL API NO.
	30-025-03247
811 S. First St., Artesia, NM 88210 <u>District III</u> – (505) 334-6178 1220 South St. Francis Dr.	5. Indicate Type of Lease STATE FEE X
1000 Rio Brazos Rd., Aztec, NM 87410 RECEIVED District IV – (505) 476-3460 RECEIVED Santa Fe, NM 87505	STATE FEE X 6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM 87505	
SUNDRY NOTICES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH	WEST PEARL QUEEN UNIT
PROPOSALS.) 1. Type of Well: Oil Well X Gas Well Other	8. Well Number #103
2. Name of Operator	9. OGRID Number
STATE OF NEW MEXICO formerly Xeric Oil & Gas Corp	25482
3. Address of Operator 1625 N. French Drive Hobbs, NM 88240	10. Pool name or Wildcat PEARL QUEEN
4. Well Location	TEME QUEEN
Unit Letter_C:990feet from the _N line and1980	feet from theWline
Section 29 Township 19S Range 35E	NMPM County LEA
11. Elevation (Show whether DR, RKB, RT, GR, etc.)	
12. Check Appropriate Box to Indicate Nature of Notice, R	eport or Other Data
	SEQUENT REPORT OF:
PERFORM REMEDIAL WORK PLUG AND ABANDON X REMEDIAL WORI TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRI	-
PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMENT	
DOWNHOLE COMMINGLE	_
OTHER: OTHER:	П
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated	
date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.	
proposed completion of recompletion.	
SEE ATTACHED P&A PROCEDURE	
······································	
ic ID.	
Spud Date: Rig Release Date:	
I hereby certify that the information above is true and complete to the best of my knowledge	e and belief.
$\langle \Lambda_1, \Lambda_1, \Lambda_2 \rangle_{\Lambda_1}$	
SIGNATURE / Wash Title COMPLIANCE OFFICER DATE_12/07/2012_	
Type or print name _MARK WHITAKER	
BY: TITLE DET. MOT	DATE 2-14-2013
Conditions of Approval (if any):	

State of New Mexico formerly Xeric Oil & Gas Corp West Pearl Queen Unit No. 103

Set CIBP at 4750' and cap w/ 25 sx cmt. Pressure test csg. Circulate hole w/ 9.5 ppg brine w/ 25 sx salt gel per 100 bbls. Perforate at 3400'. Attempt to sqz/ 30 sx cmt. WOC and Tag Perforate at 1900'. Attempt to sqz/ 40 sx cmt. WOC and Tag Perforate at 160'. Circulate cmt to surface. Cut off wellhead and install dry hole marker.

LUGGING & ABANDONMENT WORKSHEET (2 STRING CSNG) OPERATOR ST. of NM formerly XERIC OIL Gas LEASENAME WEST PEARL QUEEN UNIT WELL t# 103 29 TWN SECT 195 RNG 35E FROM 990(N/S L 1980 E(W)L FORMATION @ TO Queen TD: PBTD: FORMATION @ PBTD SIZE SET @ TOC TOC DETERMINED BY 133/8 SURFACE 133/8 108 CIRC @_108' 11"hole drilled to INTMED 1 1820 TOC CIRC INTMED 2 5/2 5020 w/250 5x 8"HOLE PROD SIZE TOP BOT TOC DETERMINED BY Drilled 11" LINER 1 hole to 1820' LINER 2 CUT & PULL @ TOP - BOTTOM INTMED 1 4840 - 4850 PERFS INTMED 2 5020 - 5039 OPERATION PROD *REQUIRED PLUGS DISTRICT I 52155 RUTTLER (AHETTE) PLUG TYPE SYCKS DEPTH @ 5020 YATES PLUG CMNT TOC unknown QUEEK EXAMPLES W/ 250 8x GRAYBURG rwan. OH35 EXZ 6400 8"hole KA ANDERS 2LXX1#1 SHOE 50 SXS 5350'-5150' from 1900' 1. SALT ruxi i s CIBP/35 1820' to TD CANTAK KEEK awn **CIBP** 25 SXS 48001 B. SALT 33∞′ PLU014 STUB 50 SXS 3600-3700 DELATATE PLUS 85 REINR SOZ 200505 400 BELL CARTOR rwise SURF 10505 0-10' CHELLYCURYOK noon PATRIET CANTON nixia: BOKEE E28EHJ tours. RUSIA OCORIETA NEW 15 ELINGBERY PLUSIC TURE THEMM DEDICALD 310UM TUDIO I PLUUM 10 KC. PLUUS # RENN rwi STEATS ATOKA TD 5039 7-025-03247 WOLLDON MIII HYTHONYSO