Submit 1 Copy To Appropriate District Office	State of New M		Form C-103	
<u>District I</u> – (575) 393-6161 1625 N. French Dr., Hobbs, NM 88240	Energy, Minerals and Nat	tural Resources	Revised August 1, 2011 WELL API NO.	
<u>District II</u> – (575) 748-1283 811 S. First St., Artesia, NM 88210	OIL CONSERVATION	N DIVISION	30-025-03219	
<u>District III</u> – (505) 334-6178	1220 South St. Fra	ancis Dr.	5. Indicate Type of Lease STATE FEE XX	
1000 Rio Brazos Rd., Aztec, NM 87410 <u>District IV</u> – (505) 476-3460	Santa Fe, NM 8	37505	6. State Oil & Gas Lease No.	
1220 S. St. Francis Dr., Santa Fe, NM 87505				
SUNDRY NOTION	CES AND REPORTS ON WELL		7. Lease Name or Unit Agreement Name	
(DO NOT USE THIS FORM FOR PROPOS DIFFERENT RESERVOIR. USE "APPLIC			East Pearl Queen Unit	
PROPOSALS.)		HOBBS OCD	8. Well Number 37	
2. Name of Operator	das well Offici		9. OGRID Number	
State of New Mexico formerly Xeri	c Oil & Gas Corp.	OV 04 2014	25482	
3. Address of Operator 1625 N. French Drive Hobbs, No.	ew Mexico 88240		 Pool name or Wildcat Pearl Queen 	
4. Well Location		RECEIVED	reari Queen	
Unit LetterO:660 feet from the S line and1980 feet from the E line				
Section 27	Township 19S	Range 35E	NMPM County Lea	
Marie (A. 1922) and the control of t	11. Elevation (Show whether D			
			表现的主义	
12 Charles	manufacta Day to Indicate	Noture of Nation	Danaut au Othau Data	
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data				
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:				
PERFORM REMEDIAL WORK TEMPORARILY ABANDON	PLUG AND ABANDON XX CHANGE PLANS	REMEDIAL WOR	RK ☐ ALTERING CASING ☐ ☐ RILLING OPNS.☐ P AND A ☐	
PULL OR ALTER CASING	CHANGE PLANS MULTIPLE COMPL	CASING/CEMEN		
DOWNHOLE COMMINGLE		0,10,110,102,112,1		
OTHER.		OTUED	П	
OTHER: 13. Describe proposed or complete.	eted operations (Clearly state al	OTHER:	nd give pertinent dates, including estimated date	
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of				
proposed completion or recompletion.				
SEE ATTACHMENTS: PROCEDURE & SCHEMATIC				
SEE ATTACHMENTS. TROCEDORE & SCHEWATTC				
Smud Data:	Rig Release I	Datas		
Spud Date:	Kig Kelease I	Jaie.		
	·			
I hereby certify that the information	above is true and complete to the	best of my knowled	ge and belief.	
\sim M \sim				
SIGNATURE TITLE Compliance Officer DATE 7/5/2013				
.'ype or print name E-mail address: PHONE: _575-393-6161				
For State Use Only				
APPROVED BY: 1 Wash Whoteham TITLE COmphance Utiliar DATE 1/11/2013				
Conditions of Approval (if any): NOV 0 4 2014				

State of New Mexico formerlyXERIC OIL & GAS_	
LEASE NAME_ EAST_PEARL QUEEN UNIT#3'	API 30-0 25 - 032 19
U.L. O Section 27 -T 19 S-R 35 E FRO	DM_[660 #/S L, 1980 E/W L.

SPECIAL NOTE—Mud Laden Fluid will consist of 9.5# brine with 12.5# Salt Gel per BBL (25 sacks of gel/per 100 BBLS Brine). All cement plugs will be 25 sacks of cement or 100', whichever is greater. **Unless otherwise specified in the approved procedure**, cement plugs shall consist of class "C" for depths to 7500'. Class "H" will be used for plugs deeper than 7500'.

1. MIRU plugging unit. Lay down production equipment.

2. Set CIBP @ 4521 '. Circulate MLF. Spot 25 sxs cmt on CIBP. PRESSURE TEST CSG.

- 3. Perf/Sqz_or Spot 25 sxs cmt @ 3450 '. If perf, WOC & TAG.
- 4. Perf /Sqz or Spot 25 sxs cmt @ 1800 '. If perf, WOC and TAG.
- 5. Perf/Sqz or Spot @ **350**, w/ sufficient volume to circ cmt to surface inside/outside of csg strings.
- 6. Cutoff wellhead and anchors, install marker.

-----SPECIAL NOTES-----

