

Submit 1 Copy To Appropriate District Office
District I - (575) 393-6161
1625 N. French Dr., Hobbs, NM 88240
District II - (575) 748-1283
811 S. First St., Artesia, NM 88210
District III - (505) 334-6178
1000 Rio Brazos Rd., Aztec, NM 87410
District IV - (505) 476-3460
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
Revised July 18, 2013

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

WELL API NO. 30-025-05057
5. Indicate Type of Lease STATE ☐ FEE ☒
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name Turner -D-
8. Well Number 1
9. OGRID Number 217598
10. Pool name or Wildcat Gladiola Devonian SW
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3895' GR

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-10) FOR PROPOSALS.)

1. Type of Well: Oil Well ☒ Gas Well ☐ Other ☐

2. Name of Operator
Aspen Operating Company, LLC

3. Address of Operator
1300 S University Dr. STE 200 Fort Worth, TX 76107

4. Well Location
Unit Letter N North: 660 feet from the South line and 1980 feet from the West line
Section 27 Township 12S Range 37E NMPM County Lea

11. Elevation (Show whether DR, RKB, RT, GR, etc.)
3895' GR

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐
DOWNHOLE COMMINGLE ☐
CLOSED-LOOP SYSTEM ☐
OTHER: ☐

E-PERMITTING

R P&A NR P&A R
C INT TO P&A P.M. COMP
C CSNG CHG Loc
TA RBDMS CHART
OTHER: ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

OTD: 12259' It is proposed to plug and abandon this well in the following manner:

1. MIRU PU. ND WH, NU BOP and POOH w/ tubing
2. RIH w/ 5 1/2" CIBP on 2 7/8" tubing and set CIBP @ 12230' w/ 5 sks on top. POOH CIRC MLF.
3. RIH w/ 5 1/2" CIBP on 2 7/8" tubing and set CIBP @ 11120' w/ 5 sks on top. POOH to 9650'
4. Spot a 200' plug (20 sks) from 9650'-9450' across Wolfcamp. POOH to 7880' 9885-9450' 50SXS.
5. Spot a 200' plug (20 sks) from 7880' - 7680' across Abo. POOH to 5900' WOC TAG
6. Spot a 200' plug (20 sks) from 5900' - 5700' across Glorieta. POOH to 4500' WOC TAG
7. Spot a 200' plug (20 sks) from 4500' - 4300' across casing shoe. POOH to 2260' WOC TAG
8. Spot a 200' plug (20 sks) from 2260' - 2060' POOH to 70' WOC TAG
9. Spot a 70' plug (10 sks) from 70' - surface. PERF @ 417' CIRC CMT TO SURFACE INSIDE OUT.
10. POOH w/ tubing, ND BOP.
11. Cut off wellhead and install 4" dry hole marker to designate a plugged and abandoned location.

Spud Date:

Rig Release Date:

The Oil Conservation Division

MUST BE NOTIFIED 24 Hours

Prior to the beginning of operations

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Michael Wilson TITLE Production Manager DATE 10/31/14

Type or print name MICHAEL WILSON E-mail address: mwilson@aspen-oil.com PHONE: 817-455-2311

For State Use Only

APPROVED BY: Mary Brown TITLE Dist. Supervisor DATE 11/6/2014

Conditions of Approval (if any):

NOV 06 2014

Turner D1

Lease #

API: 30-025-05057

660' FSL & 1980' FWL

T12S R37E, Sec. 27

Lea County, New Mexico

KB: 3895.0'
DF: 3895.0'
GL: 3895.0'
Datum: 0.0' above GL

Plugging steps in BOLD Underline

Surface Casing: 13 3/8" 48# @ 367' w/ 400 sks of

10 sks 70'-surface

MOVE TO

20 sks 2260'-2060'
25

Perf @ 2210' & SQZ under Ret @ 2180' w/ 110sks
(10-1-1986)

Intermediate Casing: 8 5/8" 24# & 32# @ 4449' w/
1938 sks circ to surface

Perf @ 4465' & SQZ under Ret @ 4430' w/ 100sks
(10-1-1986)

25
20 sks 4500'-4300'

Perf & SQZ 25 sks @ 5900'

20 sks 5900'-5700' (Glorieta Formation)

Perf & SQZ 25 sks @ 7880'

20 sks 7880'-7680' (Abo Formation)

SQZ'd Wolfcamp perfs 9595'-9835' (9-30-1968)

50
20 sks 9650'-9450' (Wolfcamp Formation)
9885-9450

TOC @ 10,920'

CIBP @ 11120' w/ 5 sks

Perfs: 11166, 11167, 11168, 11169, 11170, 11171,
11172, 11174 (Atoka)

Production Casing: 5 1/2" 17# & 20# @ 12247' w/
300 sks TOC @ 10,920'

CIBP @ 12230' w/ 5 sks

Open hole Devonian: 12254-12259

PBTD: 12259

TD: 12259

Updated: 10/30/2014

Adam Joosten

Aspen Operating Company, L.L.C.
1300 S. University Dr. STE 200
Fort Worth, TX 76107



10/30/2014

Turner D1

KB: 3895.0'
DF: 3895.0'
GL: 3895.0'
Datum: 0.0' above GL

Lease #
API: 30-025-05057
660' FSL & 1980' FWL
T12S R37E, Sec. 27
Lea County, New Mexico

Surface Casing: 13 3/8" 48# @ 367' w/ 400 sks of
cement circ to surface

Perf @ 2210' & SQZ under Ret @ 2180' w/ 110sks
(10-1-1986)

Intermediate Casing: 8 5/8" 24# & 32# @ 4449' w/
1938 sks circ to surface

Perf @ 4465' & SQZ under Ret @ 4430' w/ 100sks
(10-1-1986)

SQZ'd Wolfcamp perms 9595'-9835' (9-30-1968)

TOC @ 10,920'

Perfs: 11166, 11167, 11168, 11169, 11170, 11171,
11172, 11174 (Atoka)

Production Casing: 5 1/2" 17# & 20# @ 12247' w/
300 sks TOC@ 10,920'

Open hole Devonian: 12254-12259

PBTD: 12259
TD: 12259

Updated: 10/27/2014
Adam Joosten