OCD Permitting

District 625 N. French Dr., Hobbs, NM 88240 State of New Mexico							İ	Form C-103 August 1, 2011				
Phone: (575) 393-6161 Fax: (575) 393-0720 District II 811 S. First St., Artesia, NM 88210	Energy, Minerals and Natural							Permit 195332				
Phone:(575) 748-1283 Fax:(575) 748-9720 District III 1000 Rio Brazos Rd., Aztec, NM 87410	Resources							WELL API NUMBER 30-025-41298				
Phone:(505) 334-6178 Fax:(505) 334-6170 District IV	Oil Conservation Division 1220 S. St Francis Dr.							5. Indicate Type of Lease S				
1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462	Santa Fe, NM 87505							6. State Oil & Gas Lease No.				
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR, USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)						DIR.	7. Lease Name or Unit Agreement Name BECKNELL STATE COM					
1. Type of Well:								8. Well Number 001H				
Name of Operator COG OPERATING LLC								9. OGRID Number 229137				
3. Address of Operator								10. Pool name or Wildcat				
One Concho Center, 600 W. Illinois Ave, Midland, TX 79701 4. Well Location Unit Letter I : 2450 feet from the S line and feet 660 from the E line Section 5 Township 21S Range 33E NMPM County Lea .												
11. Elevation (Show whether DR, KB, BT, GR, etc.) 3767 GR												
Pit or Below-grade Tank Application or Closure												
Pit Type Depth to Groundwater Distance from nearest fresh water well Distance from nearest surface water Pit Liner Thickness: mil Below-Grade Tank: Volume bbls; Construction Material												
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data												
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK TEMPORARILY ABANDON CHANGE OF PLANS PULL OR ALTER CASING MULTIPLE COMPL Other: Other: OTHER OF INTENTION TO: SUBSEQUENT I REMEDIAL WORK COMMENCE DRILLING OPNS. CASING/CEMENT JOB Other: Drilling/Cement								REPORT OF: ALTER CASING PLUG AND ABANDON KX				
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work.) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion. 10/28/14 TD 8 3/4" lateral @ 21305' (KOP @ 10982'). Set 5 1/2" 17# P-110 csg @ 21286'. Cmt w/1400 sx Class H. Tailed in w/2800 sx. Circ 363 sx to surface. 11/1/14 Rig released.9/26/2014 Spudded well. Casing and Cement Program												
Date String Fluid Hole	Csg Weight	Grade	Est	Dpth	Sacks	Yield	Class	1"	Pres	Pres	Open	
Type Size 09/29/14 Surf 17.5	Size lb/ft 13.375 54.5	J55	TOC 0	Set 17 54	1300		С	Dpth	Held 1500	Drop 0	Hole	
10/05/14 Int1 12.25	9.625 40	J55	0	5476	2700		Ċ		1500	Ö		
10/30/14 Prod 8.75	5.5 17	P110	0	21286	4200		Н					
I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been/will be constructed or closed according to NMOCD guidelines □, a general permit □ or an (attached) alternative OCD-approved plan □.												
SIGNATURE	TITLE	_			DATE							
Type or print name	E-mail address	_			Telephone	e No.	_					
For State Use Only:												
APPROVED BY: Paul Kautz TITLE			Geologist DATE				<u>11</u>	11/12/2014 11:01:02 AM				

NOV 1 3 2014

