Submit I Copy To Appropring OBBS OCD State of New Mexico	Form C-103
District 1 – (575) 393-6161 Energy, Minerals and Natural Resources	Revised August 1, 2011 WELL API NO.
1625 N. French Dr., Hobbs, NM 83340 19 2014 District II - (575) 748-1283 NOV 19 2014	30-005-29212
Bill S. First St., Artesia, NM 88210 District III – (505) 334-6178	5. Indicate Type of Lease
1000 Rio Brazos Rd. Azter No IZ40 L V LD	STATE FEE
District IV – (505) 476–3460 Santa Fe, NM 87505	6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM 87505	
SUNDRY NOTICES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH	
PROPOSALS.)	Lucas Fee
1. Type of Well: Oil Well 🛛 Gas Well 🗌 Other	8. Well Number
2. Name of Operator	9. OGRID Number
Energex LLC	296260
3. Address of Operator	10. Pool name or Wildcat
4425 98th Street, Suite 200, Lubbock TX 79424	Milnesand; Penn, West 46779
4. Well Location	
Unit Letter K : 2310 feet from the South line and 2310 feet from the West line	
Section 24 Township 8S Range 3	3E NMPM Chaves County
11. Elevation (Show whether DR, RKB, RT, C	
4333 GL	
12. Check Appropriate Box to Indicate Nature of Notice	, Report or Other Data
·· ·	•
	SSEQUENT REPORT OF:
OTHER: Com	
OTHER: OTHER: Com	pletion 🛛
13. Describe proposed or completed operations. (Clearly state all pertinent details, and	ad give pertinent dates, including estimated date
13. Describe proposed or completed operations. (Clearly state all pertinent details, an of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Co	ad give pertinent dates, including estimated date
13. Describe proposed or completed operations. (Clearly state all pertinent details, and	ad give pertinent dates, including estimated date
<ol> <li>Describe proposed or completed operations. (Clearly state all pertinent details, an of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Co proposed completion or recompletion.</li> </ol>	nd give pertinent dates, including estimated date empletions: Attach wellbore diagram of
<ol> <li>Describe proposed or completed operations. (Clearly state all pertinent details, an of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Coproposed completion or recompletion.</li> <li>10/7/2014 MIRUPU. Tag DV tool at 7348'. DO DV tool and RIH to PBTD of 9342'. Ci</li> </ol>	nd give pertinent dates, including estimated date ompletions: Attach wellbore diagram of rc hole clean. Close BOP and test casing, DV
<ol> <li>Describe proposed or completed operations. (Clearly state all pertinent details, an of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Coproposed completion or recompletion.</li> <li>10/7/2014 MIRUPU. Tag DV tool at 7348'. DO DV tool and RIH to PBTD of 9342'. Citool, and wellhead to 1000 psi for 30 minutes, ok. Run GR-CBL-VDL from PBTD to 1000</li> </ol>	id give pertinent dates, including estimated date ompletions: Attach wellbore diagram of rc hole clean. Close BOP and test casing, DV ' above TOC which was located at 3070'.
<ol> <li>Describe proposed or completed operations. (Clearly state all pertinent details, an of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Coproposed completion or recompletion.</li> <li>10/7/2014 MIRUPU. Tag DV tool at 7348'. DO DV tool and RIH to PBTD of 9342'. Ci</li> </ol>	nd give pertinent dates, including estimated date ompletions: Attach wellbore diagram of rc hole clean. Close BOP and test casing, DV ' above TOC which was located at 3070'. Run pkr, acidize w/ 2000 gal 15% NEFe @ 3.5
<ol> <li>Describe proposed or completed operations. (Clearly state all pertinent details, an of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Coproposed completion or recompletion.</li> <li>10/7/2014 MIRUPU. Tag DV tool at 7348'. DO DV tool and RIH to PBTD of 9342'. Ci tool, and wellhead to 1000 psi for 30 minutes, ok. Run GR-CBL-VDL from PBTD to 1000 Good bond across zone of interest. Perf 9162-73 w/ 2 spf, 23 holes w/ 3 1/8" casing gun.</li> </ol>	id give pertinent dates, including estimated date ompletions: Attach wellbore diagram of rc hole clean. Close BOP and test casing, DV ' above TOC which was located at 3070'. Run pkr, acidize w/ 2000 gal 15% NEFe @ 3.5 run 2 %' 6.5 ppf L80 pumping assembly and
<ol> <li>Describe proposed or completed operations. (Clearly state all pertinent details, an of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Coproposed completion or recompletion.</li> <li>10/7/2014 MIRUPU. Tag DV tool at 7348'. DO DV tool and RIH to PBTD of 9342'. Ci tool, and wellhead to 1000 psi for 30 minutes, ok. Run GR-CBL-VDL from PBTD to 100 Good bond across zone of interest. Perf 9162-73 w/ 2 spf, 23 holes w/ 3 1/8" casing gun. BPM using 32 BS. Swab load. Well swabbed and flowed 8 BFPH, 50% oil cut. Pull pkr,</li> </ol>	id give pertinent dates, including estimated date ompletions: Attach wellbore diagram of rc hole clean. Close BOP and test casing, DV ' above TOC which was located at 3070'. Run pkr, acidize w/ 2000 gal 15% NEFe @ 3.5 run 2 %' 6.5 ppf L80 pumping assembly and
<ol> <li>Describe proposed or completed operations. (Clearly state all pertinent details, an of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Coproposed completion or recompletion.</li> <li>10/7/2014 MIRUPU. Tag DV tool at 7348'. DO DV tool and RIH to PBTD of 9342'. Ci tool, and wellhead to 1000 psi for 30 minutes, ok. Run GR-CBL-VDL from PBTD to 100 Good bond across zone of interest. Perf 9162-73 w/ 2 spf, 23 holes w/ 3 1/8" casing gun. BPM using 32 BS. Swab load. Well swabbed and flowed 8 BFPH, 50% oil cut. Pull pkr, land tubing @ 9221', SN @ 9184', and TAC @ 8151'. Run rods and pump. Hang well or starting and starting and starting and starting starting and to hole starting and to hole starting the starting and tables and pump. Hang well or starting and tables and pump.</li> </ol>	id give pertinent dates, including estimated date ompletions: Attach wellbore diagram of rc hole clean. Close BOP and test casing, DV ' above TOC which was located at 3070'. Run pkr, acidize w/ 2000 gal 15% NEFe @ 3.5 run 2 %' 6.5 ppf L80 pumping assembly and
<ol> <li>Describe proposed or completed operations. (Clearly state all pertinent details, an of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Coproposed completion or recompletion.</li> <li>10/7/2014 MIRUPU. Tag DV tool at 7348'. DO DV tool and RIH to PBTD of 9342'. Ci tool, and wellhead to 1000 psi for 30 minutes, ok. Run GR-CBL-VDL from PBTD to 100 Good bond across zone of interest. Perf 9162-73 w/ 2 spf, 23 holes w/ 3 1/8" casing gun. BPM using 32 BS. Swab load. Well swabbed and flowed 8 BFPH, 50% oil cut. Pull pkr, land tubing @ 9221', SN @ 9184', and TAC @ 8151'. Run rods and pump. Hang well or starting and starting and starting and starting starting and to hole starting and to hole starting the starting and tables and pump. Hang well or starting and tables and pump.</li> </ol>	id give pertinent dates, including estimated date ompletions: Attach wellbore diagram of rc hole clean. Close BOP and test casing, DV ' above TOC which was located at 3070'. Run pkr, acidize w/ 2000 gal 15% NEFe @ 3.5 run 2 %' 6.5 ppf L80 pumping assembly and
<ol> <li>Describe proposed or completed operations. (Clearly state all pertinent details, an of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Coproposed completion or recompletion.</li> <li>10/7/2014 MIRUPU. Tag DV tool at 7348'. DO DV tool and RIH to PBTD of 9342'. Ci tool, and wellhead to 1000 psi for 30 minutes, ok. Run GR-CBL-VDL from PBTD to 100 Good bond across zone of interest. Perf 9162-73 w/ 2 spf, 23 holes w/ 3 1/8" casing gun. BPM using 32 BS. Swab load. Well swabbed and flowed 8 BFPH, 50% oil cut. Pull pkr, land tubing @ 9221', SN @ 9184', and TAC @ 8151'. Run rods and pump. Hang well or starting and starting and starting and starting starting and to hole starting and to hole starting the starting and tables and pump. Hang well or starting and tables and pump.</li> </ol>	id give pertinent dates, including estimated date ompletions: Attach wellbore diagram of rc hole clean. Close BOP and test casing, DV ' above TOC which was located at 3070'. Run pkr, acidize w/ 2000 gal 15% NEFe @ 3.5 run 2 %' 6.5 ppf L80 pumping assembly and
<ol> <li>Describe proposed or completed operations. (Clearly state all pertinent details, an of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Coproposed completion or recompletion.</li> <li>10/7/2014 MIRUPU. Tag DV tool at 7348'. DO DV tool and RIH to PBTD of 9342'. Ci tool, and wellhead to 1000 psi for 30 minutes, ok. Run GR-CBL-VDL from PBTD to 100 Good bond across zone of interest. Perf 9162-73 w/ 2 spf, 23 holes w/ 3 1/8" casing gun. BPM using 32 BS. Swab load. Well swabbed and flowed 8 BFPH, 50% oil cut. Pull pkr, land tubing @ 9221', SN @ 9184', and TAC @ 8151'. Run rods and pump. Hang well or starting and starting and starting and starting starting and to hole starting and to hole starting the starting and tables and pump. Hang well or starting and tables and pump.</li> </ol>	id give pertinent dates, including estimated date ompletions: Attach wellbore diagram of rc hole clean. Close BOP and test casing, DV ' above TOC which was located at 3070'. Run pkr, acidize w/ 2000 gal 15% NEFe @ 3.5 run 2 %' 6.5 ppf L80 pumping assembly and
<ul> <li>13. Describe proposed or completed operations. (Clearly state all pertinent details, an of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Coproposed completion or recompletion.</li> <li>10/7/2014 MIRUPU. Tag DV tool at 7348'. DO DV tool and RIH to PBTD of 9342'. Ci tool, and wellhead to 1000 psi for 30 minutes, ok. Run GR-CBL-VDL from PBTD to 100 Good bond across zone of interest. Perf 9162-73 w/ 2 spf, 23 holes w/ 3 1/8" casing gun. BPM using 32 BS. Swab load. Well swabbed and flowed 8 BFPH, 50% oil cut. Pull pkr, land tubing @ 9221', SN @ 9184', and TAC @ 8151'. Run rods and pump. Hang well o and 81 BW in 24 hrs.</li> <li>Mailed to Hobbs OCD 9/22/2014.</li> </ul>	id give pertinent dates, including estimated date ompletions: Attach wellbore diagram of rc hole clean. Close BOP and test casing, DV ' above TOC which was located at 3070'. Run pkr, acidize w/ 2000 gal 15% NEFe @ 3.5 run 2 %' 6.5 ppf L80 pumping assembly and
<ul> <li>13. Describe proposed or completed operations. (Clearly state all pertinent details, an of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Coproposed completion or recompletion.</li> <li>10/7/2014 MIRUPU. Tag DV tool at 7348'. DO DV tool and RIH to PBTD of 9342'. Citool, and wellhead to 1000 psi for 30 minutes, ok. Run GR-CBL-VDL from PBTD to 100 Good bond across zone of interest. Perf 9162-73 w/ 2 spf, 23 holes w/ 3 1/8" casing gun. BPM using 32 BS. Swab load. Well swabbed and flowed 8 BFPH, 50% oil cut. Pull pkr, land tubing @ 9221', SN @ 9184', and TAC @ 8151'. Run rods and pump. Hang well of and 81 BW in 24 hrs.</li> <li>Mailed to Hobbs OCD 9/22/2014.</li> </ul>	id give pertinent dates, including estimated date ompletions: Attach wellbore diagram of rc hole clean. Close BOP and test casing, DV ' above TOC which was located at 3070'. Run pkr, acidize w/ 2000 gal 15% NEFe @ 3.5 run 2 %' 6.5 ppf L80 pumping assembly and n and start pump. Tested 61 BO, cst 35 MCF,
<ul> <li>13. Describe proposed or completed operations. (Clearly state all pertinent details, an of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Coproposed completion or recompletion.</li> <li>10/7/2014 MIRUPU. Tag DV tool at 7348'. DO DV tool and RIH to PBTD of 9342'. Ci tool, and wellhead to 1000 psi for 30 minutes, ok. Run GR-CBL-VDL from PBTD to 100 Good bond across zone of interest. Perf 9162-73 w/ 2 spf, 23 holes w/ 3 1/8" casing gun. BPM using 32 BS. Swab load. Well swabbed and flowed 8 BFPH, 50% oil cut. Pull pkr, land tubing @ 9221', SN @ 9184', and TAC @ 8151'. Run rods and pump. Hang well o and 81 BW in 24 hrs.</li> <li>Mailed to Hobbs OCD 9/22/2014.</li> </ul>	id give pertinent dates, including estimated date ompletions: Attach wellbore diagram of rc hole clean. Close BOP and test casing, DV ' above TOC which was located at 3070'. Run pkr, acidize w/ 2000 gal 15% NEFe @ 3.5 run 2 %' 6.5 ppf L80 pumping assembly and
<ul> <li>13. Describe proposed or completed operations. (Clearly state all pertinent details, at of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Coproposed completion or recompletion.</li> <li>10/7/2014 MIRUPU. Tag DV tool at 7348'. DO DV tool and RIH to PBTD of 9342'. Ci tool, and wellhead to 1000 psi for 30 minutes, ok. Run GR-CBL-VDL from PBTD to 100 Good bond across zone of interest. Perf 9162-73 w/ 2 spf, 23 holes w/ 3 1/8" casing gun. BPM using 32 BS. Swab load. Well swabbed and flowed 8 BFPH, 50% oil cut. Pull pkr, land tubing @ 9221', SN @ 9184', and TAC @ 8151'. Run rods and pump. Hang well or and 81 BW in 24 hrs.</li> <li>Mailed to Hobbs OCD 9/22/2014.</li> <li>Spud Date: 8/27/2014</li> </ul>	d give pertinent dates, including estimated date ompletions: Attach wellbore diagram of rc hole clean. Close BOP and test casing, DV ' above TOC which was located at 3070'. Run pkr, acidize w/ 2000 gal 15% NEFe @ 3.5 run 2 %' 6.5 ppf L80 pumping assembly and n and start pump. Tested 61 BO, cst 35 MCF, 9/19/2014
<ul> <li>13. Describe proposed or completed operations. (Clearly state all pertinent details, an of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Coproposed completion or recompletion.</li> <li>10/7/2014 MIRUPU. Tag DV tool at 7348'. DO DV tool and RIH to PBTD of 9342'. Citool, and wellhead to 1000 psi for 30 minutes, ok. Run GR-CBL-VDL from PBTD to 100 Good bond across zone of interest. Perf 9162-73 w/ 2 spf, 23 holes w/ 3 1/8" casing gun. BPM using 32 BS. Swab load. Well swabbed and flowed 8 BFPH, 50% oil cut. Pull pkr, land tubing @ 9221', SN @ 9184', and TAC @ 8151'. Run rods and pump. Hang well of and 81 BW in 24 hrs.</li> <li>Mailed to Hobbs OCD 9/22/2014.</li> </ul>	d give pertinent dates, including estimated date ompletions: Attach wellbore diagram of rc hole clean. Close BOP and test casing, DV ' above TOC which was located at 3070'. Run pkr, acidize w/ 2000 gal 15% NEFe @ 3.5 run 2 %' 6.5 ppf L80 pumping assembly and n and start pump. Tested 61 BO, cst 35 MCF, 9/19/2014
<ul> <li>13. Describe proposed or completed operations. (Clearly state all pertinent details, at of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Coproposed completion or recompletion.</li> <li>10/7/2014 MIRUPU. Tag DV tool at 7348'. DO DV tool and RIH to PBTD of 9342'. Ci tool, and wellhead to 1000 psi for 30 minutes, ok. Run GR-CBL-VDL from PBTD to 100 Good bond across zone of interest. Perf 9162-73 w/ 2 spf, 23 holes w/ 3 1/8" casing gun. BPM using 32 BS. Swab load. Well swabbed and flowed 8 BFPH, 50% oil cut. Pull pkr, land tubing @ 9221', SN @ 9184', and TAC @ 8151'. Run rods and pump. Hang well or and 81 BW in 24 hrs.</li> <li>Mailed to Hobbs OCD 9/22/2014.</li> <li>Spud Date: 8/27/2014</li> <li>Rig Release Date: 1 hereby certify that the information above is true and complete to the best of my knowled.</li> </ul>	d give pertinent dates, including estimated date ompletions: Attach wellbore diagram of rc hole clean. Close BOP and test casing, DV ' above TOC which was located at 3070'. Run pkr, acidize w/ 2000 gal 15% NEFe @ 3.5 run 2 %' 6.5 ppf L80 pumping assembly and n and start pump. Tested 61 BO, est 35 MCF, 9/19/2014
<ul> <li>13. Describe proposed or completed operations. (Clearly state all pertinent details, at of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Coproposed completion or recompletion.</li> <li>10/7/2014 MIRUPU. Tag DV tool at 7348'. DO DV tool and RIH to PBTD of 9342'. Ci tool, and wellhead to 1000 psi for 30 minutes, ok. Run GR-CBL-VDL from PBTD to 100 Good bond across zone of interest. Perf 9162-73 w/ 2 spf, 23 holes w/ 3 1/8" casing gun. BPM using 32 BS. Swab load. Well swabbed and flowed 8 BFPH, 50% oil cut. Pull pkr, land tubing @ 9221', SN @ 9184', and TAC @ 8151'. Run rods and pump. Hang well or and 81 BW in 24 hrs.</li> <li>Mailed to Hobbs OCD 9/22/2014.</li> <li>Spud Date: 8/27/2014</li> </ul>	d give pertinent dates, including estimated date ompletions: Attach wellbore diagram of rc hole clean. Close BOP and test casing, DV ' above TOC which was located at 3070'. Run pkr, acidize w/ 2000 gal 15% NEFe @ 3.5 run 2 %' 6.5 ppf L80 pumping assembly and n and start pump. Tested 61 BO, est 35 MCF, 9/19/2014
<ul> <li>13. Describe proposed or completed operations. (Clearly state all pertinent details, at of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Coproposed completion or recompletion.</li> <li>10/7/2014 MIRUPU. Tag DV tool at 7348'. DO DV tool and RIH to PBTD of 9342'. Ci tool, and wellhead to 1000 psi for 30 minutes, ok. Run GR-CBL-VDL from PBTD to 100 Good bond across zone of interest. Perf 9162-73 w/ 2 spf, 23 holes w/ 3 1/8" casing gun. BPM using 32 BS. Swab load. Well swabbed and flowed 8 BFPH, 50% oil cut. Pull pkr, land tubing @ 9221', SN @ 9184', and TAC @ 8151'. Run rods and pump. Hang well or and 81 BW in 24 hrs.</li> <li>Mailed to Hobbs OCD 9/22/2014.</li> <li>Spud Date: 8/27/2014</li> <li>Rig Release Date: 1 hereby certify that the information above is true and complete to the best of my knowled.</li> </ul>	d give pertinent dates, including estimated date ompletions: Attach wellbore diagram of rc hole clean. Close BOP and test casing, DV ' above TOC which was located at 3070'. Run pkr, acidize w/ 2000 gal 15% NEFe @ 3.5 run 2 %' 6.5 ppf L80 pumping assembly and n and start pump. Tested 61 BO, est 35 MCF, 9/19/2014
<ul> <li>13. Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Comproposed completion or recompletion.</li> <li>10/7/2014 MIRUPU. Tag DV tool at 7348'. DO DV tool and RIH to PBTD of 9342'. Cit tool, and wellhead to 1000 psi for 30 minutes, ok. Run GR-CBL-VDL from PBTD to 1000 Good bond across zone of interest. Perf 9162-73 w/ 2 spf, 23 holes w/ 3 1/8" casing gun. BPM using 32 BS. Swab load. Well swabbed and flowed 8 BFPH, 50% oil cut. Pull pkr, land tubing @ 9221', SN @ 9184', and TAC @ 8151'. Run rods and pump. Hang well or and 81 BW in 24 hrs.</li> <li>Mailed to Hobbs OCD 9/22/2014.</li> <li>Spud Date: 8/27/2014</li> <li>Rig Release Date: 11 hereby certify that the information above is true and complete to the best of my knowled, SIGNATURE John C. Maxey</li> <li>Type or print name John C. Maxey</li> </ul>	ad give pertinent dates, including estimated date         ompletions: Attach wellbore diagram of         rc hole clean. Close BOP and test casing, DV         ' above TOC which was located at 3070'.         Run pkr, acidize w/ 2000 gal 15% NEFe @ 3.5         run 2 %' 6.5 ppf L80 pumping assembly and         n and start pump. Tested 61 BO, est 35 MCF,         9/19/2014         ge and belief.         pum Engincer       DATE 9/19/2014
<ul> <li>13. Describe proposed or completed operations. (Clearly state all pertinent details, an of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Comproposed completion or recompletion.</li> <li>10/7/2014 MIRUPU. Tag DV tool at 7348'. DO DV tool and RIH to PBTD of 9342'. Cit tool, and wellhead to 1000 psi for 30 minutes, ok. Run GR-CBL-VDL from PBTD to 1000 Good bond across zone of interest. Perf 9162-73 w/ 2 spf, 23 holes w/ 3 1/8" casing gun. BPM using 32 BS. Swab load. Well swabbed and flowed 8 BFPH, 50% oil cut. Pull pkr, land tubing @ 9221', SN @ 9184', and TAC @ 8151'. Run rods and pump. Hang well of and 81 BW in 24 hrs.</li> <li>Mailed to Hobbs OCD 9/22/2014.</li> <li>Spud Date: 8/27/2014</li> <li>Rig Release Date: 1/2/2014</li> <li>SiGNATURE TITLE: Consulting Petrole</li> </ul>	ad give pertinent dates, including estimated date         ompletions: Attach wellbore diagram of         rc hole clean. Close BOP and test casing, DV         ' above TOC which was located at 3070'.         Run pkr, acidize w/ 2000 gal 15% NEFe @ 3.5         run 2 %' 6.5 ppf L80 pumping assembly and         n and start pump. Tested 61 BO, est 35 MCF,         9/19/2014         ge and belief.         pum Engincer       DATE 9/19/2014
<ul> <li>13. Describe proposed or completed operations. (Clearly state all pertinent details, at of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Coproposed completion or recompletion.</li> <li>10/7/2014 MIRUPU. Tag DV tool at 7348'. DO DV tool and RIH to PBTD of 9342'. Cit tool, and wellhead to 1000 psi for 30 minutes, ok. Run GR-CBL-VDL from PBTD to 100 Good bond across zone of interest. Perf 9162-73 w/ 2 spf, 23 holes w/ 3 1/8" casing gun. BPM using 32 BS. Swab load. Well swabbed and flowed 8 BFPH, 50% oil cut. Pull pkr, land tubing @ 9221', SN @ 9184', and TAC @ 8151'. Run rods and pump. Hang well of and 81 BW in 24 hrs.</li> <li>Mailed to Hobbs OCD 9/22/2014.</li> <li>Spud Date: 8/27/2014 Rig Release Date: 1/2/2014</li> <li>I hereby certify that the information above is true and complete to the best of my knowled, SIGNATURE John C. Maxey For State Use Only</li> </ul>	ad give pertinent dates, including estimated date         ompletions: Attach wellbore diagram of         rc hole clean. Close BOP and test casing, DV         ' above TOC which was located at 3070'.         Run pkr, acidize w/ 2000 gal 15% NEFe @ 3.5         run 2 %' 6.5 ppf L80 pumping assembly and         n and start pump. Tested 61 BO, est 35 MCF,         9/19/2014         ge and belief.         num Engincer       DATE 9/19/2014         neering.com       PHONE: 575-623-0438
13. Describe proposed or completed operations. (Clearly state all pertinent details, at of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Cc proposed completion or recompletion.         10/7/2014 MIRUPU. Tag DV tool at 7348'. DO DV tool and RIH to PBTD of 9342'. Ci tool, and wellhead to 1000 psi for 30 minutes, ok. Run GR-CBL-VDL from PBTD to 100 Good bond across zone of interest. Perf 9162-73 w/ 2 spf, 23 holes w/ 3 1/8'' casing gun. BPM using 32 BS. Swab load. Well swabbed and flowed 8 BFPH, 50% oil cut. Pull pkr, land tubing @ 9221', SN @ 9184', and TAC @ 8151'. Run rods and pump. Hang well o and 81 BW in 24 hrs.         Mailed to Hobbs OCD 9/22/2014.         Spud Date:       8/27/2014         Rig Release Date:         I hereby certify that the information above is true and complete to the best of my knowled, SIGNATURE         Type or print name       John C. Maxey         For State Use Only       John C. Maxey         TITLE       Petroleum Engine.	ad give pertinent dates, including estimated date         pmpletions: Attach wellbore diagram of         rc hole clean. Close BOP and test casing, DV         ' above TOC which was located at 3070'.         Run pkr, acidize w/ 2000 gal 15% NEFe @ 3.5         run 2 %' 6.5 ppf L80 pumping assembly and         n and start pump. Tested 61 BO, est 35 MCF,         9/19/2014         ge and belief.         num Engincer       DATE 9/19/2014         neering.com       PHONE: 575-623-0438
<ul> <li>13. Describe proposed or completed operations. (Clearly state all pertinent details, at of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Coproposed completion or recompletion.</li> <li>10/7/2014 MIRUPU. Tag DV tool at 7348'. DO DV tool and RIH to PBTD of 9342'. Cit tool, and wellhead to 1000 psi for 30 minutes, ok. Run GR-CBL-VDL from PBTD to 100 Good bond across zone of interest. Perf 9162-73 w/ 2 spf, 23 holes w/ 3 1/8" casing gun. BPM using 32 BS. Swab load. Well swabbed and flowed 8 BFPH, 50% oil cut. Pull pkr, land tubing @ 9221', SN @ 9184', and TAC @ 8151'. Run rods and pump. Hang well of and 81 BW in 24 hrs.</li> <li>Mailed to Hobbs OCD 9/22/2014.</li> <li>Spud Date: 8/27/2014 Rig Release Date: 1/2/2014</li> <li>I hereby certify that the information above is true and complete to the best of my knowled, SIGNATURE John C. Maxey For State Use Only</li> </ul>	ad give pertinent dates, including estimated date         ompletions: Attach wellbore diagram of         rc hole clean. Close BOP and test casing, DV         ' above TOC which was located at 3070'.         Run pkr, acidize w/ 2000 gal 15% NEFe @ 3.5         run 2 %' 6.5 ppf L80 pumping assembly and         n and start pump. Tested 61 BO, est 35 MCF,         9/19/2014         ge and belief.         num Engincer       DATE 9/19/2014         neering.com       PHONE: 575-623-0438

## NOV 2 4 2014