

Submit 1 Copy To Appropriate District Office
District I - (575) 393-6161
1625 N. French Dr., Hobbs, NM 88240
District II - (575) 748-1283
811 S. First St., Artesia, NM 88210
District III - (505) 334-6178
1000 Rio Brazos Rd., Aztec, NM 87410
District IV - (505) 476-3460
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
Revised July 18, 2013

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

NOV 14 2014

WELL API NO. 30-025-11214
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name Langlie Mathix Unit
8. Well Number 13
9. OGRID Number 243978
10. Pool name or Wildcat Langlie Mathix 7 Rurs Queen GB
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3174' DF

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK A WELL OR TO DRILL OR TO DEEPEN OR PLUG BACK A WELL IN A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: Oil Well ☐ Gas Well ☒ Other **Injection**

2. Name of Operator
Saber Oil & Gas Ventures, LLC

3. Address of Operator
400 W. Illinois - Suite 950 - Midland, TX 79701

4. Well Location
Unit Letter **I** : **1650** feet from the **South** line and **990** feet from the **East** line
Section **23** Township **24S** Range **37E** NMPM **LEA** County

11. Elevation (Show whether DR, RKB, RT, GR, etc.)
3174' DF

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☒ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐
DOWNHOLE COMMINGLE ☐
CLOSED-LOOP SYSTEM ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☒ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ P AND A ☐
CASING/CEMENT JOB ☐
OTHER: **Failed Test (MIT) 9.16.14**

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

1. Move in RUPU. ND WH. NU BOP.
2. Release 2 Pon w/ 5 1/2" AD-1 pkr.
3. PU & RIN w/ 4 3/4" W/O Bit & string mill on 2 3/8" TBH to 3200'. pon.
4. PU & RIN w/ 5 1/2" AS-1X pkr on 2 3/8" IPC TBH. Set pkr @ 3178' w/ 15 pnts. of Tension.
5. ND BOP & NU WH.
6. Test 5 1/2" Csg w/ pump truck & chart Recorder to 340 p.s.i. George Bower w/ NMOCO witnessed TEST & signed chart. ROPU & move off well.

Spud Date:

Rig Release Date:

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

TITLE

DATE

Type or print name

E-mail address:

PHONE:

For State Use Only

APPROVED BY:

TITLE

DATE

Conditions of Approval (if any):

FOR RECORD ONLY

NOV 25 2014

