

Submit 1 Copy To Appropriate District Office  
 District I  
 1625 N. French Dr., Hobbs, NM 88240  
 District II  
 1301 W. Grand Ave., Artesia, NM 88210  
 District III  
 1000 Rio Brazos Rd., Aztec, NM 87410  
 District IV  
 1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
 Energy, Minerals and Natural Resources

Form C-103  
 October 13, 2009

OIL CONSERVATION DIVISION  
 1220 South St. Francis Dr.  
 Santa Fe, NM 87505

WELL API NO. 30-025-33759
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name W A Weir
8. Well Number 14
9. OGRID Number 873
10. Pool name or Wildcat Abo
11. Elevation (Show whether DR, RKB, RT, GR, etc.)

**SUNDRY NOTICES AND REPORTS ON WELLS**  
 (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: Oil Well  Gas Well

2. Name of Operator  
Apache Corp.

3. Address of Operator  
P O box Drawer D Monument NM 88265

4. Well Location  
 Unit Letter F : 1650 feet from the N line and 1650 feet from the W line  
 Section 35 Township 19S Range 36E NMPM Lea County

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

<b>E-PERMITTING</b> P&A NR <input type="checkbox"/> P&A R <input type="checkbox"/> INT TO P&A <input type="checkbox"/> COMP <input type="checkbox"/> CSNG <input type="checkbox"/> CHG Loc <input type="checkbox"/> TA <u>PM</u> RBDMS CHART <u>SAS</u> <input type="checkbox"/>	<b>SUBSEQUENT REPORT OF:</b> REMEDIAL WORK <input type="checkbox"/> ALTERING CASING <input type="checkbox"/> COMMENCE DRILLING OPNS <input type="checkbox"/> P AND A <input type="checkbox"/> CASING/CEMENT JOB <input type="checkbox"/> OTHER: PRESSURE TEST <input type="checkbox"/>
--	--

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

Perfs 7276' - 7490'

MIRU MESA WELL SERVICE. POOH WITH PRODUCTION EQUIPMENT. MIRU CAPITAN WIRE LINE & RIH WITH CIBP TO 7225'. SET IT THERE AND BAIL 35' OF CEMENT ON TOP. LOAD THE HOLE WITH PACKER FLUID AND TEST TO 525#. CHART THE PRESSURE FOR 32 MINUTES WITH A LOSS OF 10 POUNDS. APACHE REQUESTS A TA STATUS FOR THIS WELL.

This Approval of Temporary Abandonment Expires 11/10/2019

HOBBS OGD

NOV 12 2014

Spud Date:

Rig Release Date:

RECEIVED

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE [Signature] TITLE Instrument Tech DATE 11-12-14

Type or print name Jim Ellison E-mail address: JD.Ellison@apacheccorp.com PHONE: \_\_\_\_\_


**For State Use Only**

APPROVED BY: [Signature] TITLE Staff Manager DATE 11/14/2014

Conditions of Approval (if any):

NOV 25 2014

PRINTED IN U.S.A. 6 PM



Graphic Controls

Apache Weir 14  
 MacLuskey  
 # 35  
 Harold  
 Greer  
 Scoops  
 30 min  
 1 hr  
 clock

DATE 11-10-2014

BR 2221

Apache Corp.  
 WJA Weir #14  
 30-025-33759  
 35-195-36E

HOBBS OGD

NOV 12 2014

RECEIVED

Call 505 by Alton Rodriguez

10-27-0017

60 min 11000

FOR RECORD ON

BS 11/14/2014

# 525

R