

Submit 3 Copies To Appropriate District Office
District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Ave., Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
May 27, 2004

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

WELL API NO. 30-025-24162
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No. 301216
7. Lease Name or Unit Agreement Name Shipp
8. Well Number 004
9. OGRID Number 232611
10. Pool name or Wildcat Humble City; Atoka

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: Oil Well ☒ Gas Well ☐ Other

2. Name of Operator
SUNDOWN ENERGY LP

3. Address of Operator
13455 NOEL RD, STE. 2000, DALLAS, TX 75240

4. Well Location
Unit Letter I: 1980 feet from the SOUTH line and 660 feet from the EAST line
Section 11 Township 17S Range 37E NMPM LEA County

11. Elevation (Show whether DR, RKB, RT, GR, etc.)
16' KB

Pit or Below-grade Tank Application ☐ or Closure ☐

Pit type _____ Depth to Groundwater _____ Distance from nearest fresh water well _____ Distance from nearest surface water _____

Pit Liner Thickness: _____ mil Below-Grade Tank: Volume _____ bbls; Construction Material _____

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☒ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ P AND ☐
CASING/CEMENT JOB ☐

OTHER: ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

10-13-2005: MI RU Workover rig. POH w/ rods, pump. NU BOP. POH w/ tbg & TAC.

10-14-2005: RIH w/ pkr & RBP on tbg. Left pkr & RBP swinging @ 8420'.

10-17-2005: Set RBP @ 8420', pkr @ 8380'. Ppd 4 BFW w/ 2% KCL to load. Press to 900 psi, held OK. Open bypass on pkr & load csg. Press up to 600 psi, held OK. Set RBP @ 10,173'. Press up on tbg to tst RBP, had slight leak off. Release pkr, Set pkr @ 9921', press csg to 600 psi, held OK. Set pkr @ 9951', press up on csg, slow leak off 100 psi in 2-1.2 min. Set pkr @ 9936', press csg to 500 psi, held OK. Csg leaking from 9936' to 10,036'. Release pkr. Release RBP. Pull up hole to 9877'. POH w/ prod string.

10-18-2005: RIH w/ CIBP f/ 4-1/2". 9.5 csg. Set CIBP @ 9898' (As per verbal approval by Gary Wink, NM OCD). POH. Prepare to run MIT.

hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been/will be constructed or closed according to NMOCD guidelines ☐, a general permit ☐ or an (attached) alternative OCD-approved plan ☐.

SIGNATURE J. W. Fautus TITLE Prod. Sup't. DATE 10-21-05

Type or print name J. W. Fautus

E-mail address:

Telephone No. 432-943-877

For State Use Only

APPROVED BY: Gary W. Wink TITLE OC FIELD REPRESENTATIVE II/STAFF MANAGER DATE _____

Conditions of Approval (if any):

OCT 25 2005