

State of New Mexico  
Energy, Minerals and Natural Resources Department

---

**Susana Martinez**  
Governor

**David Martin**  
Cabinet Secretary-Designate

**Brett F. Woods, Ph.D.**  
Deputy Cabinet Secretary

**David Catanach**  
Division Director  
Oil Conservation Division



January 8, 2015

Alta Mesa Services LP  
ATT: Regulatory  
15021 Katy Freeway, Suite 400  
Houston TX 77094

RE: Pulliam Farms 27 P #001-P-27-8N-35e, API # 30-009-20025

Dear Operator:

The following inspection(s) of the well files indicate that the well(s) have been drilled, but the operational status of the well(s) failed to meet standards of the New Mexico Oil Conservation Division as described in the detail attachments. To comply with standards imposed by Rules and Regulations of the Division, corrective action must be taken immediately and the situations brought into compliance.

Rule 19.15.16 states that completion forms must be filed within 20 days after completion of the well. Per each attachment is a list of what is required for each well.

Please Note: Delay in processing of regulatory forms may result in operator receiving production and dispositions error messages generated by C-115 reporting.

In the event that a satisfactory response is not received to this letter of direction by the "Corrective Action Due" by January 30, 2015, further enforcement will occur. Such enforcement may include this office applying to the Division for an order summoning you to a hearing before a Division Examiner in Santa Fe to show cause why you should not be ordered to permanently plug and abandon these wells.

Sincerely,

*Donna Mull*

Line Manager  
Hobbs OCD District Office

API # <del>30</del> 00920025	OPERATOR ALTA MESA SERVICES LP	WELL NAME <del>PULLIAM-FARMS</del> 27-P	WELL # 001

We have received your completion paperwork on the well listed above. However, before we can approve it, we need the following submitted: (Marked by XXXXX)

XXXXX	Need C-103 or BLM 3160-5 Subsequent Report on all strings of Casing & Cement
	Need C-103 or BLM 3160-5 Subsequent Report on how well was completed
XXXXX	Need Deviation Survey
	Need Directional Drill Survey
	Need C-102 with correct Bottomhole Location (Directional or Horizontal wells only)
XXXXX	Need to submit logs run on well
	Need C-104
XXXXX	Need C-105 or BLM 3160-4

	Missing info on C-103
	Missing info on C-104
	Missing info on C-105
	Need logs run on well

	OTHERS
XXXXX	Need C-103 Subsequent Report of the Plug & Abandonment of the well with dates

With the exception of logs, these can be submitted by e-mail. Please notify me by email when sending information requested

PLEASE NOTE: Delay in processing of regulatory forms may result in operator receiving production and dispositions error messages generated by C-115 reporting.