Submit 3 Copies To Appropriate District Office State of New Mexico District I LAND OF Energy Minerals and Natural Resources	Form C-103 October 25, 2005 WELL API NO.
1625 N. French Dr., Hobbs, NM 88240 District II OH. CONSERVATION DIVISION	30-025-37323
Disrtict III	5. Indicate Type of Lease
1000 Rio Brazos Rd. Aztec, NM 87410 1220 South St. Francis Dr.	STATE T FEE
District IV Santa Fe, NM 87505 1220 S. St. Francis Dr., Santa Fe, NM 87505	6. State Oil & Gas Lease No.
SUNDRY NOTICES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR DEEPEN OR PLUG BACK TO A DIFFERENT RESERVIOR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	Grizzell 8. Well Number
1. Type of Well: Oil Well Gas Well Other	13
2. Name of Operator	9. OGRID Number
Apache Corporation 3. Address of Operator	873 10. Pool Name
303 Veterans Airpark Ln., Ste. 3000, Midland, TX, 79705	Penrose Skelly; (50350)
4. Well Location Unit Letter O : 990 feet from the S line and	2310 feet from the E line
Section 8 Township 22S Range 37E	NMPM County Lea
11. Elevation (Show whether DR, RKB,RT, GR, etc.) 3407' GR	
12. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON COMMENCE DRILLING OF PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMENT JOB DOWNHOLE COMMINGLE	SUBSEQUENT REPORT OF: ALTERING CASING PAND A D ALTERING CASING CASING ALTERING CASING CASING ALTERING CASIN
	eady for OCD inspection after P&A
All pits have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan. Rat hole and cellar have been filled and leveled. Cathodic protection holes have been properly abandoned. A steel marker at least 4" in diameter and at least 4' above ground level has been set in concrete. It shows the	
OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUARTER / QUARTER LOCATION OR UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. ALL INFORMATION HAS BEEN WELDED OR	
PERMANENTLY STAMPED ON THE MARKER'S SURFACE.	
The location has been leveled as nearly as possible to the original ground contour and has been cleared of all junk, trash, flow lines and other production equipment.	
Anchors, dead men, tie downs and risers have been cut off at least two feet below ground level. If this is a one-well lease or last remaining well on lease, the battery and pit location(s) have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, production equipment and junk have been removed	
from the lease and well location. All metal bolts and other materials have been removed. Portable bases have been removed. (Poured onsite concrete bases do not have	
to be removed.) All other environmental concrens have been addressed as per OCD rules. Pipelines and flow lines have been abandoned in accordance with 19.15.9.714.B(4)(b) NMAC. All fluids have been removed from non-retrieved flow lines and pipelines.	
When all work has been completed, return this form to the appropriate District office to schedule an inspection. If more than one inspection has to be made to a P&A location because it does not meet the criteria above, a penalty may be assessed.	
SIGNATURE LOW SULLING TITLE P&A Tech	DATE 1/8/15
TYPE OR PRINT NAME Leon Sellers leon.sellers@apache	ecorp.com PHONE: 432-208-0349
APPROVED BY: Number of Approval (if any): Compliance Office DATE \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \	

FEB 0 3 2215