

Submit 3 Copies To Appropriate District
Office
District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Ave., Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM
87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
March 4, 2004

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

WELL API NO. 30-025-21671
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. 01-5373
7. Lease Name or Unit Agreement Name State HT "B" SWD
8. Well Number 1
9. OGRID Number 020989
10. Pool name or Wildcat Upper Penn

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:
Oil Well ☐ Gas Well ☒ Other **SWD**

2. Name of Operator
Smith & Marris Inc.

3. Address of Operator
Box 863 Kermit, TX. 79745

4. Well Location
Unit Letter **D** : **700** feet from the **North** line and **580** feet from the **West** line
Section **31** Township **12-S** Range **34-E** NMPM County **LEA**

11. Elevation (Show whether DR, RKB, RT, GR, etc.)

Pit or Below-grade Tank Application (For pit or below-grade tank closures, a form C-144 must be attached)

Pit Location: UL _____ Sect _____ Twp _____ Rng _____ Pit type _____ Depth to Groundwater _____ Distance from nearest fresh water well _____
Distance from nearest surface water _____ Below-grade Tank Location UL _____ Sect _____ Twp _____ Rng _____ ;
_____ feet from the _____ line and _____ feet from the _____ line

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐

TEMPORARILY ABANDON ☐ CHANGE PLANS ☐

PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☒

CASING TEST AND CEMENT JOB ☐

OTHER: ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

See Attachment

Approved as to plugging of the Well Bore.
Liability under bond is retained until
surface restoration is completed.

I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been/will be constructed or closed according to NMOCD guidelines ☐, a general permit ☐ or an (attached) alternative OCD-approved plan ☐.


SIGNATURE **[Signature]** TITLE **Pres.** DATE **8-5-05**

Type or print name **Rickey Smith** E-mail address: _____ Telephone No. **432 586-3076**

(This space for State use)

APPROVED BY **[Signature]** TITLE _____
Conditions of approval, if any: _____

OCD FIELD REPRESENTATIVE II/STAFF MANAGER
DATE **OCT 31 2005**



MAYO MARRS CASING PULLING INC.
BOX 863
KERMIT, TEXAS 79745

SMITH & MARRS INC.

Lease: STATE HT "B" SWD # 1

API # 30-025-21671

Project: P & A – CEMENTING REPORT – C-103

07-28-05 - SET CIBP @ 9600' – DUMP 35' CEMENT ON TOP

07-29-05 - SPOT 25 SXS @ 6000'-5800'

08-01-05 - PERF. @ 4150' – TEST TO 1000# - SPOT 25 SXS @ 4205'-3960' & TAG

08-02-05 - PERF. @ 2000' – TEST TO 1000# - SPOT 80 SXS @ 2050'-1452' & TAG

08-02-05 - SPOT 95 SXS @ 450'-320' & TAG

08-03-05 – SPOT 45 SXS @ 320'-283' & TAG

08-03-05 - SPOT 40 SXS @ 60' TO SURFACE

PULLED 1510' OF 5 ½" CASING

PULLED 400' OF 9 5/8" CASING

INSTALL DRY HOLE MARKER

CIRCULATE 10# MUD