Office Office	State of New	Mexico	·	Form C-103
District I	Energy, Minerals and I	Natural Resources		October 13, 2009
1625 N. French Dr., Hobbs, NM 88240			WELL API NO.	
District II 1301 W. Grand Ave., Artesia, NM 88210 OIL CONSERVATION DIVISION			30-025-33607	
District III 1220 South St. Francis Dr.			5. Indicate Type of Leas	
1000 Rio Brazos Rd., Aztec, NM 87410	santa Fe, NM 87505			FEE
<u>District IV</u> 1220 S. St. Francis Dr., Santa Fe, NM 87505	Sama 1 c, 141v	1 67 505	6. State Oil & Gas Lease	3 NO.
	CES AND REPORTS ON WE	LLS	7. Lease Name or Unit	Agreement Name
(DO NOT USE THIS FORM FOR PROPOS.	ALS TO DRILL OR TO DEEPEN OF	R PLUG BACK TO A	McGrail State	rgreement runte
(DO NOT USE THIS FORM FOR PROPOS. DIFFERENT RESERVOIR. USE "APPLICA PROPOSALS.)	ATION FOR PERMIT" (FORM C-10	1) FOR SUCTO	8. Well Number 9	•
1. Type of Well: Oil Well (	Gas Well 🗆 TA'd	A. Com	o. Went runner	
2. Name of Operator	Jas Well   JAA	- 19 TO	9. OGRID Number 873	
Apache Corp.			7. OGRID Number 673	
3. Address of Operator		To Con	10. Pool name or Wilde	at
P O box Drawer D Monument NM 8	8265	Elle Control	Monument Abo	
4. Well Location	···			
Unit Letter K :	1980 feet from the	Sline and	1650 feet fr	om the
W line		inic and	1030166t 110	Jiii tile
	T1 100	D 26	E MADM I	
Section 26	Township 19S	Range 36		Lea County /
	11. Elevation (Show whether	DR, RKB, RT, GR, etc		
			lof the state of t	
12 Charles		. NI. 4 CNT 4	D / O/I D /	
12. Check A	ppropriate Box to Indicat	e Nature of Notice,	, Report or Other Data	
NOTICE OF INT	FNTION TO:	SUE	SSEQUENT REPOR	Γ OF·
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WOR		RING CASING ☐
TEMPORARILY ABANDON	CHANGE PLANS		RILLING OPNS. P AND	
PULL OR ALTER CASING	MULTIPLE COMPL	CASING/CEMEN	<del></del> -	,
DOWNHOLE COMMINGLE	MOETH LE COMM L	OAGINO/CEMEN	(1.10p []	
DOM: 1022 00:1111111022	2 YEARS			
OTHER: MPT	a jenk	OTHER:		
13. Describe proposed or comple	ted operations. (Clearly state	all pertinent details, ar	nd give pertinent dates, inclu	uding estimated date
	k). SEE RULE 19.15.7.14 N	MAC. For Multiple Co	ompletions: Attach wellbore	e diagram of
proposed completion or reco	mpletion.			
				•
Plan to move in a pump truck. Pressur	e test the casing to 500 nsi an	d chart the pressure for	· 32 minutes	
Trail to move in a pump truck. Tressui	e test the easing to 500 psi an	d chart the pressure for	32 minutes.	
			•	
		·		
Spud Date:	Rig Releas	e Date:		
Spud Date.	Kig Keleas	c Date.		
		. ,		
I hereby certify that the information a	have is true and complete to t	a hest of my knowledg	as and balisf	
	sove is true and complete to the	ie desi di my knowledg	ge and belief.	
$\bigcap (1 \le \bigcap)$				7 02 /
SIGNATURE ()	TITLE	Instrument Tech	DATE	3 25/5
7				אוכרים אונו, אני
Type or print nameJim Ellison	E-mail add	dress: _JD.Ellison@ap	يeacheccorp.com_ PHONE:	,10-441-1139
For State Use Only		<b>^</b> 1 <i>-</i>		( )
ADDROVED SILVING	Mayor D	LAT S. On	111/1000	2/72/701I
APPROVED BY: WILLY	re uni Unitle	wo. Jupe	WISOU DATE 3	2/24/2010
Conditions of Approval (if any):		V		1 /
			MAR 26	2015 an
			111111 P 6	∠U10# \\\