Submit I Copy To Appropriate District	State of New Me	Form C-103			
Office <u>District I</u> = (575) 393-6161	Energy, Minerals and Natural Resources			ed August 1, 2011	
1625 N. French Dr., Hobbs, NM 88240			WELL API NO.		
<u>District II</u> – (575) 748-1283 811 S. First St., Artesia, NM 88210	OIL CONSERVATION DIVISION		30-025-28308		
<u>District III</u> – (505) 334-6178	1220 South St. Francis Dr.		5. Indicate Type of Lease STATE FI	EE 🏻	
1000 Rio Brazos Rd., Aztec, NM 87410	Santa Fe, NM 87505		6. State Oil & Gas Lease N		
<u>District IV</u> – (505) 476-3460 1220 S. St. Francis Dr., Santa Fe, NM	2 3.1.1.1 2 4, 1 1.1.1 8 .		0. State Off & Gas Lease N	ю.	
87505	OFC AND DEDODES ON WELLS		7 1		
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A			7. Lease Name or Unit Agr South Hobbs (G/SA) Unit	reement Name	
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SECTION FOR PERMIT (FORM C-101) FOR PERMIT (FORM C-101) FOR SECTION FOR PERMIT (FORM C-101) FOR		South Hoods (G/SA) Ollit			
			8. Well Number COOP 5	8. Well Number COOP 5	
2. Name of Operator	Gas Well Other: Injector		9. OGRID Number: 157984		
Occidental Permian Ltd.	White or		3. 3 3 rumor. 13730 r		
3. Address of Operator	The state of the s		10. Pool name or Wildcat Hobbs (G/SA)		
HCR 1 Box 90 Denver City, TX 79	323	RECEIVED		,	
4. Well Location					
Unit Letter _L : 19	80feet from theSouth lin	e and 646	feet from the West lin	ie .	
Section 34	Township 18S	Range 381	NMPM Lea	County	
,	11. Elevation (Show whether DR,				
	3636.8' (KB)	, , ,	,		
12. Check A	appropriate Box to Indicate N	ature of Notice,	Report or Other Data		
NOTICE OF IN	TENTION TO	l OUE	OCCUENT DEDODT	~ E	
NOTICE OF IN			SSEQUENT REPORT (
PERFORM REMEDIAL WORK ☑ PLUG AND ABANDON ☐ REMEDIAL WORK ☐ ALTERING CASING ☐					
TEMPORARILY ABANDON					
DOWNHOLE COMMINGLE	MOETIFEE COMFE	CASING/CEIVIEN	11 JOB		
DOWNI IOLE COMMININGLE					
OTHER:		OTHER:			
	eted operations. (Clearly state all p				
	rk). SEE RULE 19.15.7.14 NMAC	C. For Multiple Co	mpletions: Attach wellbore d	iagram of	
proposed completion or reco	ompletion.				
1. POOH w/ inj equipment					
2. Clean out well to PBTD @4457'.	Tag fill				
3. Run USIT log	-		·		
4. Clean out well to TD &4490'	During this procedure we plan to use				
4. Perforate 4450-70'	the closed-loop system with a steel				
6. Acid treat per prog tank and haul contents to the required					
6. Scale squeeze disposal per ODC Rule 19.15.17					
7. RIH w/ injection equipment8. Return well to injection	•				
o. Retain wen to injection					
Spud Date:	Rig Release Da	ite:			
I hereby certify that the information a	phave is true and complete to the he	act of my knowled	ra and haliaf		
Thereby certify that the information a	soove is true and complete to the be	est of my knowledg	ge and benef.		
$\Omega M_{\bullet} \wedge$					
SIGNATURE / SIGNATURE	TITLE_Injection	n Well AnalstD	ATE4-14-15		
	91 P 9 H P 1	1 120	DUONE 004 502 422		
Type or print nameRobbie Underl	nill E-mail address_Robert_U	nderhill@oxy.com	PHQNE:_ <u>806-592-6287</u>		
For State Use Only		_		, ,	
APPROVED BY:	TITLE P	etroleum Engir	deer Date 04	1/22/15	
Conditions of Approval (if any):				7	

APR 2 2 2015

M