

Submit 1 Copy To Appropriate District Office

District I - (575) 393-6161
1625 N. French Dr., Hobbs, NM 88240
District II - (575) 748-1283
811 S. First St., Artesia, NM 88210
District III - (505) 334-6178
1000 Rio Brazos Rd., Aztec, NM 87410
District IV - (505) 476-3460
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico

Energy, Minerals and Natural Resources

Form C-103

August 1, 2011

HOBBS OGD

OIL CONSERVATION DIVISION

20 South St. Francis Dr.
Santa Fe, NM 87505

RECEIVED

WELL API NO. 30-025-36871
5. Indicate Type of Lease STATE ☒ FEE ☐
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name Red Raider State
8. Well Number 1
9. OGRID Number 229137
10. Pool name or Wildcat Featherstone; Bone Spring, East
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3643' GR

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: Oil Well ☒ Gas Well ☐ Other ☐	
2. Name of Operator COG Operating LLC	
3. Address of Operator One Concho Center, 600 W Illinois Ave, Midland, TX 79701	
4. Well Location Unit Letter K : 1650 feet from the S line and 1980 feet from the W line Section 19 Township 20S Range 36E NMPM County Lea	
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3643' GR	

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐
DOWNHOLE COMMINGLE ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ P AND A ☐
CASING/CEMENT JOB ☐

OTHER: ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

1. MIRU plugging equipment. Dig out cellar. ND wellhead. NU BOP. POH w/ tbg. Spot 25 sx at 9518' (DVTail)
2. RIH and set 5 1/2 CIBP @ 7550'. Circulate hole w/mud laden fluid. Spot 20 sx cement on top of CIBP 7550-7350.
3. Spot 20 sx cement @ 5400-5200'. WOC & Tag. (SHOE) 25
4. Spot 55 sx cement @ 3950-3400. WOC & Tag.
5. Cut and pull +/- 1650' 5 1/2 casing.
5. Spot 45 sx cement @ 1700-1600. WOC & Tag (STUB)
6. Spot 45 sx cement @ 575-475. WOC & Tag.
7. Spot 40 sx surface plug. 100' to surface
8. Cut off wellhead and weld on Dry Hole Marker.

Pressure test csg

The Oil Conservation Division

MUST BE NOTIFIED 24 Hours

Prior to the beginning of operations

Spud Date:

Rig Release Date:

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Ben Montgomeray TITLE Agent DATE 4-29-15

Type or print name Ben Montgomeray E-mail address: benm@hemandassociates.com PHONE: 932-580-7161
For State Use Only

APPROVED BY: Maureen Brown TITLE Dist. Supervisor DATE 4/30/2015

Conditions of Approval (if any):

MAY 01 2015

Author:	B Maiorino	
Well Name	Red Raider St	Well No. #1
Field	Fetherstone	API #: 30-025-36871
County	Lea	Prop #:
State	New Mexico	Zone: Bone Spring
Date	4/27/2015	
GL	3643'	
KB	3665'	

Description	O.L.	Grade	Weight	Depth	Cmt Sx	TOC
Surface Csg	13 3/8	H40	48	524	250	Surface
Inter Csg	9 5/8	HKC 55, J55	40	5,300	1420	Surface
Prod Csg	5 1/2	N80, HCP110	17	11,911	1,830	1700'

