

Submit 1 Copy To Appropriate District Office
District I - (575) 393-6161
1625 N. French Dr., Hobbs, NM 88240
District II - (575) 748-1283
811 S. First St., Artesia, NM 88210
District III - (505) 334-6178
1000 Rio Brazos Rd., Aztec, NM 87410
District IV - (505) 476-3460
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
Revised July 18, 2013

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

WELL API NO. 30-025-28142 28141
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name State MTS
8. Well Number 2
9. OGRID Number 310761
10. Pool name or Wildcat Wolfcamp SWD; Wolfcamp
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3841.7 GR

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: Oil Well ☐ Gas Well ☒ Other SWD

2. Name of Operator
Oasis Water Solutions, LLC

3. Address of Operator
Box 36 Monument, NM 88265

4. Well Location
Unit Letter E : 1980 feet from the N line and 510 feet from the W line
Section 10 Township 19S Range 35E NMPM Lea County

11. Elevation (Show whether DR, RKB, RT, GR, etc.)
3841.7 GR

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐
DOWNHOLE COMMINGLE ☐
CLOSED-LOOP SYSTEM ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☒ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ P AND A ☐
CASING/CEMENT JOB ☐
OTHER: Convert to SWD ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

Convert to SWD per SWD 1490.

HOBBS OCD

See Attached:

MAY 19 2015

RECEIVED

Spud Date:

Rig Release Date:

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Eddie W. Seay TITLE Agent DATE 5/13/15

Type or print name Eddie W. Seay E-mail address: seay04@leaco.net PHONE: 575-392-2236

For State Use Only

APPROVED BY: [Signature] TITLE Petroleum Engineer DATE 05/21/15

Conditions of Approval (if any):

MAY 21 2015

Attachment to C-103
Oasis Water Solutions, LLC
Subsequent Report of Conversion to SWD
MTS #2

Notified OCD of work.

- 1) Move in rig, lay down rods and tubing.
- 2) Go in hole with scraper to casing and fill. Clean down to 106722 ft.
- 3) Rig up Haliburton to add perforations in Wolfcamp, add 2 shots per ft. from 10558 to 10578 ft., and 4 shots per ft. from 10598 to 10658 ft.
- 4) Run in hole with 3/1 IPC-L-80 tubing and arrow set packer, set at 10506 ft.
- 5) Load backside with packer fluid, wait on test. 4/20/2015

HOBBS OCD

MAY 19 2015

RECEIVED