Submit 1 Copy To Appropriate District Office	State of New Me			Form C-103	
District 1 – (575) 393-6161 Energy, Minerals and Natural Resources 625 N. French Dr., Hobbs, NM 88240			Revised July 18, 2013 WELL API NO. 30-025-42455		
District II - (575) 748-1283 811 S. First St., Artesia, NM 88210 District III - (575) 748-1283 0IL CONSERVATION DIVISION			5. Indicate Type of L	ease	
istrict III - (505) 334-6178 1220 South St. Francis Dr. 100 Rio Brazos Rd., Aztec, NM 87410 Santa Fe, NM 87505			6. State Oil & Gas La	FEE	
District IV – (505) 476-3460 Salita FC, INIVI 87505 1220 S. St. Francis Dr., Santa Fe, NM 87505			0. State Off & Gas La	ase no.	
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.) 1. Type of Well: Oil Well S Gas Well Other			 7. Lease Name or Un Chiles 28 State 8. Well Number 1H 	8. Well Number	
		0 3 2015			
2. Name of Operator Devon Energy Production Company, LP			9. OGRID Number 6137	~	
3. Address of Operator 333 West. Sheridan Avenue			10. Pool name or Wildcat		
Oklahoma City, OK 73102-5015 405-552-6558			Berry; Bone Spring, South (96660)		
4. Well Location Unit Letter <u>D</u> : <u>350</u> feet fro	m the <u>N</u> line and	<u>350</u> feet fro	m the W line		
Section 28 21S		lange		County	
· · · · · · · · · · · · · · · · · · ·	vation <i>(Show whether DR,</i> /12' GR	RKB, RT, GR, e	etc.)		
12. Check Appropri	iate Box to Indicate N	ature of Notic	e, Report or Other Da	ta	
•			IBSEQUENT REPO		
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF PERFORM REMEDIAL WORK D PLUG AND ABANDON REM E-PERMITTING <swd injection=""></swd>					
	GE PLANS		IVERSION	RBDMS	
				TA	
DOWNHOLE COMMINGLE			G	CHG LOC	
	57	OTH INT	TO RA P&A NF	RP&A R	
OTHER: 13. Describe proposed or completed ope	rations (Clearly state all r	ortinent detaile	and give nertinent dates i	naluding astimated data	
of starting any proposed work). SEE proposed completion or recompletion	RULE 19.15.7.14 NMAC				
Due to full losses after attempting multiple tin 3810' (108' inside intermediate shoe) and the	nes to successfully place the new to successfully place the new to be new to	ne tieback cemen op of it. The fina	nt plug, the decision was m al cement program went as	ade to set a CIBP at follows:	
Due to full tosses and attempting multiple times to successfully place the fieldack content plag, the decision was made to set a CIBF at 3810' (108' inside intermediate shoe) and then spot 100' of cement on top of it. The final cement program went as follows: 1) From 4478' to 4398' (this top was confirmed by tagging the top of the plug after it was placed) 2) CIBP at 3810' with cement from 3810' to 3710' 3) From 1955' to 1855' (50' above and below surface shoe at 1905' MD) 4) From 100' to surface'' Wellbore schematics attached. 5TEP Z has been added 40 Provious intent i. Thereby certify that the information above is true and complete to the best of my knowledge and belief.					
2) CIBP at 3810' with cement from $3810'$ to $3710'$					
 3) From 1955' to 1855' (50' above and belo 4) From 100' to surface" 	bw surface shoe at 1905' M	ID)		epermine	
Wellbore schematics attached.			1 1	man man	
	STEP	2ha	s been ado	led	
	top	revious	intent.		
I hereby certify that the information above is	true and complete to the be	est of my knowl	edge and belief.	<u></u>	
SIGNATURE Dell		E: <u>Regulatory</u>		6/1/2015	
Type or print name: David H. Cook	E-mail address: david.	cook@dvn.com	PHONE: <u>405-5</u> ;	<u>52-7848</u>	
For State Use Only	\mathbf{X}	+ <		1/2/2017	
APPROVED BY:	WM TITLE DU	L. Dup	2001500 DATE	6/3/2013	
v			JUN 0 3	2015' MB	



TD: 4738' MD