Submit 3 Copies To Appropriate District	State of New Me	xico	Form C-103
Office District I	Energy, Minerals and Natu	ral Resources	May 27, 2004
1625 N. French Dr., Hobbs, NM 88240			WELL API NO. 30-025-37429
<u>District II</u> 1301 W. Grand Ave., Artesia, NM 88210	OIL CONSERVATION		5. Indicate Type of Lease
District III	1220 South St. Fran		STATE FEE
1000 Rio Brazos Rd., Aztec, NM 87410 District IV	Santa Fe, NM 87	7505	6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM			E1582-4
87505 SUNDRY NOTI	CES AND REPORTS ON WELLS		7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPO	SALS TO DRILL OR TO DEEPEN OR PLU	JG BACK TO A	South Vacuum
DIFFERENT RESERVOIR. USE "APPLIC PROPOSALS.)	CATION FOR PERMIT (FORM C-101) FO	K SUCH	8. Well Number 221
1. Type of Well: Oil Well	Gas Well 🛛 Other		
2. Name of Operator			9. OGRID Number 164070
Paladin Energy Corp. 3. Address of Operator			10. Pool name or Wildcat
10290 Monroe Drive, Suite 301 Da	illas, TX 75229		Vacuum McKee, South
Well Location			
	10 feet from the South	line and 1	650 feet from theWestline
Section 22	Township 18-S	Range 35-H	E NMPM Lea County
	11. Elevation (Show whether DR	RKB, RT, GR, etc.	
	3901'		
Pit or Below-grade Tank Application 🛛 o			5
Pit typeDepth to Groundwater_60'			nce from nearest surface water_more than 1500'
	il Below-Grade Tank: Volume		s; Construction Material synthetic
12. Check	Appropriate Box to Indicate N	fature of Notice,	Report or Other Data
NOTICE OF IN	ITENTION TO:	i SUB	SEQUENT REPORT OF:
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WOR	
TEMPORARILY ABANDON	CHANGE PLANS		ILLING OPNS. P AND A
PULL OR ALTER CASING	MULTIPLE COMPL	CASING/CEMEN	IT JOB
		OTUED	П
OTHER:	sloted energtions (Clearly state all	OTHER:	nd give pertinent dates, including estimated dat
13. Describe proposed or comp	oleted operations. (Clearly state all ork). SEE RULE 1103. For Multir	pertinent details, ar	ttach wellbore diagram of proposed completion
13. Describe proposed or comp	oleted operations. (Clearly state all ork). SEE RULE 1103. For Multip	pertinent details, ar	nd give pertinent dates, including estimated dat ttach wellbore diagram of proposed completion
13. Describe proposed or comp of starting any proposed w	oleted operations. (Clearly state all ork). SEE RULE 1103. For Multip	pertinent details, ar	ttach wellbore diagram of proposed completion
13. Describe proposed or comp of starting any proposed we or recompletion.	ork). SEE RULE 1103. For Multip	pertinent details, and le Completions: A	ttach wellbore diagram of proposed completion
13. Describe proposed or composed we or recompletion. 10/20/05 TIH w/285 jts 7" 29# casis	ork). SEE RULE 1103. For Multip	pertinent details, and le Completions: A	ttach wellbore diagram of proposed completion
13. Describe proposed or comp of starting any proposed we or recompletion.	ork). SEE RULE 1103. For Multip ng. Circulate and wash casing to 12 t 7" csg,	pertinent details, and le Completions: A	ttach wellbore diagram of proposed completion
13. Describe proposed or composed was or recompletion. 10/20/05 TIH w/285 jts 7" 29# casis 10/21/05 RU Schlumberger cement 1st stage, 125 sks 50:50 poz; "H"+5 2nd stage lead, 130 sks 35:65 poz "l	ork). SEE RULE 1103. For Multip ng. Circulate and wash casing to 12 t 7" csg, % D44 +2% D20 +3% D800+ .2% H"+5% D44 +6% D20 +6%D112 +	pertinent details, and le Completions: A 2,745'. D167. 2% D46 +5% D79	+.35% D800,
13. Describe proposed or composed was or recompletion. 10/20/05 TIH w/285 jts 7" 29# casis 10/21/05 RU Schlumberger cement 1st stage, 125 sks 50:50 poz; "H"+5 2nd stage lead, 130 sks 35:65 poz "l 2nd stage tail, 520 sks 50:50 poz; "I	ork). SEE RULE 1103. For Multipung. Circulate and wash casing to 12 t 7" csg, % D44 +2% D20 +3% D800+ .2% H"+5% D44 +6% D20 +6%D112 + H" +5%D44 +2%D20 +.3%D800 +	pertinent details, and le Completions: A c.,745°. D1672% D46 +5% D79 .05 gps D801.	+.35% D800,
of starting any proposed or composed was or recompletion. 10/20/05 TIH w/285 jts 7" 29# casis 10/21/05 RU Schlumberger cemen 1st stage, 125 sks 50:50 poz; "H"+5 2nd stage lead, 130 sks 35:65 poz; "I 2nd stage tail, 520 sks 50:50 poz; "I 3rd stage lead, 340 sks 35:65 poz, "	ork). SEE RULE 1103. For Multipung. Circulate and wash casing to 12 t 7" csg, % D44 +2% D20 +3% D800+ .2% H"+5% D44 +6% D20 +6%D112 + H"+5%D44 +2%D20 +.3%D800 + H"+5%D44 +6%D20 +.6%D112+	pertinent details, and le Completions: A c.,745°. D1672% D46 +5% D79 .05 gps D801.	+.35% D800,
of starting any proposed we or recompletion. 10/20/05 TIH w/285 jts 7" 29# casis 10/21/05 RU Schlumberger cemen 1st stage, 125 sks 50:50 poz; "H"+5 2nd stage lead, 130 sks 35:65 poz; "I 2nd stage tail, 520 sks 50:50 poz; "I 3rd stage lead, 340 sks 35:65 poz, "3rd stage tail, 100 sks 50:50 poz "H"	ng. Circulate and wash casing to 12 t 7" csg, % D44 +2% D20 +3% D800+ .2% H"+5% D44 +6% D20 +6%D112 + H" +5%D44 +2%D20 +.3%D800 + H"+5%D44 +2%D20 +.6%D112+ +5%D44 +2%D20 +.2% D800.	pertinent details, and le Completions: A c.,745°. D1672% D46 +5% D79 .05 gps D801.	+.35% D800,
of starting any proposed or composed was or recompletion. 10/20/05 TIH w/285 jts 7" 29# casis 10/21/05 RU Schlumberger cemen 1st stage, 125 sks 50:50 poz; "H"+5 2nd stage lead, 130 sks 35:65 poz; "I 2nd stage tail, 520 sks 50:50 poz; "I 3rd stage lead, 340 sks 35:65 poz, "	ng. Circulate and wash casing to 12 t 7" csg, % D44 +2% D20 +3% D800+ .2% H"+5% D44 +6% D20 +6%D112 + H"+5%D44 +6%D20 +.6%D112+ . +5%D44 + 2%D20 +.6%D112+ . +5%D44 + 2%D20 +.2% D800. ge. Casing set @ 12,745'.	pertinent details, an ole Completions: A c.,745'. D1672% D46 +5% D79 .05 gps D801. 2%D46 +.5%D79	+.35% D800,
of starting any proposed we or recompletion. 10/20/05 TIH w/285 jts 7" 29# casis 10/21/05 RU Schlumberger cement 1st stage, 125 sks 50:50 poz; "H"+5 2nd stage lead, 130 sks 35:65 poz; "I 2nd stage tail, 520 sks 50:50 poz; "I 3rd stage lead, 340 sks 35:65 poz, "3rd stage tail, 100 sks 50:50 poz "H" Circ 20 bbls to reserve from 2nd stage ND BOP set slips w/325,000, cut of Prep to drill cement, tag cmt @ 796	ng. Circulate and wash casing to 12 t 7" csg, % D44 +2% D20 +3% D800+ .2% H"+5% D44 +6% D20 +6%D112 + H"+5%D44 +6%D20 +.6%D112+ .5%D44 +2%D20 +.6%D112+ .5%D44 + 2%D20 +.2% D800. ge. Casing set @ 12,745'. ff casing. NU BOP test stack to 3002', drill cmt and DV tool @ 7980'.	pertinent details, an ole Completions: A c.,745'. D1672% D46 +5% D79 .05 gps D801. 2%D46 +.5%D79	+.35% D800, +.05 gps D801,
of starting any proposed we or recompletion. 10/20/05 TIH w/285 jts 7" 29# casis 10/21/05 RU Schlumberger cement 1st stage, 125 sks 50:50 poz; "H"+5 2nd stage lead, 130 sks 35:65 poz; "I 2nd stage tail, 520 sks 50:50 poz; "I 3rd stage lead, 340 sks 35:65 poz, "3rd stage tail, 100 sks 50:50 poz "H" Circ 20 bbls to reserve from 2nd stage ND BOP set slips w/325,000, cut of Prep to drill cement, tag cmt @ 796 10/22/05 PU drill pipe, circ pipe vo	ng. Circulate and wash casing to 12 t 7" csg, % D44 +2% D20 +3% D800+ .2% H"+5% D44 +6% D20 +6%D112 + H"+5%D44 +2%D20 +.3%D800 + H"+5%D44 +2%D20 +.2% D800. se. Casing set @ 12,745'. f casing. NU BOP test stack to 300 2', drill cmt and DV tool @ 7980'. lume, PU drill pipe, tag cmt @ 11,9	pertinent details, an ole Completions: A c.,745'. D1672% D46 +5% D79 .05 gps D801. 2%D46 +.5%D79	+.35% D800,
of starting any proposed we or recompletion. 10/20/05 TIH w/285 jts 7" 29# casis 10/21/05 RU Schlumberger cement 1st stage, 125 sks 50:50 poz; "H"+5 2nd stage lead, 130 sks 35:65 poz; "I 2nd stage tail, 520 sks 50:50 poz; "I 3rd stage lead, 340 sks 35:65 poz; "I 3rd stage tail, 100 sks 50:50 poz; "I Circ 20 bbls to reserve from 2nd stage ND BOP set slips w/325,000, cut of Prep to drill cement, tag cmt @ 796 10/22/05 PU drill pipe, circ pipe vo 12,700' RD lay down machine. Dri	ng. Circulate and wash casing to 12 t 7" csg, % D44 +2% D20 +3% D800+ .2% H"+5% D44 +6% D20 +6%D112 + H"+5%D44 +2%D20 +.3%D800 + .4%D44 + 2%D20 +.2% D800. ge. Casing set @ 12,745'. ff casing. NU BOP test stack to 300 2', drill cmt and DV tool @ 7980'. lume, PU drill pipe, tag cmt @ 11,9 ill cmt and wiper plug.	pertinent details, an le Completions: A 2,745'. D1672% D46 +5% D79 .05 gps D801. 2%D46 +.5%D79	+.35% D800, +.05 gps D801, OV tool @ 12,017'. PU drill pipe, tag cmt @
of starting any proposed we or recompletion. 10/20/05 TIH w/285 jts 7" 29# casis 10/21/05 RU Schlumberger cement 1st stage, 125 sks 50:50 poz; "H"+5 2nd stage lead, 130 sks 35:65 poz; "I 2nd stage tail, 520 sks 50:50 poz; "I 3rd stage lead, 340 sks 35:65 poz; "I 3rd stage tail, 100 sks 50:50 poz "H" Circ 20 bbls to reserve from 2nd stage ND BOP set slips w/325,000, cut of Prep to drill cement, tag cmt @ 796 10/22/05 PU drill pipe, circ pipe vo 12,700' RD lay down machine. Dri 10/23/05 Drill cmt and float color, of	ng. Circulate and wash casing to 12 t 7" csg, % D44 +2% D20 +3% D800+ .2% H"+5% D44 +6% D20 +6%D112 + T" +5%D44 +2%D20 +.3%D800 + H"+5%D44 +2%D20 +.2% D800. ge. Casing set @ 12,745'. If casing. NU BOP test stack to 300 2', drill cmt and DV tool @ 7980'. lume, PU drill pipe, tag cmt @ 11,9 ll cmt and wiper plug. sirc before running gyro, tst casing to	pertinent details, an le Completions: A 2,745'. D1672% D46 +5% D79 .05 gps D801. 2%D46 +.5%D79	+.35% D800, +.05 gps D801,
of starting any proposed we or recompletion. 10/20/05 TIH w/285 jts 7" 29# casis 10/21/05 RU Schlumberger cement 1st stage, 125 sks 50:50 poz; "H"+5 2nd stage lead, 130 sks 35:65 poz; "I 2nd stage tail, 520 sks 50:50 poz; "I 3rd stage lead, 340 sks 35:65 poz; "I 3rd stage tail, 100 sks 50:50 poz; "I Circ 20 bbls to reserve from 2nd stage ND BOP set slips w/325,000, cut of Prep to drill cement, tag cmt @ 796 10/22/05 PU drill pipe, circ pipe vo 12,700' RD lay down machine. Dri	ng. Circulate and wash casing to 12 t 7" csg, % D44 +2% D20 +3% D800+ .2% H"+5% D44 +6% D20 +6%D112 + T" +5%D44 +2%D20 +.3%D800 + H"+5%D44 +2%D20 +.2% D800. ge. Casing set @ 12,745'. If casing. NU BOP test stack to 300 2', drill cmt and DV tool @ 7980'. lume, PU drill pipe, tag cmt @ 11,9 ll cmt and wiper plug. sirc before running gyro, tst casing to	pertinent details, an le Completions: A 2,745'. D1672% D46 +5% D79 .05 gps D801. 2%D46 +.5%D79	+.35% D800, +.05 gps D801, OV tool @ 12,017'. PU drill pipe, tag cmt @
of starting any proposed we or recompletion. 10/20/05 TIH w/285 jts 7" 29# casis 10/21/05 RU Schlumberger cement 1st stage, 125 sks 50:50 poz; "H"+5 2nd stage lead, 130 sks 35:65 poz; "I 2nd stage tail, 520 sks 50:50 poz; "I 3rd stage lead, 340 sks 35:65 poz; "I 3rd stage tail, 100 sks 50:50 poz; "H" Circ 20 bbls to reserve from 2nd stage ND BOP set slips w/325,000, cut of Prep to drill cement, tag cmt @ 796 10/22/05 PU drill pipe, circ pipe vo 12,700' RD lay down machine. Dri 10/23/05 Drill cmt and float color, of float shoe while mudding up. Drill	ng. Circulate and wash casing to 12 t 7" csg, % D44 +2% D20 +3% D800+ .2% H"+5% D44 +6% D20 +6%D112 + H"+5%D44 +2%D20 +.3%D800 + H"+5%D44 +2%D20 +.2% D800. ge. Casing set @ 12,745'. If casing. NU BOP test stack to 300 2', drill cmt and DV tool @ 7980'. lume, PU drill pipe, tag cmt @ 11,9 ill cmt and wiper plug. circ before running gyro, tst casing tahead.	pertinent details, an ole Completions: A c.,745'. D1672% D46 +5% D7905 gps D801. 2%D46 +.5%D79. D0# (OK) 95', drill cmt and E co 1500# (ok). RU	+.35% D800, +.05 gps D801, OV tool @ 12,017'. PU drill pipe, tag cmt @ slick line truck and run gyro. Drill cmt and
of starting any proposed we or recompletion. 10/20/05 TIH w/285 jts 7" 29# casis 10/21/05 RU Schlumberger cement 1st stage, 125 sks 50:50 poz; "H"+5 2nd stage lead, 130 sks 35:65 poz; "I 2nd stage tail, 520 sks 50:50 poz; "I 3rd stage lead, 340 sks 35:65 poz; "I 3rd stage tail, 100 sks 50:50 poz; "H" Circ 20 bbls to reserve from 2nd stage ND BOP set slips w/325,000, cut of Prep to drill cement, tag cmt @ 796 10/22/05 PU drill pipe, circ pipe vo 12,700' RD lay down machine. Dri 10/23/05 Drill cmt and float color, of float shoe while mudding up. Drill I hereby certify that the information	ng. Circulate and wash casing to 12 t 7" csg, % D44 +2% D20 +3% D800+ .2% H"+5% D44 +6% D20 +6%D112 + H"+5%D44 +2%D20 +.3%D800 + H"+5%D44 +2%D20 +.2% D800. ge. Casing set @ 12,745'. If casing. NU BOP test stack to 300 2', drill cmt and DV tool @ 7980'. lume, PU drill pipe, tag cmt @ 11,9 ill cmt and wiper plug. circ before running gyro, tst casing tahead.	pertinent details, and le Completions: A c.,745'. D1672% D46 +5% D7905 gps D801. 2%D46 +.5%D79. D0# (OK) .95', drill cmt and E co 1500# (ok). RU	+.35% D800, +.05 gps D801, OV tool @ 12,017'. PU drill pipe, tag cmt @ slick line truck and run gyro. Drill cmt and ge and belief. I further certify that any pit or below
of starting any proposed we or recompletion. 10/20/05 TIH w/285 jts 7" 29# casis 10/21/05 RU Schlumberger cement 1st stage, 125 sks 50:50 poz; "H"+5 2nd stage lead, 130 sks 35:65 poz; "I 2nd stage tail, 520 sks 50:50 poz; "I 3rd stage lead, 340 sks 35:65 poz; "I 3rd stage tail, 100 sks 50:50 poz; "H" Circ 20 bbls to reserve from 2nd stage ND BOP set slips w/325,000, cut of Prep to drill cement, tag cmt @ 796 10/22/05 PU drill pipe, circ pipe vo 12,700' RD lay down machine. Dri 10/23/05 Drill cmt and float color, of float shoe while mudding up. Drill I hereby certify that the information	ng. Circulate and wash casing to 12 t 7" csg, % D44 +2% D20 +3% D800+ .2% H"+5% D44 +6% D20 +6%D112 + H"+5%D44 +2%D20 +.3%D800 + H"+5%D44 +2%D20 +.2% D800. ge. Casing set @ 12,745'. If casing. NU BOP test stack to 300 2', drill cmt and DV tool @ 7980'. lume, PU drill pipe, tag cmt @ 11,9 ill cmt and wiper plug. circ before running gyro, tst casing to ahead.	pertinent details, an ole Completions: A c.,745'. D1672% D46 +5% D7905 gps D801. 2%D46 +.5%D79. 00# (OK) 95', drill cmt and E co 1500# (ok). RU est of my knowled. A general permit E	+.35% D800, +.05 gps D801, OV tool @ 12,017'. PU drill pipe, tag cmt @ slick line truck and run gyro. Drill cmt and ge and belief. I further certify that any pit or below or an (attached) alternative OCD-approved plan
of starting any proposed we or recompletion. 10/20/05 TIH w/285 jts 7" 29# casis 10/21/05 RU Schlumberger cement 1st stage, 125 sks 50:50 poz; "H"+5 2nd stage lead, 130 sks 35:65 poz; "I 2nd stage tail, 520 sks 50:50 poz; "I 3rd stage lead, 340 sks 35:65 poz; "I 3rd stage tail, 100 sks 50:50 poz; "H" Circ 20 bbls to reserve from 2nd stage ND BOP set slips w/325,000, cut of Prep to drill cement, tag cmt @ 796 10/22/05 PU drill pipe, circ pipe vo 12,700' RD lay down machine. Dri 10/23/05 Drill cmt and float color, of float shoe while mudding up. Drill I hereby certify that the information	ng. Circulate and wash casing to 12 t 7" csg, % D44 +2% D20 +3% D800+ .2% H"+5% D44 +6% D20 +6%D112 + H"+5%D44 +2%D20 +.3%D800 + H"+5%D44 +2%D20 +.2% D800. ge. Casing set @ 12,745'. If casing. NU BOP test stack to 300 2', drill cmt and DV tool @ 7980'. lume, PU drill pipe, tag cmt @ 11,9 ill cmt and wiper plug. circ before running gyro, tst casing to ahead.	pertinent details, an ole Completions: A c.,745'. D1672% D46 +5% D7905 gps D801. 2%D46 +.5%D79. 00# (OK) 95', drill cmt and E co 1500# (ok). RU est of my knowled. A general permit E	+.35% D800, +.05 gps D801, OV tool @ 12,017'. PU drill pipe, tag cmt @ slick line truck and run gyro. Drill cmt and ge and belief. I further certify that any pit or below
13. Describe proposed or compost of starting any proposed we or recompletion. 10/20/05 TIH w/285 jts 7" 29# casis 10/21/05 RU Schlumberger cement 1st stage, 125 sks 50:50 poz; "H"+5 2nd stage lead, 130 sks 35:65 poz; "I 2nd stage tail, 520 sks 50:50 poz; "I 3rd stage lead, 340 sks 35:65 poz, "3rd stage lead, 340 sks 35:65 poz, "Girc 20 bbls to reserve from 2nd stage ND BOP set slips w/325,000, cut of Prep to drill cement, tag cmt @ 796 10/22/05 PU drill pipe, circ pipe vo 12,700' RD lay down machine. Drill 10/23/05 Drill cmt and float color, of float shoe while mudding up. Drill I hereby certify that the information grade tank has been/will be constructed of SIGNATURE	ng. Circulate and wash casing to 12 t 7" csg, % D44 +2% D20 +3% D800+ .2% H"+5% D44 +6% D20 +6%D112 + H"+5%D44 +2%D20 +.3%D800 + H"+5%D44 +2%D20 +.2% D800. ge. Casing set @ 12,745'. If casing. NU BOP test stack to 300 2', drill cmt and DV tool @ 7980'. lume, PU drill pipe, tag cmt @ 11,9 ill cmt and wiper plug. circ before running gyro, tst casing to ahead. TITLE Mana	pertinent details, and le Completions: A le Comp	+.35% D800, +.05 gps D801, OV tool @ 12,017'. PU drill pipe, tag cmt @ slick line truck and run gyro. Drill cmt and ge and belief. I further certify that any pit or below or an (attached) alternative OCD-approved plan portDATE10/25/05
of starting any proposed we or recompletion. 10/20/05 TIH w/285 jts 7" 29# casis 10/21/05 RU Schlumberger cement 1st stage, 125 sks 50:50 poz; "H"+52nd stage lead, 130 sks 35:65 poz; "I 2nd stage tail, 520 sks 50:50 poz; "I 3rd stage lead, 340 sks 35:65 poz, "I 3rd stage tail, 100 sks 50:50 poz; "H" Circ 20 bbls to reserve from 2nd stage ND BOP set slips w/325,000, cut of Prep to drill cement, tag cmt @ 796 10/22/05 PU drill pipe, circ pipe vo 12,700' RD lay down machine. Dri 10/23/05 Drill cmt and float color, of float shoe while mudding up. Drill I hereby certify that the information grade tank has been/will be constructed of	ng. Circulate and wash casing to 12 t 7" csg, % D44 +2% D20 +3% D800+ .2% H"+5% D44 +6% D20 +6%D112 + H"+5%D44 +2%D20 +.3%D800 + H"+5%D44 +2%D20 +.2% D800. ge. Casing set @ 12,745'. If casing. NU BOP test stack to 300 2', drill cmt and DV tool @ 7980'. lume, PU drill pipe, tag cmt @ 11,9 ill cmt and wiper plug. circ before running gyro, tst casing to ahead. TITLE Mana	pertinent details, and le Completions: A le Comp	+.35% D800, +.05 gps D801, OV tool @ 12,017'. PU drill pipe, tag cmt @ slick line truck and run gyro. Drill cmt and ge and belief. I further certify that any pit or below or an (attached) alternative OCD-approved plan
13. Describe proposed or composed starting any proposed we or recompletion. 10/20/05 TIH w/285 jts 7" 29# casin 10/21/05 RU Schlumberger cement 1st stage, 125 sks 50:50 poz; "H"+5 2nd stage lead, 130 sks 35:65 poz; "I 2nd stage tail, 520 sks 50:50 poz; "I 3rd stage lead, 340 sks 35:65 poz, "3rd stage lead, 340 sks 35:65 poz, "I Circ 20 bbls to reserve from 2nd stage ND BOP set slips w/325,000, cut of Prep to drill cement, tag cmt @ 796 10/22/05 PU drill pipe, circ pipe vo 12,700' RD lay down machine. Dri 10/23/05 Drill cmt and float color, of float shoe while mudding up. Drill I hereby certify that the information grade tank has been/will be constructed of SIGNATURE Type or print name Ann Westberry For State Use Only	ng. Circulate and wash casing to 12 to 7" csg, % D44 +2% D20 +3% D800+ .2% A"+5% D44 +6% D20 +6%D112 + A" +5%D44 +2%D20 +.3%D800 + A"+5%D44 +2%D20 +.2% D800. ge. Casing set @ 12,745'. If casing. NU BOP test stack to 300 2', drill cmt and DV tool @ 7980'. lume, PU drill pipe, tag cmt @ 11,9 all cmt and wiper plug. Sirc before running gyro, tst casing tahead. TITLE Mana E-mail address: awestberry	pertinent details, and le Completions: A le Comp	+.35% D800, +.05 gps D801, DV tool @ 12,017'. PU drill pipe, tag cmt @ slick line truck and run gyro. Drill cmt and ge and belief. I further certify that any pit or below or an (attached) alternative OCD-approved plan portDATE10/25/05 m Telephone No.214-654-0132 X4
13. Describe proposed or compost of starting any proposed we or recompletion. 10/20/05 TIH w/285 jts 7" 29# casin 10/21/05 RU Schlumberger cement 1st stage, 125 sks 50:50 poz; "H"+5 2nd stage lead, 130 sks 35:65 poz; "I 2nd stage tail, 520 sks 50:50 poz; "I 3rd stage lead, 340 sks 35:65 poz, "3rd stage lead, 340 sks 35:65 poz, "I Circ 20 bbls to reserve from 2nd stage ND BOP set slips w/325,000, cut of Prep to drill cement, tag cmt @ 796 10/22/05 PU drill pipe, circ pipe vo 12,700' RD lay down machine. Dri 10/23/05 Drill cmt and float color, of float shoe while mudding up. Drill I hereby certify that the information grade tank has been/will be constructed of SIGNATURE	ng. Circulate and wash casing to 12 t 7" csg, % D44 +2% D20 +3% D800+ .2% H"+5% D44 +6% D20 +6%D112 + H"+5%D44 +2%D20 +.3%D800 + H"+5%D44 +2%D20 +.2% D800. ge. Casing set @ 12,745'. If casing. NU BOP test stack to 300 2', drill cmt and DV tool @ 7980'. lume, PU drill pipe, tag cmt @ 11,9 ill cmt and wiper plug. circ before running gyro, tst casing to ahead. TITLE Mana	pertinent details, and le Completions: A le Comp	+.35% D800, +.05 gps D801, OV tool @ 12,017'. PU drill pipe, tag cmt @ slick line truck and run gyro. Drill cmt and ge and belief. I further certify that any pit or below or an (attached) alternative OCD-approved plan portDATE10/25/05