Submit 1 Copy To Appropriate District State of New Mexico Form C-103 Office Revised July 18, 2013 Energy, Minerals and Natural Resources District I - (575) 393-6161 WELL API NO. 1625 N. French Dr., Hobbs, NM 88240 District II - (575) 748-1283 30-025-34696 OIL CONSERVATION DIVISION 811 S. First St., Artesia, NM 88210 5. Indicate Type of Lease District III - (505) 334-6178 1220 South St. Francis Dr. STATE 🖂 1000 Rio Brazos Rd., Aztec, NM 87410 Santa Fe. NM 87505 District IV - (505) 476-3460 6. State Oil & Gas Lease No. 1220 S. St. Francis Dr., Santa Fe, NM SUNDRY NOTICES AND REPORTS ON WELLS 7. Lease Name or Unit Agreement Name (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH MAYFLY 14 STATE COM HOBBS OCD 8. Well Number 3 1. Type of Well: Oil Well Gas Well Other 2. Name of Operator 9. OGRID Number AUG I 4 2015 LEGACY RESERVES OPERATING LP / 240974 3. Address of Operator 10. Pool name or Wildcat PO BOX 10848, MIDLAND, TX 79702 SHOE BAR; STRAWN, NORTHWEST RECEIVED 4. Well Location Unit Letter 228 feet from the NORTH line and 1654 feet from the WEST line' Section Township 16S Range 35E **NMPM** County LEA 11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3982' GL 12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK □ PLUG AND ABANDON REMEDIAL WORK ALTERING CASING [\boxtimes **TEMPORARILY ABANDON** CHANGE PLANS COMMENCE DRILLING OPNS.□ P AND A П MULTIPLE COMPL CASING/CEMENT JOB PULL OR ALTER CASING П DOWNHOLE COMMINGLE П **CLOSED-LOOP SYSTEM** OTHER: OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion. Jul 6-13 2015 MIRU. Unhang well. Unseat pump. POOH w/rods and pump. NUBOP. Release TAC. TOOH w/340 jts tbg.POOH w/remaining 20 jts tbg and found tbg collar parted. PU overshot, grapple, and bumper sub. TIH to top of fish, latch on to fish (2 jts, TAC, 3 jts,4' PS, SN, MJ). Start TOOH w/ fish. TOOH w/tbg and collar on top of TAC come unscrewed. Left TAC and BHA still in hole. RU spear and bumper sub. TIH w/fishing tools. Latch on to fish, release TAC, TOOH w/tbg and BHA. RIH w/tbg and BH assembly. NDBOP. Set TAC (17 pts). NU wellhead. PU repaired rod pump. RIH w/pump and rods. Seared an appropriate tools. well. Loaded the and pressured up to 500 psi-held good w/good pump action. pumping. Left well on Auto. Start well Spud Date: Rig Release Date: I hereby certify that the information above is true and complete to the best of my knowledge and belief. TITLE SENIOR ENGINEER SIGNATURE -DATE 08/11/2015 Type or print name __ KENT WILLIAMS E-mail address: kwilliams@legacylp.com PHONE: 432-689-5200

APPROVED BY:

Conditions of Approval (if any):

For State Use Only

TITLE Petroleum Engineer

DATE 08/14/15