Submit 1 Copy To Appropriate District Office	State of New Mexico		Form C-103	
District I – (575) 393-6161	Energy, Minerals and Natural Resources		Revised July 18, 2013	
1625 N. French Dr., Hobbs, NM 88240			WELL API NO.	
<u>District II</u> – (575) 748-1283	OIL CONSERVATION	DIVISION	30-025-29192	
811 S. First St., Artesia, NM 88210 District III – (505) 334-6178	1220 South St. Fran		5. Indicate Type of Lease	
1000 Rio Brazos Rd., Aztec, NM 87410			STATE 🖾 FEE 🗌	
District IV - (505) 476-3460	Santa Fe, NM 87505		6. State Oil & Gas Lease No.	
1220 S. St. Francis Dr., Santa Fe, NM 87505		HOBBSOCD	E 754	
SUNDRY NOTIO	CES AND REPORTS ON WELLS	0 @ 201F	7. Lease Name or Unit Agreement Name	
SUNDRY NOTIO (DO NOT USE THIS FORM FOR PROPOS DIFFERENT RESERVOIR USE "APPLIC	NORTH VACUUM ABO NORTH UNIT			
DIFFERENT RESERVOIR. USE "APPLIC PROPOSALS.)	ATION FOR PERMIT" (FORM C-101) FC	NK SUCH		
1. Type of Well: Oil Well	Gas Well 🗌 Other INJECTION	WELLOFCEIVED	8. Well Number #3 INJ	
2. Name of Operator			9. OGRID Number 277558	
LIME ROCK RESOURCES II-A, L.P.				
3. Address of Operator			10. Pool name or Wildcat	
c/o Mike Pippin LLC, 3104 N. Sullivan, Farmington, NM 87401			North Vacuum Abo (61760)	
4. Well Location				
Unit Letter <u>O</u> :	460_feet from the <u>South</u>	_ line and <u>1680</u>	feet from the <u>East</u> line	
Section 2	Township 17-S R	Range 34-E	NMPM Lea County	
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 4045' GL				
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data				
NOTICE OF IN	TENTION TO	SUB	SEQUENT REPORT OF:	
PERFORM REMEDIAL WORK		REMEDIAL WORK		
	CHANGE PLANS	COMMENCE DRI		
		CASING/CEMENT		
		ON ON OF OF OF OF		
CLOSED-LOOP SYSTEM				
OTHER:		OTHER: Squeez	e Casing Leak	
	rations. (Clearly state all pertinent details,		including estimated date of starting any proposed work).	
SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.				
Following a failed MIT test, Line Rock squeezed the 4-1/2" csg as follows: On 7/6/15, ran CBL & Casing Inspection Log. CBL				

indicated TOC @ 4600' (see attached CBL section), but spotty cmt deeper in places. The Casing Inspection Log indicated bad 4-1/2" csg @ 5300'-5700'. On 7/20/15, MIRUSU. Retrieved RBP @ 8347' & TOH. Set a 4-1/2" CIBP @ 5820' w/20' cmt on top. Set 4-1/2" cmt ret @ 5520'. Established a rate w/water. SQ holes below retainer w/200 sx "H" cmt. Drilled out cmt from 4990' to 5510'. SQ would not hold pressure. Drilled out cmt ret @ 5520' & fell out of cmt @ 5627'. CO to CIBP @ 5820'. PT csg but would not hold pressure. Using pkr, located small csg leak holes @ 5314'-5721', but holes were too small to establish a rate. Spotted 50 sx cmt @ 5123'-5715' & attempted to stage cmt into the small csg leak holes. Drilled out cmt from 5127'-5785'. Pressure test failed: pressured to 540 psi, which bled off 100 psi in 22 min. TOH & released rig on 7/30/15. Line Rock plans to evaluate the well for additional remedial work.

Spud Date:	3/26/85	Drilling Rig Release Date: April 1985
I hereby certif	fy that the information a	bove is true and complete to the best of my knowledge and belief.
SIGNATURE		TITLE Petroleum Engineer - Agent DATE 8/19/15
Type or print	name Mike Pippi	E-mail address: <u>mike@pippinllc.com</u> PHONE: <u>505-327-4573</u>
For State Us	e.Only	
APPROVED	BY: Makeys	Drown TITLE Dist Supervision DATE 8/24/2015
Conditions of	Approval (if any):	