Submit 3 Copies To Appropriate District	State of New	Mexico	Form C	-103
Office District I	Energy, Minerals and 1		May 27.	
1625 N. French Dr., Hobbs, NM 88240 District II			WELL API NO.	
1301 W. Grand Ave., Artesia, NM 88210	OIL CONSERVAT	ON DIVISION	30-025-09639	
<u>District III</u> 1000 Rio Brazos Rd., Aztec, NM 87410	1220 South St. Francis Dr.		5. Indicate Type of Lease STATE FEE	ed
District IV	Santa Fe, NN	A 87505	6. State Oil & Gas Lease No.	
1220 S. St. Francis Dr., Santa Fe, NM 87505			NM 12612	
SUNDRY NOT	TICES AND REPORTS ON WE	LLS	7. Lease Name or Unit Agreement Na	me
DIFFERENT RESERVOIR. USF "APPL	(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH			
PROPOSALS.)			NM 70962X	
1. Type of Well: Oil Well	Gas Well Other In	ector 🔀	8. Well Number Cooper Jal Unit 132	
2. Name of Operator	SDG Resources L. P.		9. OGRID Number 193003	
3. Address of Operator	P. O. Box 1390		10. Pool name or Wildcat JALMA	т.
•	Montrose, CO 81402		Tansill, Yates & 7-Rivers	.1.
			,	
4. Well Location	*			
Unit LetterI2	2310feet from theSOUTH	line and 660	feet from theEAST line	
Section 24	Township 24S	Range 37E	NMPM LEA County	
	11. Elevation (Show whether			
Pit or Below-grade Tank Application	3,30	7' GL		
1			Distance from nearest surface water_>1000 fee	t
			n Material Synthetic	
12. Check	Appropriate Box to Indicat	e Nature of Notice, l	Report or Other Data	
NOTICE OF I	NTENTION TO:	SUBS	SEQUENT REPORT OF:	
PERFORM REMEDIAL WORK \Box		REMEDIAL WORK		;
TEMPORARILY ABANDON		COMMENCE DRIL		
PULL OR ALTER CASING		CASING/CEMENT	JOB	
OTHER: Perform Step-Rate Test.		OTHER:	give pertinent dates, including estimate	
of starting any proposed w	ork). SEE RULE 1103. For Mi	an periment details, and altiple Completions. Att	ach wellbore diagram of proposed comp	d date
or recompletion.		ample Completions. 7th	den wendere diagram of proposed comp	iction
Objective: Perform Step-Rate	Test.			
1. Shut well in 24 hours prior to	toat			
2. R.U. Arc Pressure Data, Inc.	test.		022425	
3. RIH with pressure bomb and l	ocate at mid-perfs.		222225263	
4. Start injection at 100 bwpd for	. 1 1			
5. Ramp rates up at 100 – 200 by	vpd increments per hour.		TO A CO	
Note: Obtain at least 3 points before	wpd increments per hour. ore parting pressure and $3-4$ po	ints after parting pressure	e. S S S S	\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \
Note: Obtain at least 3 points before Note: Maximum rate should be 10	wpd increments per hour. ore parting pressure and 3 – 4 po 000 bwpd.	ints after parting pressur	e. 2	· · ·
Note: Obtain at least 3 points before Maximum rate should be 10	wpd increments per hour. ore parting pressure and 3 – 4 po 000 bwpd. D. Arc Pressure Data, Inc.	ints after parting pressur	e. (200)	•
Note: Obtain at least 3 points before Note: Maximum rate should be 10. 6. POOH with pressure bomb. R	wpd increments per hour. ore parting pressure and 3 – 4 po 000 bwpd. D. Arc Pressure Data, Inc.	ints after parting pressur	e. (2) (3) (3) (3) (4) (4) (4) (4) (4) (4) (4) (4) (4) (4	
Note: Obtain at least 3 points before Note: Maximum rate should be 10 common POOH with pressure bomb. R 7. Place well on injection at 420	wpd increments per hour. ore parting pressure and 3 – 4 po 000 bwpd. D. Arc Pressure Data, Inc. bwpd.		19 5 17 01 2 2 2 2 3 3 5 5 7 1	
Note: Obtain at least 3 points before Note: Maximum rate should be 10 6. POOH with pressure bomb. R 7. Place well on injection at 420 I hereby certify that the information	wpd increments per hour. ore parting pressure and 3 – 4 po 000 bwpd. D. Arc Pressure Data, Inc. bwpd.	ne best of my knowledge	and belief. I further certify that any pit or l	pelow-
Note: Obtain at least 3 points before Note: Maximum rate should be 10 6. POOH with pressure bomb. R 7. Place well on injection at 420 I hereby certify that the information	wpd increments per hour. ore parting pressure and 3 – 4 po 000 bwpd. D. Arc Pressure Data, Inc. bwpd.	ne best of my knowledge	19 5 17 01 2 2 2 2 3 3 5 5 7 1	pelow- an □.
Note: Obtain at least 3 points before Note: Maximum rate should be 10 6. POOH with pressure bomb. R 7. Place well on injection at 420 I hereby certify that the information	wpd increments per hour. ore parting pressure and 3 – 4 po 000 bwpd. D. Arc Pressure Data, Inc. bwpd. above is true and complete to the closed according to NMOCD guidely	ne best of my knowledge	and belief. I further certify that any pit or I or an (attached) alternative OCD-approved pl	an □.
Note: Obtain at least 3 points before Note: Maximum rate should be 10 for POOH with pressure bomb. R. 7. Place well on injection at 420 I hereby certify that the information grade tank has been/will be constructed of SIGNATURE Communication.	wpd increments per hour. ore parting pressure and 3 – 4 po 100 bwpd. D. Arc Pressure Data, Inc. bwpd. above is true and complete to the closed according to NMOCD guidel Caryales TITL	ne best of my knowledge ines	and belief. I further certify that any pit or I or an (attached) alternative OCD-approved plugineer DATE_11/10/05	an □. ;_
Note: Obtain at least 3 points before Note: Maximum rate should be 10 for POOH with pressure bomb. R. 7. Place well on injection at 420 I hereby certify that the information grade tank has been/will be constructed of SIGNATURE Contracts. Type or print name	wpd increments per hour. ore parting pressure and 3 – 4 po 100 bwpd. D. Arc Pressure Data, Inc. bwpd. above is true and complete to the closed according to NMOCD guidel Caryales TITL	ne best of my knowledge ines , a general permit E_Senior Petroleum En	and belief. I further certify that any pit or I or an (attached) alternative OCD-approved plagineerDATE_11/10/05	an □. ;_
Note: Obtain at least 3 points before Note: Maximum rate should be 10 for POOH with pressure bomb. R. 7. Place well on injection at 420 I hereby certify that the information grade tank has been/will be constructed of SIGNATURE Communication.	wpd increments per hour. ore parting pressure and 3 – 4 po 100 bwpd. D. Arc Pressure Data, Inc. bwpd. above is true and complete to the closed according to NMOCD guidel Caryales TITL	ne best of my knowledge ines , a general permit E_Senior Petroleum En	and belief. I further certify that any pit or I or an (attached) alternative OCD-approved plagineerDATE_11/10/05	an □. ;_
Note: Obtain at least 3 points before Note: Maximum rate should be 106. POOH with pressure bomb. R. 7. Place well on injection at 420 I hereby certify that the information grade tank has been/will be constructed of SIGNATURE Type or print name For State Use Only APPROVED BY:	wpd increments per hour. ore parting pressure and 3 – 4 po 100 bwpd. D. Arc Pressure Data, Inc. bwpd. above is true and complete to the closed according to NMOCD guidel Caryales TITL	ne best of my knowledge ines , a general permit E_Senior Petroleum En pse: Penningo@sdgresour	and belief. I further certify that any pit or I or an (attached) alternative OCD-approved plugineer DATE_11/10/05	an □. ;_
Note: Obtain at least 3 points before Note: Maximum rate should be 106. POOH with pressure bomb. R. 7. Place well on injection at 420 I hereby certify that the information grade tank has been/will be constructed of SIGNATURE Type or print name For State Use Only	wpd increments per hour. ore parting pressure and 3 – 4 po 1000 bwpd. D. Arc Pressure Data, Inc. bwpd. above is true and complete to the closed according to NMOCD guidel Conjugate TITL Emails and complete to the complete to the closed according to NMOCD guidely.	ne best of my knowledge ines , a general permit E_Senior Petroleum En pse: Penningo@sdgresour	and belief. I further certify that any pit or I or an (attached) alternative OCD-approved plugineer DATE_11/10/05 rces.com Telephone No. 432-580-850 TAFF MANAGNOV 1 4 2005	an □. ;_

