New Mexico Oil Conservation Division, District I 1625 N. French Drive

Form 3160-5 (August 1999)

UNITED STATES

DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

Hobbs, NM 88240 ONCX

FORM APPROVED OMB No. 1004-0135 Expires November 30, 2000

Request **SUNDRY NOTICES AND REPORTS ON WELLS**

Do not use this form for proposals to drill or to re-enter an

LC064118

If Indian, Allottee or Tribe Name

Lease Serial No.

abandoned well. Use Form 3160-3 (APD) for such proposals.		
SUBMIT IN TRIPLICATE - Other ins	7. If Unit or CA/Agreement, Name and/or No.	
1. Type of Well ☐ Oil Well ☐ Gas Well ☒ Other અ		8. Well Name and No. E C HILL B FEDERAL #006
2. Name of Operator Latigo Petroleum, Inc.		9. API Well No. 30-025-10969
3a. Address 550 W. Texas, Suite 700 Midland TX 79701	3b. Phone No. (include area code) (432)684-4293	10. Field and Pool, or Exploratory Area
4. Location of Well (Footage, Sec., T., R., M., or Survey Description) 1980' FNL & 810' FWL SEC 35(E) T23S, R37E		TEAGUE; PADDOCK-BLINEBRY; SIMPS 11. County or Parish, State LEA NM
12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE	E, REPORT, OR OTHER DATA
TYPE OF SUBMISSION	TYPE OF ACTION	

Notice of Intent ☐ Fracture Treat Reclamation Well Integrity Alter Casing Other . Recomplete ☐ Subsequent Report New Construction Casing Repair Temporarily Abandon **Change Plans** Plug and Abandon ☐ Final Abandonment Notice Water Disposal П Plug Back Convert to Injection 13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof.

Deepen

Production (Start/ Resume)

If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)

- 1. Set 7" cement retainer @ 7350'. Squeeze w/100 sx "C" cement. Cap w/20' cement.
- 2. Circulate hole w/ 10# mud to surface.
- 3. Perf & squeeze @ 4800' w/50 sx "C" cement , leaving 50' cement in casing.
- 4. Cut & pull 7" casing @ 2906'. Spot 40 sx "C" cement plug @ 2956'.
- 5. Spot 40 sx "C" cement plug @ 1250'.6. Spot 40 sx "C" cement plug @ 370'.
- 7. Spot 20 sx "C" cement plug from 60' to surface.
- 8. Cut off wellhead 3' below ground level. Set dry hole marker.

fraudulent statements or representations as to any matter within its jurisdiction.

 \Box

Acidize

9. Clean and level location.

TYPE OF SUBMISSION



☐ Water Shut-Off

 I hereby certify that the foregoing is true and correct Name (Printed/Typed) Lisa Hunt 	Title Regulatory Analyst
Signature Triangle Advance A	Date 11/14/2005
THIS SPACE I	FOR FEDERAL OR STATE OFFICE USE
Approved by ADEKG SGD.I DAVID R. GLASS	Date NOV 1 5 2005
Conditions of approval, if any, are attached. Approval of this noticertify that the applicant holds legal or equitable title to those right which would entitle the applicant to conduct operations thereon.	