Submit 3 Copies To Appropriate District Office	State of New Mexico		Form C-103
District I 1625 N. French Dr., Hobbs, NM 88240	Energy, Minerals and Natural Resources		May 27, 2004 WELL API NO.
District II	OIL CONSERVATIO	N DIVISION	30-025-12512
1301 W. Grand Ave., Artesia, NM 88210 District III	1220 South St. Francis Dr.		5. Indicate Type of Lease
1000 Rio Brazos Rd., Aztec, NM 87410	Santa Fe, NM 87505		STATE X FEE 6. State Oil & Gas Lease No.
District IV 1220 S. St. Francis Dr., Santa Fe, NM	,		B-3290
87505 SUNDRY NOTICES AND REPORTS ON WELLS		7. Lease Name or Unit Agreement Name	
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH			
PROPOSALS.)		MEXICO "U" 8. Well Number 1	
1. Type of Well: Oil Well X Gas Well Other			9. OGRID Number
2. Name of Operator XERIC OIL & GAS CORPORATION		9. OGRID Number 025482	
3. Address of Operator		10. Pool name or Wildcat	
P. O. BOX 352, MIDLAND, TX 79702		Hobbs Grayburg San Andres	
4. Well Location			
Unit Letter B: 330 feet from the North line and 1650 feet from the East line Section 8 Township 19S Range 38E NMPM County Lea			
Section 8 Township 19S Range 38E NMPM County Lea 11. Elevation (Show whether DR, RKB, RT, GR, etc.)			
Pit or Below-grade Tank Application or Closure			
Pit typeDepth to GroundwaterDistance from nearest fresh water wellDistance from nearest surface water			
Pit Liner Thickness: mil Below-Grade Tank: Volume bbls; Construction Material			
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data			
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:			
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING			K ALTERING CASING
TEMPORARILY ABANDON ☐ CHANGE PLANS ☒ COMMENCE DRILLING OPNS.☐ P AND A ☐			
PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMENT JOB			
OTHER:			
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date			
of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.			
THE OIL CONSERVATION DIVISION MUST			
BE NOTIFIED 24 HOURS PRIOR TO THE			
		BEGINNING OF	F PLUGGING OPERATIONS.
1. MIRU Pulling Unit			
 Tag top of fish @ ± 1900'. Circulate hole w/9.65# fresh water mud. 			
4. Set cement retainer @ ± 1700' and squeeze 100 sx through retainer.			
5. Spot 50 sx cmt @ top of retainer and tag plug.			
6 Snot 50 sx cmt 500' & circulate to surface			
7. RD Pulling Unit, install dry hole marker & clean location.			
7. RD Pulling Unit, install dry hole marker & clean location. Wellbore Diagram Attached Period No. 100 No.			
			\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\
			ge and belief. I further certify that any nit or below-
I hereby coultry that the internation above is trac and complete to the cost of my knowledge and context. I further termy that any pit of below-			
grade tank has been/will be constructed or closed according to NMOCD guidelines [], a general permit [] or an (attached) alternative OCD-approved plan [].			
SIGNATURE (MOSU)	Agustard TITLE	Production Ana	Alyst DATE ///0/05
Type or print name Angie Crawford E-mail address: Acrawford@xogoperating.com Telephone No. 432-683-3171			
For State Use Only			
APPROVED BY: James Conditions of Annual Conditions			
Conditions of Approval (if any): NUV 2 2 2005			
V			·

XERIC OIL & GAS CORP. WELLBORE DIAGRAM


WELL: Mexico U#1 COUNTY: Lea

STATE: NM

CASING: 5/2" @3983

CEMENTED WITH: 3005

CEMENT TOP:



PBTD: 4075

TD: 4075