Office Energy, Minerals and	ew Mexico Natural Resources	Form C-103 May 27, 2004
District 1		WELL API NO.
1625 N. French Dr., Hobbs, NM 87240 District II OIL CONSEDIVA	THOM DIVIGION	30-025-37476
1301 W. Grand Ave., Artesia, NM 88210 1220 South St. Francis Dr.		5. Indicate Type of Lease
		STATE 🔀 FEE 🗆
1000 Rio Brazos Rd., Aztec, NM 87410 Santa Fe, District IV	NM 87505	
1220 S. St. Francis Dr., Santa Fe, NM 87505		6. State Oil & Gas Lease No.
SUNDRY NOTICES AND REPORTS ON WELLS [(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH		7. Lease Name or Unit Agreement Name:
PROPOSALS.)		EK 7 State
1. Type of Well:		8. Well Number
Oil Well X Gas Well Other		1
2. Name of Operator		9. OGRID Number
EOG Resources Inc.		7377
3. Address of Operator		10. Pool name or Wildcat
P.O. Box 2267 Midland, Texas 79702		Mescalero Escarpe; Bone Spring
4. Well Location		
Unit Letter N : 440 feet from the South line and 1980 feet from the West line		
L	8S Range 34E	NMPM County Lea
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 4072 GR		
Pit or Below-grade Tank Application or Closure		
Pit type Depth to Groundwater Distance from near	est fresh water well Dis	tance from nearest surface water
	olumebbls; Construction	
12. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data		
12. Check Appropriate Box to Inc	dicate Nature of Notice,	Report, or Other Data
NOTICE OF INTENTION TO:		•
	SUB	Report, or Other Data SEQUENT REPORT OF: ALTERING CASING
NOTICE OF INTENTION TO:	SUB	SEQUENT REPORT OF: ALTERING CASING NG OPNS. PLUG AND
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON	SUB REMEDIAL WORK	SEQUENT REPORT OF: ALTERING CASING
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON TEMPORARILY ABANDON CHANGE PLANS PULL OR ALTER CASING MULTIPLE COMPLETION	SUB REMEDIAL WORK COMMENCE DRILLI CASING TEST AND CEMENT JOB	SEQUENT REPORT OF: ALTERING CASING NG OPNS. PLUG AND ABANDONMENT
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON TEMPORARILY ABANDON CHANGE PLANS PULL OR ALTER CASING MULTIPLE COMPLETION OTHER:	SUB REMEDIAL WORK COMMENCE DRILLI CASING TEST AND CEMENT JOB OTHER:	SEQUENT REPORT OF: ALTERING CASING NG OPNS. PLUG AND ABANDONMENT X
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON TEMPORARILY ABANDON CHANGE PLANS PULL OR ALTER CASING MULTIPLE COMPLETION	SUB REMEDIAL WORK COMMENCE DRILLI CASING TEST AND CEMENT JOB OTHER: all pertinent details, and give	SEQUENT REPORT OF: ALTERING CASING NG OPNS. PLUG AND ABANDONMENT X e pertinent dates, including estimated date
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON TEMPORARILY ABANDON CHANGE PLANS PULL OR ALTER CASING MULTIPLE COMPLETION OTHER: 13. Describe proposed or completed operations. (Clearly state of starting any proposed work). SEE RULE 1103. For Mor recompletion. 11/10/05 Spud well.	SUB REMEDIAL WORK COMMENCE DRILLI CASING TEST AND CEMENT JOB OTHER: all pertinent details, and give fultiple Completions: Attach	SEQUENT REPORT OF: ALTERING CASING NG OPNS. PLUG AND ABANDONMENT X e pertinent dates, including estimated date
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON TEMPORARILY ABANDON CHANGE PLANS PULL OR ALTER CASING MULTIPLE COMPLETION OTHER: 13. Describe proposed or completed operations. (Clearly state of starting any proposed work). SEE RULE 1103. For Mor recompletion. 11/10/05 Spud well. Ran 12 jts 11 3/4, 42 #, H-40 surface	SUB REMEDIAL WORK COMMENCE DRILLI CASING TEST AND CEMENT JOB OTHER: all pertinent details, and give fultiple Completions: Attach	SEQUENT REPORT OF: ALTERING CASING NG OPNS. PLUG AND ABANDONMENT E pertinent dates, including estimated dates wellbore diagram of proposed completion
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON TEMPORARILY ABANDON CHANGE PLANS PULL OR ALTER CASING MULTIPLE COMPLETION OTHER: 13. Describe proposed or completed operations. (Clearly state of starting any proposed work). SEE RULE 1103. For Mor recompletion. 11/10/05 Spud well. Ran 12 jts 11 3/4, 42 #, H-40 surface Cemented w/ 345 sx Class C + 2 % Cacc	SUB REMEDIAL WORK COMMENCE DRILLI CASING TEST AND CEMENT JOB OTHER: all pertinent details, and give fultiple Completions: Attach	SEQUENT REPORT OF: ALTERING CASING NG OPNS. PLUG AND ABANDONMENT E pertinent dates, including estimated date wellbore diagram of proposed completion Sex. CIRC 51 sex to surface.
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON TEMPORARILY ABANDON CHANGE PLANS PULL OR ALTER CASING MULTIPLE COMPLETION OTHER: 13. Describe proposed or completed operations. (Clearly state of starting any proposed work). SEE RULE 1103. For Mor recompletion. 11/10/05 Spud well. Ran 12 jts 11 3/4, 42 #, H-40 surface Cemented w/ 345 sx Class C + 2 % Cac WCC 12 hrs. Tested casing to 1000 p	SUB REMEDIAL WORK COMMENCE DRILLI CASING TEST AND CEMENT JOB OTHER: all pertinent details, and give fultiple Completions: Attach	SEQUENT REPORT OF: ALTERING CASING NG OPNS. PLUG AND ABANDONMENT E pertinent dates, including estimated date wellbore diagram of proposed completion Sex. CIRC 51 sex to surface.
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON TEMPORARILY ABANDON CHANGE PLANS PULL OR ALTER CASING MULTIPLE COMPLETION OTHER: 13. Describe proposed or completed operations. (Clearly state of starting any proposed work). SEE RULE 1103. For Mor recompletion. 11/10/05 Spud well. Ran 12 jts 11 3/4, 42 #, H-40 surface Cemented w/ 345 sx Class C + 2 % Cac WCC 12 hrs. Tested casing to 1000 p 11/13/05 Ran 75 jts 8 5/8", 32 #, J-55 casing	SUB REMEDIAL WORK COMMENCE DRILLI CASING TEST AND CEMENT JOB OTHER: all pertinent details, and give fultiple Completions: Attach e casing set @ 520'. 1, 14.8 ppg, 1.32 cuft/ si for 30 min. Test go set @ 3305'.	SEQUENT REPORT OF: ALTERING CASING NG OPNS. PLUG AND ABANDONMENT Experiment dates, including estimated dates wellbore diagram of proposed completion Sex. CIRC 51 sx to surface.
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON TEMPORARILY ABANDON CHANGE PLANS PULL OR ALTER CASING MULTIPLE COMPLETION OTHER: 13. Describe proposed or completed operations. (Clearly state of starting any proposed work). SEE RULE 1103. For Mor recompletion. 11/10/05 Spud well. Ran 12 jts 11 3/4, 42 #, H-40 surface Cemented w/ 345 sx Class C + 2 % CaC WOC 12 hrs. Tested casing to 1000 p 11/13/05 Ran 75 jts 8 5/8", 32 #, J-55 casing Cemented w/ 500 sx 50:50 POZ C, 11.9	SUB REMEDIAL WORK COMMENCE DRILLI CASING TEST AND CEMENT JOB OTHER: all pertinent details, and give fultiple Completions: Attach e casing set @ 520'. 1, 14.8 ppg, 1.32 cuft/ si for 30 min. Test go set @ 3305'.	SEQUENT REPORT OF: ALTERING CASING NG OPNS. PLUG AND ABANDONMENT Experiment dates, including estimated dates wellbore diagram of proposed completion Sex. CIRC 51 sx to surface.
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON TEMPORARILY ABANDON CHANGE PLANS PULL OR ALTER CASING MULTIPLE COMPLETION OTHER: 13. Describe proposed or completed operations. (Clearly state of starting any proposed work). SEE RULE 1103. For Mor recompletion. 11/10/05 Spud well. Ran 12 jts 11 3/4, 42 #, H-40 surface Cemented w/ 345 sx Class C + 2 % Cac WCC 12 hrs. Tested casing to 1000 p 11/13/05 Ran 75 jts 8 5/8", 32 #, J-55 casing	SUB REMEDIAL WORK COMMENCE DRILLI CASING TEST AND CEMENT JOB OTHER: call pertinent details, and give fultiple Completions: Attach se casing set @ 520'. 1, 14.8 ppg, 1.32 cuft/ si for 30 min. Test go set @ 3305'. 1 ppg, 2.62 cuft/sx; 250	SEQUENT REPORT OF: ALTERING CASING NG OPNS. PLUG AND ABANDONMENT Experiment dates, including estimated dates wellbore diagram of proposed completion Sex. CIRC 51 sx to surface.
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON TEMPORARILY ABANDON CHANGE PLANS PULL OR ALTER CASING MULTIPLE COMPLETION OTHER: 13. Describe proposed or completed operations. (Clearly state of starting any proposed work). SEE RULE 1103. For Mor recompletion. 11/10/05 Spud well. Ran 12 jts 11 3/4, 42 #, H-40 surface Cemented w/ 345 sx Class C + 2 % Cac WCC 12 hrs. Tested casing to 1000 p 11/13/05 Ran 75 jts 8 5/8", 32 #, J-55 casing Cemented w/ 500 sx 50:50 POZ C, 11.9 CIRC 68 sx to surface. WCC 17 hrs. 11/14/05 tested casing to 2000 psi for 30 min I hereby certify that the jaformation above is true and complete	SUB REMEDIAL WORK COMMENCE DRILLI CASING TEST AND CEMENT JOB OTHER: all pertinent details, and give fultiple Completions: Attach se casing set @ 520'. 1, 14.8 ppg, 1.32 cuft/ si for 30 min. Test go set @ 3305'. ppg, 2.62 cuft/sx; 250 to the best of my knowledge	SEQUENT REPORT OF: ALTERING CASING NG OPNS. PLUG AND ABANDONMENT Expertinent dates, including estimated date wellbore diagram of proposed completion Sex. CIRC 51 sex to surface. Sex. CIRC 51 sex to surface. Sex. Class C, 14.8 ppg, 1.33 cuft/sex.
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON TEMPORARILY ABANDON CHANGE PLANS PULL OR ALTER CASING MULTIPLE COMPLETION OTHER: 13. Describe proposed or completed operations. (Clearly state of starting any proposed work). SEE RULE 1103. For Mor recompletion. 11/10/05 Spud well. Ran 12 jts 11 3/4, 42 #, H-40 surface Cemented w/ 345 sx Class C + 2 % Cac WCC 12 hrs. Tested casing to 1000 p 11/13/05 Ran 75 jts 8 5/8", 32 #, J-55 casing Cemented w/ 500 sx 50:50 POZ C, 11.9 CIRC 68 sx to surface. WCC 17 hrs. 11/14/05 tested casing to 2000 psi for 30 min	SUB REMEDIAL WORK COMMENCE DRILLI CASING TEST AND CEMENT JOB OTHER: all pertinent details, and give fultiple Completions: Attach se casing set @ 520'. 1, 14.8 ppg, 1.32 cuft/ si for 30 min. Test go set @ 3305'. ppg, 2.62 cuft/sx; 250 to the best of my knowledge	SEQUENT REPORT OF: ALTERING CASING NG OPNS. PLUG AND ABANDONMENT Expertinent dates, including estimated date wellbore diagram of proposed completion Sex. CIRC 51 sex to surface. Sex. CIRC 51 sex to surface. Sex. Class C, 14.8 ppg, 1.33 cuft/sex.
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON TEMPORARILY ABANDON CHANGE PLANS PULL OR ALTER CASING MULTIPLE COMPLETION OTHER: 13. Describe proposed or completed operations. (Clearly state of starting any proposed work). SEE RULE 1103. For Mor recompletion. 11/10/05 Spud well. Ran 12 jts 11 3/4, 42 #, H-40 surface Cemented w/ 345 sx Class C + 2 % Cac WCC 12 hrs. Tested casing to 1000 p 11/13/05 Ran 75 jts 8 5/8", 32 #, J-55 casing Cemented w/ 500 sx 50:50 POZ C, 11.9 CIRC 68 sx to surface. WCC 17 hrs. 11/14/05 tested casing to 2000 psi for 30 min I hereby certify that the information above is true and complete grade tank has been/will be constructed or closed according to NMOCD grade tank has been/will be constructed or closed according to NMOCD grade tank has been/will be constructed or closed according to NMOCD grade tank has been/will be constructed or closed according to NMOCD grade tank has been/will be constructed or closed according to NMOCD grade tank has been/will be constructed or closed according to NMOCD grade tank has been/will be constructed or closed according to NMOCD grade tank has been/will be constructed or closed according to NMOCD grade tank has been/will be constructed or closed according to NMOCD grade tank has been/will be constructed or closed according to NMOCD grade tank has been/will be constructed or closed according to NMOCD grade tank has been/will be constructed or closed according to NMOCD grade tank has been/will be constructed or closed according to NMOCD grade tank has been/will be constructed or closed according to NMOCD grade tank has been/will be constructed or closed according to NMOCD grade tank has been/will be constructed or closed according to NMOCD grade tank has been/will be constructed or closed according to NMOCD grade tank has been/will be constructed or closed according to NMOCD grade tank has been/will be constructed or closed according to NMOCD grade tank has been/will be constructed or closed according to NMOCD grade tank has been/	SUB REMEDIAL WORK COMMENCE DRILLI CASING TEST AND CEMENT JOB OTHER: all pertinent details, and give fultiple Completions: Attach se casing set @ 520'. 1, 14.8 ppg, 1.32 cuft/ si for 30 min. Test go set @ 3305'. ppg, 2.62 cuft/sx; 250 Test good. to the best of my knowledge midelines, a general permit	SEQUENT REPORT OF: ALTERING CASING NG OPNS. X PLUG AND ABANDONMENT Experiment dates, including estimated date wellbore diagram of proposed completion Sex. CIRC 51 sx to surface. Sex. CIRC 51 sx to surface. Sex. Class C, 14.8 ppg, 1.33 cuft/sx. Example and belief. I further certify that any pit or below— or an (attached) alternative OCD-approved plan
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON TEMPORARILY ABANDON CHANGE PLANS PULL OR ALTER CASING MULTIPLE COMPLETION OTHER: 13. Describe proposed or completed operations. (Clearly state of starting any proposed work). SEE RULE 1103. For Mor recompletion. 11/10/05 Spud well. Ran 12 jts 11 3/4, 42 #, H-40 surface Cemented w/ 345 sx Class C + 2 % Cac WCC 12 hrs. Tested casing to 1000 p 11/13/05 Ran 75 jts 8 5/8", 32 #, J-55 casing Cemented w/ 500 sx 50:50 POZ C, 11.9 CIRC 68 sx to surface. WCC 17 hrs. 11/14/05 tested casing to 2000 psi for 30 min I hereby certify that the jaformation above is true and complete	SUB REMEDIAL WORK COMMENCE DRILLI CASING TEST AND CEMENT JOB OTHER: all pertinent details, and give fultiple Completions: Attach se casing set @ 520'. 1, 14.8 ppg, 1.32 cuft/ si for 30 min. Test go set @ 3305'. ppg, 2.62 cuft/sx; 250 Test good. to the best of my knowledge midelines, a general permit	SEQUENT REPORT OF: ALTERING CASING NG OPNS. X PLUG AND ABANDONMENT Experiment dates, including estimated dates wellbore diagram of proposed completion Sex. CIRC 51 sx to surface. Sex. Class C, 14.8 ppg, 1.33 cuft/sx. Example and belief. I further certify that any pit or below— or an (attached) alternative OCD-approved plan

PETROLEUM ENGINEER

_____DATE_

For State Use Only

APPROVED BY Conditions of Approval, if any:

NOV 2 2 2005