
Office State of New Mexico	Form C-103
District I Energy, Minerals and Natural Resources	May 27, 2004
1625 N. French Dr., Hobbs, NM 88240 District II	WELL API NO. 30-025-05410
1301 W. Grand Ave., Artesia, NM 88210 OIL CONSERVATION DIVISION	5. Indicate Type of Lease
District III 1220 South St. Francis Dr. 1000 Rio Brazos Rd., Aztec, NM 87410	STATE ☐ FEE ☒
District IV Santa Fe, NIVI 8/303	6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM 87505	
SUNDRY NOTICES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH	
PROPOSALS.)	Lovington Paddock Unit (26749)
1. Type of Well: Oil Well Gas Well Other	8. Well Number 144
2. Name of Operator	9. OGRID Number
Pure Resources, L. P. (150628) 3. Address of Operator	150628 10. Pool name or Wildcat
500 W. Illinois Midland, Texas 79701	Lovington; Paddock (40660)
4. Well Location	
Unit Letter B: 330 feet from the North line and	2310 feet from the East line
Section 6 Township 17-S Range 37-E	NMPM County LEA
11. Elevation (Show whether DR, RKB, RT, GR, etc.	
3,820° DF	Designation of the second seco
Pit or Below-grade Tank Application or Closure NA, propose to use Steel Tanks w/BOP Spill Contain	ľ
Pit typeDepth to GroundwaterDistance from nearest fresh water wellDis	
Pit Liner Thickness: mil Below-Grade Tank: Volumebbls; C	
12. Check Appropriate Box to Indicate Nature of Notice,	Report or Other Data
NOTICE OF INTENTION TO: SUE	SEQUENT REPORT OF:
PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐ REMEDIAL WOR	<u> </u>
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐ COMMENCE DR	ILLING OPNS. P AND A
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐ CASING/CEMEN	IT JOB
OTHER: Propose to pull equipment TA & Test Wellhore	П
OTHER: Propose to pull equipment, TA & Test Wellbore. OTHER: OTHER: OTHER: OTHER:	nd give pertinent dates, including estimated date
OTHER: Propose to pull equipment, TA & Test Wellbore. OTHER: OTHER: OTHER: OTHER: OTHER: OTHER: OTHER: OTHER: OTHER: OTHER:	
13. Describe proposed or completed operations. (Clearly state all pertinent details, at	
13. Describe proposed or completed operations. (Clearly state all pertinent details, at of starting any proposed work). SEE RULE 1103. For Multiple Completions: A or recompletion.	ttach wellbore diagram of proposed completion
 Describe proposed or completed operations. (Clearly state all pertinent details, an of starting any proposed work). SEE RULE 1103. For Multiple Completions: A or recompletion. Pure Resources, L. P. respectfully requests approval to Temporarily Abandon this we 	ttach wellbore diagram of proposed completion
13. Describe proposed or completed operations. (Clearly state all pertinent details, at of starting any proposed work). SEE RULE 1103. For Multiple Completions: A or recompletion.	llbore, with work to begin-week of November
 13. Describe proposed or completed operations. (Clearly state all pertinent details, an of starting any proposed work). SEE RULE 1103. For Multiple Completions: A or recompletion. Pure Resources, L. P. respectfully requests approval to Temporarily Abandon this we 28, 2005, by the following proceedure: 1. POH w/tbg, and production equipment, as applicable. 	llbore, with work to begin-week of November
 Describe proposed or completed operations. (Clearly state all pertinent details, an of starting any proposed work). SEE RULE 1103. For Multiple Completions: A or recompletion. Pure Resources, L. P. respectfully requests approval to Temporarily Abandon this we 28, 2005, by the following proceedure: POH w/tbg, and production equipment, as applicable. RIH w/ CIBP and set @ ± 8,150°. 	llbore, with work to begin-week of November
 13. Describe proposed or completed operations. (Clearly state all pertinent details, an of starting any proposed work). SEE RULE 1103. For Multiple Completions: A or recompletion. Pure Resources, L. P. respectfully requests approval to Temporarily Abandon this we 28, 2005, by the following proceedure: 1. POH w/tbg, and production equipment, as applicable. 	llbore, with work to begin-week of November
 Describe proposed or completed operations. (Clearly state all pertinent details, an of starting any proposed work). SEE RULE 1103. For Multiple Completions: A or recompletion. Pure Resources, L. P. respectfully requests approval to Temporarily Abandon this we 28, 2005, by the following proceedure: POH w/tbg, and production equipment, as applicable. RIH w/ CIBP and set @ ± 8,150°. Test casing per NMOCD rules to demonstrate mechanical integrity of well. 	ttach wellbore diagram of proposed completion
 Describe proposed or completed operations. (Clearly state all pertinent details, an of starting any proposed work). SEE RULE 1103. For Multiple Completions: A or recompletion. Pure Resources, L. P. respectfully requests approval to Temporarily Abandon this we 28, 2005, by the following proceedure: POH w/tbg, and production equipment, as applicable. RIH w/ CIBP and set @ ± 8,150°. Test casing per NMOCD rules to demonstrate mechanical integrity of well. (Please see attached Wellbore Schematic) 	Ittach wellbore diagram of proposed completion ellbore, with work to begin-week of November
 Describe proposed or completed operations. (Clearly state all pertinent details, an of starting any proposed work). SEE RULE 1103. For Multiple Completions: A or recompletion. Pure Resources, L. P. respectfully requests approval to Temporarily Abandon this we 28, 2005, by the following proceedure: POH w/tbg, and production equipment, as applicable. RIH w/ CIBP and set @ ± 8,150°. Test casing per NMOCD rules to demonstrate mechanical integrity of well. 	Ittach wellbore diagram of proposed completion ellbore, with work to begin-week of November
 Describe proposed or completed operations. (Clearly state all pertinent details, an of starting any proposed work). SEE RULE 1103. For Multiple Completions: A or recompletion. Pure Resources, L. P. respectfully requests approval to Temporarily Abandon this we 28, 2005, by the following proceedure: POH w/tbg, and production equipment, as applicable. RIH w/ CIBP and set @ ± 8,150°. Test casing per NMOCD rules to demonstrate mechanical integrity of well. (Please see attached Wellbore Schematic) 	Ittach wellbore diagram of proposed completion ellbore, with work to begin-week of November
 Describe proposed or completed operations. (Clearly state all pertinent details, an of starting any proposed work). SEE RULE 1103. For Multiple Completions: A or recompletion. Pure Resources, L. P. respectfully requests approval to Temporarily Abandon this we 28, 2005, by the following proceedure: POH w/tbg, and production equipment, as applicable. RIH w/ CIBP and set @ ± 8,150°. Test casing per NMOCD rules to demonstrate mechanical integrity of well. (Please see attached Wellbore Schematic) 	Ittach wellbore diagram of proposed completion ellbore, with work to begin-week of November
 Describe proposed or completed operations. (Clearly state all pertinent details, an of starting any proposed work). SEE RULE 1103. For Multiple Completions: A or recompletion. Pure Resources, L. P. respectfully requests approval to Temporarily Abandon this we 28, 2005, by the following proceedure: POH w/tbg, and production equipment, as applicable. RIH w/ CIBP and set @ ± 8,150°. Test casing per NMOCD rules to demonstrate mechanical integrity of well. (Please see attached Wellbore Schematic) 	Ittach wellbore diagram of proposed completion ellbore, with work to begin-week of November
 Describe proposed or completed operations. (Clearly state all pertinent details, an of starting any proposed work). SEE RULE 1103. For Multiple Completions: A or recompletion. Pure Resources, L. P. respectfully requests approval to Temporarily Abandon this we 28, 2005, by the following proceedure: POH w/tbg, and production equipment, as applicable. RIH w/ CIBP and set @ ± 8,150°. Test casing per NMOCD rules to demonstrate mechanical integrity of well. (Please see attached Wellbore Schematic) 	Ittach wellbore diagram of proposed completion ellbore, with work to begin-week of November
 Describe proposed or completed operations. (Clearly state all pertinent details, an of starting any proposed work). SEE RULE 1103. For Multiple Completions: A or recompletion. Pure Resources, L. P. respectfully requests approval to Temporarily Abandon this we 28, 2005, by the following proceedure: POH w/tbg, and production equipment, as applicable. RIH w/ CIBP and set @ ± 8,150°. Test casing per NMOCD rules to demonstrate mechanical integrity of well. (Please see attached Wellbore Schematic) BOP equipment used will be 3K psi. Steel tanks and BOP spill containment will be understand the process of the process of the period of the pe	tilized, as necessary, in lieu of pit construction.
 Describe proposed or completed operations. (Clearly state all pertinent details, at of starting any proposed work). SEE RULE 1103. For Multiple Completions: A or recompletion. Pure Resources, L. P. respectfully requests approval to Temporarily Abandon this we 28, 2005, by the following proceedure: POH w/tbg, and production equipment, as applicable. RIH w/ CIBP and set @ ± 8,150'. Test casing per NMOCD rules to demonstrate mechanical integrity of well. (Please see attached Wellbore Schematic) BOP equipment used will be 3K psi. Steel tanks and BOP spill containment will be unlikely that the information above is true and complete to the best of my knowled. 	tilized, as necessary, in lieu of pit construction.
 Describe proposed or completed operations. (Clearly state all pertinent details, at of starting any proposed work). SEE RULE 1103. For Multiple Completions: A or recompletion. Pure Resources, L. P. respectfully requests approval to Temporarily Abandon this we 28, 2005, by the following proceedure: POH w/tbg, and production equipment, as applicable. RIH w/ CIBP and set @ ± 8,150'. Test casing per NMOCD rules to demonstrate mechanical integrity of well. (Please see attached Wellbore Schematic) BOP equipment used will be 3K psi. Steel tanks and BOP spill containment will be under the best of my knowled grade tank has been/will be constructed or closed according to NMOCD guidelines □, a general permit □ 	tilized, as necessary, in lieu of pit construction. ge and belief. I further certify that any pit or below- or an (attached) alternative OCD-approved plan
 Describe proposed or completed operations. (Clearly state all pertinent details, at of starting any proposed work). SEE RULE 1103. For Multiple Completions: A or recompletion. Pure Resources, L. P. respectfully requests approval to Temporarily Abandon this we 28, 2005, by the following proceedure: POH w/tbg, and production equipment, as applicable. RIH w/ CIBP and set @ ± 8,150'. Test casing per NMOCD rules to demonstrate mechanical integrity of well. (Please see attached Wellbore Schematic) BOP equipment used will be 3K psi. Steel tanks and BOP spill containment will be unlikely that the information above is true and complete to the best of my knowled. 	tilized, as necessary, in lieu of pit construction. ge and belief. I further certify that any pit or below- or an (attached) alternative OCD-approved plan
13. Describe proposed or completed operations. (Clearly state all pertinent details, at of starting any proposed work). SEE RULE 1103. For Multiple Completions: A or recompletion. Pure Resources, L. P. respectfully requests approval to Temporarily Abandon this we 28, 2005, by the following proceedure: 1. POH w/tbg, and production equipment, as applicable. 2. RIH w/ CIBP and set @ ± 8,150°. 3. Test casing per NMOCD rules to demonstrate mechanical integrity of well. (Please see attached Wellbore Schematic) BOP equipment used will be 3K psi. Steel tanks and BOP spill containment will be used tank has been/will be constructed or closed according to NMOCD guidelines □, a general permit □ SIGNATURE Claube. Bohling □, TITLE Regulatory Agent □	tilized, as necessary, in lieu of pit construction. ge and belief. I further certify that any pit or below- or an (attached) alternative OCD-approved plan
13. Describe proposed or completed operations. (Clearly state all pertinent details, at of starting any proposed work). SEE RULE 1103. For Multiple Completions: A or recompletion. Pure Resources, L. P. respectfully requests approval to Temporarily Abandon this we 28, 2005, by the following proceedure: 1. POH w/tbg, and production equipment, as applicable. 2. RIH w/ CIBP and set @ ± 8,150°. 3. Test casing per NMOCD rules to demonstrate mechanical integrity of well. (Please see attached Wellbore Schematic) BOP equipment used will be 3K psi. Steel tanks and BOP spill containment will be used tank has been/will be constructed or closed according to NMOCD guidelines □, a general permit □ SIGNATURE Claube Bohlma TITLE Regulatory Agent □	tilized, as necessary, in lieu of pit construction. ge and belief. I further certify that any pit or below- or an (attached) alternative OCD-approved plan DATE11/23/2005
13. Describe proposed or completed operations. (Clearly state all pertinent details, at of starting any proposed work). SEE RULE 1103. For Multiple Completions: A or recompletion. Pure Resources, L. P. respectfully requests approval to Temporarily Abandon this we 28, 2005, by the following proceedure: 1. POH w/tbg, and production equipment, as applicable. 2. RIH w/ CIBP and set @ ± 8,150°. 3. Test casing per NMOCD rules to demonstrate mechanical integrity of well. (Please see attached Wellbore Schematic) BOP equipment used will be 3K psi. Steel tanks and BOP spill containment will be used tank has been/will be constructed or closed according to NMOCD guidelines □, a general permit □ SIGNATURE	tilized, as necessary, in lieu of pit construction. ge and belief. I further certify that any pit or below- or an (attached) alternative OCD-approved plan DATE 11/23/2005 Telephone No.
13. Describe proposed or completed operations. (Clearly state all pertinent details, at of starting any proposed work). SEE RULE 1103. For Multiple Completions: A or recompletion. Pure Resources, L. P. respectfully requests approval to Temporarily Abandon this we 28, 2005, by the following proceedure: 1. POH w/tbg, and production equipment, as applicable. 2. RIH w/ CIBP and set @ ± 8,150'. 3. Test casing per NMOCD rules to demonstrate mechanical integrity of well. (Please see attached Wellbore Schematic) BOP equipment used will be 3K psi. Steel tanks and BOP spill containment will be used tank has been/will be constructed or closed according to NMOCD guidelines □, a general permit □ SIGNATURE Abando Bohling TITLE Regulatory Agent □ Type or print name E-mail address: E-mail address:	tilized, as necessary, in lieu of pit construction. ge and belief. I further certify that any pit or below- or an (attached) alternative OCD-approved plan DATE 11/23/2005 Telephone No.
13. Describe proposed or completed operations. (Clearly state all pertinent details, at of starting any proposed work). SEE RULE 1103. For Multiple Completions: A or recompletion. Pure Resources, L. P. respectfully requests approval to Temporarily Abandon this we 28, 2005, by the following proceedure: 1. POH w/tbg, and production equipment, as applicable. 2. RIH w/ CIBP and set @ ± 8,150°. 3. Test casing per NMOCD rules to demonstrate mechanical integrity of well. (Please see attached Wellbore Schematic) BOP equipment used will be 3K psi. Steel tanks and BOP spill containment will be used tank has been/will be constructed or closed according to NMOCD guidelines □, a general permit □ SIGNATURE	tilized, as necessary, in lieu of pit construction. ge and belief. I further certify that any pit or below- or an (attached) alternative OCD-approved plan DATE 11/23/2005 Telephone No.

LPU #144 API No. 30-025-05410



5-1/2" CSG - set @ 8435' CMT w/ 800 sks