

DISTRICT I

P.O. Box 1980, Hobbs, NM 88240

DISTRICT II

P.O. Box Drawer DD, Artesia, NM 88210

DISTRICT III

1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088

Santa Fe, New Mexico 87504-2088

WELL API NO.	30-025-06648
5. Indicate Type of Lease	STATE ☐ FEE ☒
6. State Oil / Gas Lease No.	
7. Lease Name or Unit Agreement Name	MITTIE WEATHERLY
8. Well No.	2
9. Pool Name or Wildcat	EUNICE SAN ANDRES, NORTH(GAS)
10. Elevation (Show whether DF, RKB, RT,GR, etc.)	

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMI (FORM C-101) FOR SUCH PROPOSALS.

1. Type of Well:	OIL WELL ☐ GAS WELL ☒ OTHER ☐
2. Name of Operator	CHEVRON USA INC
3. Address of Operator	15 SMITH RD, MIDLAND, TX 79705
4. Well Location	Unit Letter <u>F</u> : <u>1980</u> Feet From The <u>NORTH</u> Line and <u>990</u> Feet From The <u>WEST</u> Line Section <u>17</u> Township <u>21-S</u> Range <u>37-E</u> NMPM <u>LEA</u> COUNTY
10. Elevation (Show whether DF, RKB, RT,GR, etc.)	

11.

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPERATION ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☒
OTHER: ☒ ADD PERFS & ACID STIMULATE

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

10-31-05: MIRU PU. TIH W/40 JTS KILL STRING.
11-01-05: RU SAND LINE DRILL. KNOCK OUT CIBP W/SAND LINE DRILL. PUSH DN HOLE TO 5372. TIH W/GAUGE RING & TAG TIGHT SPOT @ 4050. TIH W/BIT & TIH TO 5383'.
11-02-05: RUN GR/CPNL/CCL LOG GR 5200-3000. RUN GR/CBL/CCL FR 5200-3000.
11-03-05: PERF 4906-10, 4892-96, 4864-68, 4810-14, 4754-58, 4604-08, 4496-4504, 4328-34, 4280-86, 4244-50, 4161-66, 4134-42, 4122-28, 4106-14, 4084-92.
11-04-05: TIH W/PPI TOOLS & MARK SETTINGS. PUH & SET & TEST TOOLS. NO BLEED.
11-07-05: ACIDIZE PERFS 3957-4910 W/3600 GALS 15% HCL. PUH & DUMP 20 BBLS ANN. SET PKR W/SN @ 3903.
11-08-05: SWAB.
11-09-05: MOVE TOOLS. ISOLATE 4906'-10'. SWAB. REL TOOLS. TIH W/RBP & PKR. ISOLATE 4892-96. RU SWAB.
11-10-05: MOVE TOOLS. ISOLATE 4864-68'. SWAB. MOVE TOOLS. ISOLATE 4810-14. SWAB. MOVE TOOLS. ISOLATE 4754-58. SWAB.
11-11-05: REL PKR. RET RBP. TIH W/RBP & PKR. SET RBP @ 4788. PUH. SET PKR @ 4726. SWAB. MOVE TOOLS. RBP @ 4635. PUH. SET PKR @ 4570. SWAB. MOVE TOOLS. SET RBP @ 4541. PUH. SET PKR @ 4476. SWAB.
11-14-05: MOVE TOOLS. SET PLUG @ 4382. PUH. SET PKR. MOVE TOOLS. ISOLATE 4280-86. MOVE TOOLS. RBP @ 4258. PKR @ 4223. MOVE TOOLS. RBP @ 4195. PKR @ 4155. MOVE TOOLS. ISOLATE 4134-42.
11-15-05: RBP @ 4150. PKR @ 3910. MOVE PKR TO 4100. PUH. SET PKR @ 3910.
11-16-05: SWAB. PUMP CHEM SQZ 50 BBLS 8.6 CONT. 110 GALS BAKER RE-4777 FOLLOWED BY 200 BW. REL PKR. TIH W/TBG.
11-17-05: TIH W/SUB, 121 JTS 2 7/8" PROD TBG. SUB @ 3903. RIG DOWN. FINAL REPORT

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Denise Pinkerton TITLE Regulatory Specialist DATE 11/23/2005
TYPE OR PRINT NAME Denise Pinkerton Telephone No. 432-687-7375

(This space for State Use)

APPROVED [Signature] TITLE PETROLEUM ENGINEER
CONDITIONS OF APPROVAL, IF ANY:

DATE

DEC 02 2005
Nichols 12-93 ver 1.0