Form 3160-5 (August 1999)

D В

POMICIOCATIA

ED 0135 R 30, 2000

UNITED STATES	1.11NH11LN11N1	FORM APROVE
DEPARTMENT OF THE INTERIOR	CONFIDENTIAL	OMB NO. 1004-0
BUREAU OF LAND MANAGEMENT		EXPIRES: NOVEMBER
SUNDRY NOTICES AND REPORTS ON WELLS	5.	Lease Serial No.

Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals				MNM100568	
abandoned well. Us	e Form 3160-3 (APD) for such i	proposals		6. If Indian, Allottee of	or Tribe Name
SUBMIT IN TRIPLICATE					
			7. Unit or CA Agreement Name and No.		
1a. Type of Well Oil Well Ga	as Well 🔲 Other				
		······		8 Well Name and No	0.
2. Name of Operator				Rattlesnake Federal Unit 1	
DEVON ENERGY PRODUCTION COMPANY, LP			9. API Well No.		
3. Address and Telephone No.				30	0-025-36928
20 North Broadway, Ste 1500, Oklahoma City, OK 73102 405-552-8198			10. Field and Pool, or Exploratory		
4. Location of Well (Report location clearly and in accordance with Federal requirements)*			l		
1100 FNL 1980 FEL		Wildcat 12. County or Parish 13. State			
		·	1 15. State		
NWNE Sec 26 T26S R34E				Lea	NM
CHECK A	APPROPRIATE BOX(s) TO INC			, OR OTHER DATA	
TYPE OS SUBMISSION		TYPE	OF ACTION		
☐ Notice of Intent	Acidize	☑ Deepen	Production	n (Start/Resume)	☐ Water Shut-Off
	Alter Casing	Fracture Treat	Reclamati	on .	☐ Well Integrity
Subsequent Report	Casing Repair	New Construction	Recomple	te	Other Completion
Final Abandonment Notice	Change Plans	Plug and Abandon	Temporar	ily Abandon	Report
13. Describe Proposed or Completed Operations (C	Convert to Injection	☐ Plug Back	Water Dis	posal	·
MIRU PU. RIH w/ log and pressured ca 15,570' w/ 3000 gals 20 % retarded acid and set. Tested cement retainer to 310 hole and set at 15,500'. Dump 10' of ce Fishing for guns. Had to mill on guns. 42 holes. RIH with treating packer on to casing to 500# - held ok. Acidize (15,3' packer and set at 13,031'. Circulate we	I w/ 40 ball sealers. Test BOP 10# - held good. Drilled out ret ement on top or retainer. RIH v Drilled out cement retainer. top of perfs. Circulate hole. S 11-15,570') with 3000 gallons o	to 6500# - held good. Potainer at 15,390', squeeze w/ guns, packer and tubic Clean and circulate entifications 1 pot with 300 of gallons 1 pf 15% HCl. Unset packer lead. Test casing to 3600	OOH wetubing peris (15,500 ng Perbrate e hole. Rijh w 5% HC acros	g and packer. RIH w 0-15,570]. RU wirelind d 15,311] 5,379'; 112 guns and perforate s perfs. Pull packer ntire hole. Frac with l. Put well on produce	/ cement retainer to 15,390' ne lubricated retainer in the 2 holes. POOH. Lost guns. d 15,500-15,570' again with up to 15,136' and set. Test 100,000# Sinterball. RIH w/
Signed This space for Federal or State Office us. Approved by Conditions of approval, if any:	Name Title	Norvella Adar Sr. Staff Engineering 1		Date Date	9/12/2005
Somming of approval, it any:					
ts jurisdiction.	erson knowingry and willully to make any	department of agency of the ormer	u States arry faise,	icinious or traudulent statem	erns or representations to any matter with
io pariodioti.					