Form 3160-5 (Jugust 1999)

## **UNITED STATES** DEPARTMENT OF THE INTERIOR

Hohts, NM 88240

FORM APPROVED OMB No. 1004-0135 Expires November 30, 2000

## **BUREAU OF LAND MANAGEMENT**

5. Lease Serial No.

SUNDRY NOTICES AND REPORTS ON WELLS  Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.				6. If Indian, Allottee or Tribe Name		
						SUBMIT IN TRIPLICATE - Other instructions on reverse side
I. Type of Well  ☑ Oil Well ☐ Gas Well ☐ Other					ame and No.	
2. Name of Operator Latigo Petroleum, Inc.				Wyatt B #1  9. API Well No.		
3a. Address				30-025-01372 10. Field and Pool, or Exploratory Area		
4 Location of Well (Footage Sec. T. R. M. or Survey Description)				Corbin Abo		
990' FSL & 330' FEL Sec 33 (P), T17S, R33E CONDITIONS OF APPROVAL				11. County or Parish, State Lea NM		
12. CHECK AP	PROPRIATE BOX(ES) T	O INDICATE NAT	URE OF NOTICE,	REPORT, O	R OTHER DATA	
TYPE OF SUBMISSION	TYPE OF ACTION					
<ul><li>☑ Notice of Intent</li><li>☐ Subsequent Report</li></ul>	☐ Acidize ☐ Alter Casing ☐ Casing Repair	<ul><li>☐ Deepen</li><li>☐ Fracture Treat</li><li>☐ New Construction</li></ul>	Production (St Reclamation Recomplete	art/ Resume)	☐ Water Shut-Off ☐ Well Integrity ☐ Other	
☐ Final Abandonment Notice	☐ Change Plans ☐ Convert to Injection	<ul><li>☒ Plug and Abando</li><li>☐ Plug Back</li></ul>	n ☐ Temporarily A ☐ Water Disposa			
following completion of the involved operations. If the operation results in a multing testing has been completed. Final Abandonment Notices shall be filed only after all determined that the site is ready for final inspection.)  Cap CIBP @ 8510' w/ 35' cmt.  Perf @ 7700', squeeze w/ 50 sx, leave 50' cement in casing. Cut & pull 4-1/2" csg @ 4163'.  RIH, spot 35 sx cmt plug @ 4213'.  Spot 35 sx cmt plug @ 359'.  Perf @ 225', pump 35 sx cmt plug.  Set 10 sx surface plug.  Cut off WH, install dry hole marker.						
	·			-7-2		
14. I hereby certify that the foregoi Name (Printed/Typed) Lisa Hunt	ng is true and correct	Title Reg	ulatory Analyst			
			Date 11/29/2005			
	THIS SPACE	FOR FEDERAL OF	STATE OFFICE US	SE		
Approved by			Title		Date	
Conditions of approval, if any, are certify that the applicant holds lega which would entitle the applicant t	al or equitable title to those righ		Office			

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.



MEMO: Latigo Petroleum Inc., 550 West Texas Suite 700, Midland Tx, 79701

From: Gary Gourley, PE, BLM Roswell Field Office, 1-(505)-627-0249

## Regarding the Plugging and Abandonment approval for the:

Wyatt B # 01. API# 30 -025 -01372 990 '/S & 330 '/E Sec 33-P, T 17 S, R 33 E Lea County, New Mexico

From our records it appears the last workover job left a top of fish or CIBP at 8640 ft. not the 8510 ft stated. The first thing the plugger needs to do is Tag bottom and verify. Note bottom then cap with 35 ft of cement. My enclosed diagram shows this as either plug 1-A or 1-B.

#02 Plug is attempt to Perf & Sqz at 7700 ft.

# 03 Plug needs to be a Perf & Sqz attempt for the 8 5/8 inch shoe plug. The intent to cut and pull the 4 ½ inch casing can then be done above the top of this shoe plug approximately 4125 ft (i.e. needs to be 75 ft above shoe at least to 4138 ft. This shoe plug shall be Tagged. Then No Stub Plug shall be necessary.

#04 13 3/8 inch surface shoe plug shall be minimum of 100 ft balanced over shoe approximately from 250 ' to 350 '. Must be Tagged.

#05 Minimum 50 foot surface plug.

See Enclosed Sketch of well bore.

