Submit 3 Copies To Appropriate District	State of New M			Form C-103
Office District I	Energy, Minerals and Nat	ural Resources		May 27, 2004
1625 N. French Dr., Hobbs, NM 87240			WELL API NO.	
District II	OIL CONSERVATION DIVISION		30-025-33823	
1301 W. Grand Ave., Artesia, NM 88210 District III	1220 South St. Francis Dr.		5. Indicate Type of Leas	
1000 Rio Brazos Rd., Aztec, NM 87410	Santa Fe, NM	87505	STATE 🗷	FEE 🗌
District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505			6. State Oil & Gas Lease	e No.
SUNDRY NOTICES AND REPORTS ON WELLS  [(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A			7. Lease Name or Unit A	Agreement Name:
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)			Mule Deer 36 State	
1. Type of Well:			8. Well Number	
Oil Well 🗶 Gas Well 🗌	Other		8	
2. Name of Operator			9. OGRID Number	
EOG Resources Inc.		<del></del> ,	7377	
3. Address of Operator			10. Pool name or Wilder	
P.O. Box 2267 Midland, Tex	<u>as 79702</u>		Red Tank; Bone Sprin	ng
4. Well Location				
Unit Letter::	1650 feet from the S	outh line and	770 feet from the	<u>East</u> line
Section 36		Range 32E		ounty <b>Lea</b>
	11. Elevation (Show whethe	er DR, RKB, RT,  GR, et 3737 <b>G</b> R	c.)	
Pit or Below-grade Tank Application	*		(69.3	
Pit type Depth to Groundwater .	Distance from nearest fr	esh water well Di	stance from nearest surface was	ter
Pit Liner Thickness: mil	Below-Grade Tank: Volum	nebbls; Constructi	on Material $\frac{\sqrt{S}}{2}$	5 5
		•	3 2 4 5	
12. Check A	appropriate Box to Indica		Report, or Other Dat SEQUENT REPOR	a j
PERFORM REMEDIAL WORK	PLUG AND ABANDON 🗶	REMEDIAL WORK	☐ SQAL	TERING CASING
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DRILL		UG AND BANDONMENT
PULL OR ALTER CASING	MULTIPLE COMPLETION	CASING TEST AND CEMENT JOB		ANDOMNENT
OTHER:		OTHER:		
13. Describe proposed or completed of starting any proposed work). or recompletion.	-	_		=
Proposed P&A procedure:		TUE AII	CONSERVATION D	TOURS IRRUST
1. Set CIBP @ +/- 8835'	+ 35' cement can			
2. Cut and pull 4 1/2" of	<del>-</del>	BE NOT	TIFIED 24 HOURS P	'RICR TO THE
-	ug +/- from 6695'-6895'	Tag BEGINNS	NG OF PLUGGING	OPERATIONS.
4. Spot 100' (25 sx) plu	ug from 4654'- 4754'	Tag	<u>.</u>	
, 5. Spot 100' (25 sx) plu	ng from 1173'-1273' face plug from 50'-0'	Tag	-11.1-1/2	OF THE PARTIES DI
6. Spot 50' (12 sx) sur	face plug from 50'-0'	SPOT 100 PLUG	, F/400-300 (FK	RESH WATER TO
7. Weld on P&A marker, o	clean & restore location			
I hereby certify that the information al grade tank has been/will sonstructed or o	bove is true and complete to the	ne best of my knowledg	e and belief. I further certify	that any pit or below-
7/1				
SIGNATURE	1	E-mail address:	pry Analyst DAT	E
Type or print name Stan Wagner			Telephone	No. 432 686 3689 DEC 1 3 2005
For State Use Only	111, 15%			DEC TO TOO?
APPROVED BY Conditions of Approval, if any:	- CONCE	JE FELD REPRESENT	ATIVE II/STAFF MANAG	The second of th
Conditions of Approval, Il any				AT CALL

## MULE DEER STATE "36" NO. 8 LEA CO., NEW MEXICO APRIL 10, 2003

## WELLBORE SCHEMATIC

