

Submit 3 Copies To Appropriate District
Office
District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 South First, Artesia, NM 87210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources
OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-103
Revised March 25, 1999

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: Oil Well ☒ Gas Well ☐ Other ☐	5. Indicate Type of Lease STATE ☒ FEE ☐
2. Name of Operator <i>M.E.W. Enterprise</i>	6. State Oil & Gas Lease No. <i>23920</i>
3. Address of Operator <i>P.O. Box 39 Roswell, N.M. 8820</i>	7. Lease Name or Unit Agreement Name: <i>Sun State</i>
4. Well Location Unit Letter <i>M</i> : <i>660</i> feet from the <i>S</i> line and <i>660</i> feet from the <i>W</i> line Section <i>36</i> Township <i>7S</i> Range <i>30E</i> NMPM County <i>CHAURS</i>	8. Well No. <i>1</i>
9. Pool name or Wildcat <i>Cato San Andres</i>	
10. Elevation (Show whether DR, RKB, RT, GR, etc.)	

11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒	REMEDIAL WORK ☐ ALTERING CASING ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐	COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐	CASING TEST AND CEMENT JOB ☐
OTHER: ☐	OTHER: ☐

12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation. *July of 2001, Rig up on well, set CIBP at 3425' dump Bail 20' cmt on Plug. Displace hole w/ mud. Rig up and Perf 2 shot at 1350' pump cmt, SI overnight. RTH Tag Plug 1170'. Pullout of hole & SI.*
Need to: Perforate at 422' pump cmt plug 50' below and above surface casing shoe at 372'. Displace hole w/ mud, pump 60' surface plug, cap & set Dry hole make.

If approved it will have Job completed no Later Than July 30, 2006

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE *Russell Whitel* TITLE *Pres* DATE *12-13-05*

Type or print name *Russell Whitel* Telephone No. *627-2065*
(This space for State use)

APPROVED BY *Larry W. Wink* DATE *DEC 28 2005*
Conditions of approval, if any:

THE OIL CONSERVATION DIVISION MUST
BE NOTIFIED 24 HOURS PRIOR TO THE
BEGINNING OF PLUGGING OPERATIONS.