ر يا منظم المعلول في المنظم المعلول في المنظم المعلول في المنظم المنظم المنظم المنظم المنظم المنظم المنظم المن				
Submit 3 Copies To Appropriate District State of New Mexico	Form C-103			
Office Energy, Minerals and Natural Resources	May 27, 2004			
1625 N. French Dr., Hobbs, NM 87240	WELL API NO. 30-025-34073			
1301 W Grand Ave Artesia NM 88210 OIL COINSERVA HOUNDAVISION	5. Indicate Type of Lease			
1000 Rio Brazos Rd., Aztec, NM 87410 Santa Fe, NM 87505	STATE FEE X			
District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505	6. State Oil & Gas Lease No. 21108			
SUNDRY NOTICES AND REPORTS ON WELLS (100 NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH	7. Lease Name or Unit Agreement Name: Snyder A Com			
PROPOSALS.) 1. Type of Well:	8. Well Number			
Oil Well X Gas Well Other	1			
2. Name of Operator Energen Resources Corporation	9. OGRID Number 162928			
3. Address of Operator	10. Pool name or Wildcat			
3300 North A St., Building 4, Suite 100 Midland, TX 79705	Shoe Bar; Strawn, Northeast			
4. Well Location				
Unit Letter U: 990 feet from the South line and	874 feet from the West line			
Section 6 Township 16-S Range 36-E				
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3956' GR, 3976' KB				
Pit or Below-grade Tank Application or Closure				
Pit type Depth to Groundwater Distance from nearest fresh water well Dis	stance from nearest surface water			
Pit Liner Thickness: mil Below-Grade Tank: Volumebbls; Construction	on Material			
12. Check Appropriate Box to Indicate Nature of Notice, NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLI PULL OR ALTER CASING MULTIPLE CASING TEST AND CEMENT JOB	SEQUENT REPORT OF: ALTERING CASING			
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLI PULL OR ALTER CASING MULTIPLE CASING TEST AND	SEQUENT REPORT OF: ALTERING CASING ING OPNS. PLUG AND			
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLI PULL OR ALTER CASING MULTIPLE CASING TEST AND CEMENT JOB	SEQUENT REPORT OF: ALTERING CASING ING OPNS. PLUG AND ABANDONMENT PROBLEM OF THE PROBLEM OF			
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON COMMENCE DRILLI PULL OR ALTER CASING MULTIPLE CASING TEST AND CEMENT JOB OTHER: OTHER: OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, and give of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach	ALTERING CASING ABANDONMENT PLUG AND ABANDONMENT Repertment dates, including estimated date a wellbore diagram of proposed completion Pad NU a BOP, picked up and SLMIH Par'. 12/7/05 - Set packer @ 8477', P. RU wireline truck, RIH to 50' Wireline. RIH w/stinger and 2-3/8" Pumped 150 sx "C" plug, P00H to inger. 12/10/05 - RIH w/5-1/2" AD in plug down to 4762'. 12/13/05 -			
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLI PULL OR ALTER CASING MULTIPLE COMPLETION CASING TEST AND CEMENT JOB OTHER: OTHER: OTHER: OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, and giv of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attack or recompletion. 12/6/05 - Notified NMOCD of intent to start P&A. MIRU PU. ND wellhe w/2-3/8" x 5-1/2" Baker AD-1 packer & 258 jts of 2-/38" tubing to 847 pumped 25 bbls 10# brine down tubing, loaded tubing. POOH w/tbg & pkr from surface. 12/8/05 - RIH w/wireline and set @ 8477'. POOH & RD v tbg, pumped 66 bbls 10# MLF, stung into retainer, established rate. 3630', spotted a 25 sx plug @5630' up to 5378'. POOH w/all tbg. & stipacker & 2-3/8" tubing to 4600'. Mixed & pumped 150 sx "C", displaced Unset packer, tagged top of plug @ 4760'. RIH w/wireline and perforat I hereby certify that the information above is true and complete to the best of my knowledge.	ALTERING CASING ING OPNS. PLUG AND ABANDONMENT Pe pertinent dates, including estimated date a wellbore diagram of proposed completion Padd NU a BOP, picked up and SLMIH Pr'. 12/7/05 - Set packer @ 8477', C. RU wireline truck, RIH to 50' Wireline. RIH w/stinger and 2-3/8" Pumped 150 sx "C" plug, P00H to inger. 12/10/05 - RIH w/5-1/2" AD di plug down to 4762'. 12/13/05 - ted 5-1/2" csg @1950'. RIH w/pkr e and belief. I further certify that any pit or below-			
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLI PULL OR ALTER CASING MULTIPLE CASING TEST AND CEMENT JOB OTHER: OTHER: OTHER: OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, and giv of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attack or recompletion. 12/6/05 - Notified NMOCD of intent to start P&A. MIRU PU. ND wellhe w/2-3/8" x 5-1/2" Baker AD-1 packer & 258 jts of 2-/38" tubing to 847 pumped 25 bbls 10# brine down tubing, loaded tubing. POOH w/tbg & pkr from surface. 12/8/05 - RIH w/wireline and set @ 8477'. POOH & RD w tbg, pumped 66 bbls 10# MLF, stung into retainer, established rate. 3630', spotted a 25 sx plug @5630' up to 5378'. POOH w/all tbg. & stipacker & 2-3/8" tubing to 4600'. Mixed & pumped 150 sx "C", displaced Unset packer, tagged top of plug @ 4760'. RIH w/wireline and perforations.	ALTERING CASING ABANDONMENT PLUG AND ABANDONMENT PLUG AND ABANDONMENT Re pertinent dates, including estimated date a wellbore diagram of proposed completion Pad NU a BOP, picked up and SLMIH PAT'. 12/7/05 - Set packer @ 8477', P. RU wireline truck, RIH to 50' Wireline. RIH w/stinger and 2-3/8" Pumped 150 sx "C" plug, P00H to inger. 12/10/05 - RIH w/5-1/2" AD inger. 12/10/05 - RIH w/5-1/2" AD inger. 12/10/05 - RIH w/5-1/2" AD inger. 12/10/05 - RIH w/pkr Re and belief. I further certify that any pit or below— or an (attached) alternative OCD-approved plan			
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLI PULL OR ALTER CASING MULTIPLE COMPLETION CEMENT JOB OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, and giv of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attack or recompletion. 12/6/05 - Notified NMOCD of intent to start P&A. MIRU PU. ND wellhe w/2-3/8" x 5-1/2" Baker AD-1 packer & 258 jts of 2-/38" tubing to 847 pumped 25 bbls 10# brine down tubing, loaded tubing. POOH w/tbg & pkr from surface. 12/8/05 - RIH w/wireline and set @ 8477'. POOH & RD w tbg, pumped 66 bbls 10# MLF, stung into retainer, established rate. 3630', spotted a 25 sx plug @5630' up to 5378'. POOH w/all tbg. & str packer & 2-3/8" tubing to 4600'. Mixed & pumped 150 sx "C", displaced Unset packer, tagged top of plug @ 4760'. RIH w/wireline and perforat I hereby certify that the information above is true and complete to the best of my knowledg grade tank has been will be constructed or closed according to NMOCD guidelines X, a general permit SIGNATURE TITLE Regulato E-mail address: Type or print name Carolyn Larson.	SEQUENT REPORT OF: ALTERING CASING ING OPNS. PLUG AND ABANDONMENT Report in the proposed completion and NU a BOP, picked up and SLMIH Proposed completion and NU a BOP, picked up and SLMIH Proposed completion and NU a BOP, picked up and SLMIH Proposed completion and NU a BOP, picked up and SLMIH Proposed completion and NU a BOP, picked up and SLMIH Proposed completion and NU a BOP, picked up and SLMIH Proposed completion and NU a BOP, picked up and SLMIH Proposed completion and NU a BOP, picked up and SLMIH Proposed completion and NU a BOP, picked up and SLMIH Proposed completion and NU a BOP, picked up and SLMIH Proposed completion and NU a BOP, picked up and SLMIH Proposed completion and NU a BOP, picked up and SLMIH Proposed completion Alamanda Calling Alamanda			
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLI PULL OR ALTER CASING MULTIPLE COMPLETION CEMENT JOB OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, and giv of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attack or recompletion. 12/6/05 - Notified NMOCD of intent to start P&A. MIRU PU. ND wellhe w/2-3/8" x 5-1/2" Baker AD-1 packer & 258 jts of 2-/38" tubing to 847 pumped 25 bbls 10# brine down tubing, loaded tubing. POOH w/tbg & pkr from surface. 12/8/05 - RIH w/wireline and set @ 8477'. POOH & RD w tbg, pumped 66 bbls 10# MLF, stung into retainer, established rate. 3630', spotted a 25 sx plug @5630' up to 5378'. POOH w/all tbg. & str packer & 2-3/8" tubing to 4600'. Mixed & pumped 150 sx "C", displaced Unset packer, tagged top of plug @ 4760'. RIH w/wireline and perforat I hereby certify that the information above is true and complete to the best of my knowledg grade tank has been will be constructed or closed according to NMOCD guidelines X, a general permit SIGNATURE TITLE Regulato E-mail address: Type or print name Carolyn Larson.	SEQUENT REPORT OF: ALTERING CASING ING OPNS. PLUG AND ABANDONMENT Report in the proposed completion and NU a BOP, picked up and SLMIH Proposed completion and NU a BOP, picked up and SLMIH Proposed completion and NU a BOP, picked up and SLMIH Proposed completion and NU a BOP, picked up and SLMIH Proposed completion and NU a BOP, picked up and SLMIH Proposed completion and NU a BOP, picked up and SLMIH Proposed completion and NU a BOP, picked up and SLMIH Proposed completion and NU a BOP, picked up and SLMIH Proposed completion and NU a BOP, picked up and SLMIH Proposed completion and NU a BOP, picked up and SLMIH Proposed completion and NU a BOP, picked up and SLMIH Proposed completion and NU a BOP, picked up and SLMIH Proposed completion Alamanda Calling Alamanda			
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLI PULL OR ALTER CASING MULTIPLE CASING TEST AND CEMENT JOB OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, and giv of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attack or recompletion. 12/6/05 · Notified NMOCD of intent to start P&A. MIRU PU. ND wellhe w/2-3/8" x 5-1/2" Baker AD-1 packer & 258 jts of 2-/38" tubing to 847 pumped 25 bbls 10# brine down tubing, loaded tubing. POOH w/tbg & pkr from surface. 12/8/05 - RIH w/wireline and set @ 8477'. POOH & RD w tbg, pumped 66 bbls 10# MLF, stung into retainer, established rate. 3630', spotted a 25 sx plug @5630' up to 5378'. POOH w/all tbg. & str packer & 2-3/8" tubing to 4600'. Mixed & pumped 150 sx "C", displaced Unset packer, tagged top of plug @ 4760'. RIH w/wireline and perforat I hereby certify that the information above is true and complete to the best of my knowledge grade tank has been will be constructed or closed according to NMOCD guidelines X , a general permit SIGNATURE TITLE Regulato E-mail address: Type or print name Carolyn Larson.	SEQUENT REPORT OF: ALTERING CASING ING OPNS. PLUG AND ABANDONMENT Report in the proposed completion and NU a BOP, picked up and SLMIH Proposed completion and NU a BOP, picked up and SLMIH Proposed completion and NU a BOP, picked up and SLMIH Proposed completion and NU a BOP, picked up and SLMIH Proposed completion and NU a BOP, picked up and SLMIH Proposed completion and NU a BOP, picked up and SLMIH Proposed completion and NU a BOP, picked up and SLMIH Proposed completion and NU a BOP, picked up and SLMIH Proposed completion and NU a BOP, picked up and SLMIH Proposed completion and NU a BOP, picked up and SLMIH Proposed completion and NU a BOP, picked up and SLMIH Proposed completion and NU a BOP, picked up and SLMIH Proposed completion Alamanda Calling Alamanda			

Submit 3 Copies To Appropriate District Office	State of New Energy, Minerals and N			Form C-103 May 27, 2004	
District 1 1625 N. French Dr., Hobbs, NM 87240	30212	2232421	WELL API NO.	Iviay 21, 2004	
District II 1301 W. Grand Ave., Artesia, NM 88210	OIL CONSERVAT	ÎON DIVÎSÎON	30-025-34		
District III	1220 South St.	Francis Dr. 🛴 \	5. Indicate Type of I		
1000 Rio Brazos Rd., Aztec, NM 87410 District IV	Santa Fe, INI	1/8/505 B	STATE	FEE X	
1220 S. St. Francis Dr., Santa Fe, NM 87505	E Rec	teived 6	6. State Oil & Gas L 21108	ease No.	
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		7. Lease Name or Unit Agreement Name: Snyder A Com			
1. Type of Well: Oil Well X Gas Well Other		8. Well Number			
2. Name of Operator		9. OGRID Number			
Energen Resources Corporation		162928			
3. Address of Operator		10. Pool name or Wildcat			
3300 North A St., Building 4, Suite 100 Midland, TX 79705 Shoe Bar; Strawn, Northeast 4. Well Location				<u>in. Northeast</u>	
Unit LetterU:	990 feet from the	South line and	874 feet from	the West line	
Section 6	Township 16-S	Range 36-E	NMPM	County Lea	
	11. Elevation (Show wheth 3956)	her DR, RKB, RT, GR, et GR, 3976' KB	c.)		
Pit or Below-grade Tank Application	or Closure 🗆				
Pit type Depth to Groundwater _	Distance from nearest	fresh water well Dis	stance from nearest surface	water	
Pit Liner Thickness: mil	Below-Grade Tank: Volu	mebbls; Construction	on Material		
12. Check A NOTICE OF INTE	ppropriate Box to Indic ENTION TO: PLUG AND ABANDON [SEQUENT REPO		
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DRILLI	ING OPNS.	PLUG AND	
PULL OR ALTER CASING	MULTIPLE COMPLETION	CASING TEST AND CEMENT JOB		ABANDONMENT	
OTHER:		OTHER:			
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.					
12/13/05 (cont) to 1708', squeezed 35 sx plug. Disp to 1850'. POOH w/packer, RIH w/wireline, perf @ 448', POOH w/wireline. RIH w/packer, set @262', squeezed a 40sx plug w/2% CACL, displaced to 348', WOC, tagged TOC @327'. POOH, RIH & perf @ 70', POOH, ND BOP, NU wellhead, pumped 20 sx plug down 5-1/2" casing, circulated cement out 8-5/8" annulus. SI the well, will cut off wellhead, anchors and install DHM at a later date. Well is plugged and abandoned. Approved as to plugging of the Well Bore.					
Liability under bond is retained until surface restoration is completed.					
I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been will be constructed or closed afterding to NMOCD guidelines X, a general permit or an (attached) alternative OCD-approved plan					
SIGNATURE ORDINA		TITLE Regulator			
Type or print name Carolyn Larson	•	E-mail address:	clarson@energen.c		
APPROVED BY YOU'LL DOOR FIELD REPRESENTATIVE II/STAFF MANAGER Conditions of Approved if any DATE Conditions of Approved if any DATE					
APPROVED BY Lary W	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	TITLECENTATIVE	II/STAFF MA	TE	
Conditions of Approval, if anx:	OC	FIELD REPRESENTATIVE	D7	DEO	
-	-			DEC 28 2005	