Submit 3 Copies To Appropriate District Office	State of New Mexico		Form C-103 March 4, 2004
District I 1625 N. French Dr., Hobbs, NM 88240	Energy, Minerals and Natural Resources		VELL API NO.
District II 1301 W. Grand Ave., Artesia, NM 88210	OIL CONSERVATION DIVISION		30-025-237 7 Indicate Type of Lease
District III 1220 South St. Francis Dr.		cis Dr.	STATE FEE
1000 Rio Brazos Rd., Aztec, NM 87410 <u>District IV</u> Santa Fe, NM 87505		505	. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM 87505			<i>i</i> .
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A			. Lease Name or Unit Agreement Name
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH			Kingwood
PROPOSALS.) 1. Type of Well:			. Well Number
Oil Well Gas Well Other			1
2. Name of Operator		9	. OGRID Number
Chevron USA	A Inc	1	0. Pool name or Wildcat
3. Address of Operator 15 Smith Rd, Midland, TX 79705			Paddock
4. Well Location	,		
***************************************	1780feet from theSouth	1: 4	650 feet from the East line
Unit Letter :	reet from the	line and 1	leet from theinie
Section 25			MPM Lea County
11. Elevation (Show whether DR, RKB, RT, GR, etc.)			
Pit or Below-grade Tank Application (For	pit or below-grade tank closures, a form	C-144 must be attached)	
Pit Location: UL J Sect 25 Twp 21	S Rng 36E Pit type Steel De	epth to Groundwater 14	8 Distance from nearest fresh water well Over 1000
Distance from nearest surface water			Rng;
1780 feet from the South line and 10	650 feet from the East line (S	iteel Tank)	5 4 5 3
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data			
NOTICE OF INT			EQUENT REPORT OF
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK	☐ ALTÈRING CASING ☐
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DRILL	ING OPNS.□ PLUG AND ☑ ABANDONMENT
PULL OR ALTER CASING	MULTIPLE	CASING TEST AND	
	COMPLETION	CEMENT JOB	
OTHER:		OTHER:	
13. Describe proposed or compl	eted operations. (Clearly state all p	pertinent details, and g	ive pertinent dates, including estimated date
	rk). SEE RULE 1103. For Multip	le Completions: Attac	th wellbore diagram of proposed completion
or recompletion. 1. Notify OCD 24 hrs prior to MI and RU		8. Perf 8 5/8 @ 375 sqz	z 75sx plug 375-250 (12 3/4 Shoe) WOC Tag @ 300
 RIH Tag CIBP @5100, , spot 25sx, plug 5100-4900(Paddock)WOC Tag 4895. Displace hole w/MLF, 9.5# Brine w/25# gel P/BBL. Spot 40sx 150 - Surf WOC Tag @ Surf. Spot 40sx 150 - Surf WOC Tag @ Surf. 			
4. Perf 4 holes @ 4100 Unable to EPIR 11. Install Dryhole Marker 5-5-05 Spot 25sx 4150-3900 (S.Andres) WOC Tag @ 3906.			
6. Spot 90sx plug 2850-2600 (8 5/8 Sho	e Stub) WOC Tag 2590.		
7. Perf 8 5/8 @ 1250, sqz 90sx plug 125			
I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been/will be constructed or closed according to NMOCD guidelines , a general permit or an (attached) alternative OCD-approved plan.			
grade tank has been win be constituted of	7/		
SIGNATURE /	TITLE	Consultant	DATE_ 5-5-05
Type or print name Jimmy Bagi	ey E-mail ac	idress:	Telephone No. 432-561-8600
(This space for State use)			
APPPROVED BY LOUIS WANK OF HELB REPRESENTATIVE ITSTATIVE TO 9 2008			
Conditions of approval, if any:			
1/			

Approved as to plugging of the Well Bore. Liability under bond is retained until surface restoration is completed.