Form 3160-5 (April 2004)

UNITED STATES OCCUPIOBBS DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

	FORM APPROVED OM B No. 1004-0137 Expires: March 31, 2007
-	

	Expires: March 31, 2007
5.	Lease Serial No.
	CC032592A
6.	If Indian, Allottee or Tribe Name
	N/A
7.	If Unit or CA/Agreement, Name and/or No.

SUNDRY NOTICES AND REPO	RTS ON WELLS	CC032592A
Do not use this form for proposals to a sbandoned well. Use Form 3160-3 (AP		If Indian, Allottee or Tribe Name N/A
SUBMIT IN TRIPLICATE- Other instruc	ctions on reverse side.	7. If Unit or CA/Agreement, Name and/or No.
Type of Well Gas Well Other		N/A
	8. Well Name and No. Trantula 3 Federal #1 (35881)	
Name of Operator Range Operating New Mexico, Inc. (227)	9. API Well No.	
Address 777 Main Street Suite 800 Fort Worth, TX 76102	b. Phone No. (include area code) 817-810-1908	30-025-33928 3 7 45 7 10. Field and Pool, or Exploratory Area
Location of Well (Footage, Sec., T., R., M., or Survey Description)		Justis, Tubb-Drinkard (35280)
At Surface: 990' FNL & 330' FEL Sec. 3, T25S, R37E At Proposed Prod. Zone: 990' FNL & 330' FEL Sec. 3, T25S	s, R37E	11. County or Parish, State Lea, NM
12. CHECK APPROPRIATE BOX(ES) TO IN	IDICATE NATURE OF NOTICE,	REPORT, OR OTHER DATA
TYPE OF SUBMISSION	TYPE OF ACTION	
Acidize	Deepen Production ((Start/Resume) Water Shut-Off
Notice of Intent Alter Casing	Fracture Treat Reclamation	Well Integrity
Subsequent Report Casing Repair	New Construction Recomplete	Other
Final Abandonment Notice Convert to Injection	Plug and Abandon Temporarily Plug Back Water Dispos	
If the proposal is to deepen directionally or recomplete horizontally, g Attach the Bond under which the work will be performed or provide t following completion of the involved operations. If the operation rest testing has been completed. Final Abandonment Notices shall be file determined that the site is ready for final inspection.) TD 6606 © 1:30 AM MDT 120606	the Bond No. on file with BLM/BIA. Requits in a multiple completion or recompletion	uired subsequent reports shall be filed within 30 days on in a new interval, a Form 3160-4 shall be filed once
Attach the Bond under which the work will be performed or provide following completion of the involved operations. If the operation resistesting has been completed. Final Abandonment Notices shall be file	the Bond No. on file with BLM/BIA. Requits in a multiple completion or recompletion of only after all requirements, including recompletion of the state of the st	uired subsequent reports shall be filed within 30 days on in a new interval, a Form 3160-4 shall be filed once lamation, have been completed, and the operator has CUSED LOG / GAMA RAY COMBO. CREW. RUN 156 JTS 5.5, 17 # M80
Attach the Bond under which the work will be performed or provide following completion of the involved operations. If the operation rest testing has been completed. Final Abandonment Notices shall be file determined that the site is ready for final inspection.) TD 6606 @ 1:30 AM MDT 12/05/05 TOOH F/LOGS. RU/LOG WELL. RUN DUEL LATERGRD. T I H FOR LAY DOWN. TOOH LAYING DOWN CASING TO 6606'. CIRC CSG. CMT 5.5 CASING 1st S	the Bond No. on file with BLM/BIA. Requits in a multiple completion or recompleted only after all requirements, including recompleted only after all requirements. The complete only after a supplied on the complete on the com	cured subsequent reports shall be filed within 30 days on in a new interval, a Form 3160-4 shall be filed once lamation, have been completed, and the operator has cused LOG / GAMA RAY COMBO. CREW. RUN 156 JTS 5.5, 17 # M80 20167 + 4 pps D42 + 0.1 % D 13 st STAGE.
Attach the Bond under which the work will be performed or provide following completion of the involved operations. If the operation rest testing has been completed. Final Abandonment Notices shall be file determined that the site is ready for final inspection.) TD 6606 @ 1:30 AM MDT 12/05/05 TOOH F/ LOGS. RU/LOG WELL. RUN DUEL LATERGRD. TIH FOR LAY DOWN. TOOH LAYING DOWN. CASING TO 6606'. CIRC CSG. CMT 5.5 CASING 1st States 1st STAGE 600 SKS 50:50 POZ:CLASS C+2% D20+5% D	the Bond No. on file with BLM/BIA. Requits in a multiple completion or recompleted only after all requirements, including recompleted only after all requirements. The complete only after a supplied on the complete on the com	uired subsequent reports shall be filed within 30 days on in a new interval, a Form 3160-4 shall be filed once lamation, have been completed, and the operator has CUSED LOG / GAMA RAY COMBO. CREW. RUN 156 JTS 5.5, 17 # M80 2167 + 4 pps D42 + 0.1 % D 13
Attach the Bond under which the work will be performed or provide following completion of the involved operations. If the operation rest testing has been completed. Final Abandonment Notices shall be file determined that the site is ready for final inspection.) TD 6606 @ 1:30 AM MDT 12/05/05 TOOH F/ LOGS. RU/LOG WELL. RUN DUEL LATERGED. T I H FOR LAY DOWN. TOOH LAYING DOWN. CASING TO 6606'. CIRC CSG. CMT 5.5 CASING 1st STAGE 600 SKS 50:50 POZ:CLASS C+2% D20+5% D 1st STAGE PLUG DN @ 12:14 PM MDT, 1/07/05 BUMF	the Bond No. on file with BLM/BIA. Requits in a multiple completion or recompletion donly after all requirements, including reclaim of the completion of the	cused subsequent reports shall be filed within 30 days on in a new interval, a Form 3160-4 shall be filed once lamation, have been completed, and the operator has cused LOG/GAMA RAY COMBO. CREW. RUN 156 JTS 5.5,17 # M80 P167 + 4 pps D42 + 0.1 % D 13 at STAGE. ACCEPTED FOR RECO
Attach the Bond under which the work will be performed or provide following completion of the involved operations. If the operation rest testing has been completed. Final Abandonment Notices shall be file determined that the site is ready for final inspection.) TD 6606 @ 1:30 AM MDT 12/05/05 TOOH F/ LOGS. RU/LOG WELL. RUN DUEL LATERGED. T I H FOR LAY DOWN. TOOH LAYING DOWN. CASING TO 6606'. CIRC CSG. CMT 5.5 CASING 1st S 1st STAGE 600 SKS 50:50 POZ:CLASS C+2% D20+5% D 1st STAGE PLUG DN @ 12:14 PM MDT, 1/07/05 BUMF CMT 5.5 CASING 2 nd STAG 2nd STAGE 350 SKS 50:50 POZ:C = 10% D20 + 5 % (BW 2 nd STAGE PLUG DN @ 6:00 PM MDT 12/07/05 BUMP NIPPLE DOWN / SET SLIPS / CUT OFF 5.5 CASING. J RIG DOWN RIG RELEASED @ 12:01 AM MDT 12/08.	the Bond No. on file with BLM/BIA. Requits in a multiple completion or recompletion donly after all requirements, including reclaim of the completion of the	cused subsequent reports shall be filed within 30 days on in a new interval, a Form 3160-4 shall be filed once lamation, have been completed, and the operator has cused LOG/GAMA RAY COMBO. CREW. RUN 156 JTS 5.5,17 # M80 P167 + 4 pps D42 + 0.1 % D 13 pt STAGE. ACCEPTED FOR RECCEPTED FOR RECCE
Attach the Bond under which the work will be performed or provide following completion of the involved operations. If the operation rest testing has been completed. Final Abandonment Notices shall be file determined that the site is ready for final inspection.) TD 6606 @ 1:30 AM MDT 12/05/05 TOOH F/ LOGS. RU/LOG WELL. RUN DUEL LATERGED. T I H FOR LAY DOWN. TOOH LAYING DOWN. CASING TO 6606'. CIRC CSG. CMT 5.5 CASING 1st S 1st STAGE 600 SKS 50:50 POZ:CLASS C+2% D20+5% D 1st STAGE PLUG DN @ 12:14 PM MDT, 1/07/05 BUMF CMT 5.5 CASING 2 nd STAG 2nd STAGE 350 SKS 50:50 POZ:C = 10% D20 + 5 % (BW 2 nd STAGE PLUG DN @ 6:00 PM MDT 12/07/05 BUMF NIPPLE DOWN / SET SLIPS / CUT OFF 5.5 CASING. J RIG DOWN RIG RELEASED @ 12:01 AM MDT 12/08.	the Bond No. on file with BLM/BIA. Requits in a multiple completion or recompletion donly after all requirements, including reclaim only after all requirements, including reclaim of the second of th	cused Log/Gama Ray Combo. Cused Log/Gama Ray Combo. Crew. Run 156 JTS 5.5 ,17 # M80 2167 + 4 pps D42 + 0.1 % D 13 21 STAGE. ACCEPTED FOR RECCEPTED FOR
Attach the Bond under which the work will be performed or provide following completion of the involved operations. If the operation rest testing has been completed. Final Abandonment Notices shall be file determined that the site is ready for final inspection.) TD 6606 @ 1:30 AM MDT 12/05/05 TOOH F/ LOGS. RU/LOG WELL. RUN DUEL LATERGED. T I H FOR LAY DOWN. TOOH LAYING DOWN. CASING TO 6606'. CIRC CSG. CMT 5.5 CASING 1st S 1st STAGE 600 SKS 50:50 POZ:CLASS C+2% D20+5% D 1st STAGE PLUG DN @ 12:14 PM MDT, 1/07/05 BUMF CMT 5.5 CASING 2 nd STAG 2nd STAGE 350 SKS 50:50 POZ:C = 10% D20 + 5 % (BW 2 nd STAGE PLUG DN @ 6:00 PM MDT 12/07/05 BUMP NIPPLE DOWN / SET SLIPS / CUT OFF 5.5 CASING. J RIG DOWN RIG RELEASED @ 12:01 AM MDT 12/08.	the Bond No. on file with BLM/BIA. Requits in a multiple completion or recompletion donly after all requirements, including reclaim of the completion of the	cused Log/Gama Ray Combo. Cused Log/Gama Ray Combo. Crew. Run 156 JTS 5.5 ,17 # M80 2167 + 4 pps D42 + 0.1 % D 13 21 STAGE. ACCEPTED FOR RECCEPTED FOR
Attach the Bond under which the work will be performed or provide following completion of the involved operations. If the operation rest testing has been completed. Final Abandonment Notices shall be file determined that the site is ready for final inspection.) TD 6606 @ 1:30 AM MDT 12/05/05 TOOH F/ LOGS. RU/LOG WELL. RUN DUEL LATERGED. T I H FOR LAY DOWN. TOOH LAYING DOWN. CASING TO 6606'. CIRC CSG. CMT 5.5 CASING 1st S 1st STAGE 600 SKS 50:50 POZ:CLASS C+2% D20+5% D 1st STAGE PLUG DN @ 12:14 PM MDT, 1/07/05 BUMF CMT 5.5 CASING 2 nd STAG 2nd STAGE 350 SKS 50:50 POZ:C = 10% D20 + 5 % (BW 2 nd STAGE PLUG DN @ 6:00 PM MDT 12/07/05 BUMF NIPPLE DOWN / SET SLIPS / CUT OFF 5.5 CASING. J RIG DOWN RIG RELEASED @ 12:01 AM MDT 12/08/14. I hereby certify that the foregoing is true and correct Name (Printed/Typed)	the Bond No. on file with BLM/BIA. Requits in a multiple completion or recompletion donly after all requirements, including reclaim only after all requirements, including reclaim of the second of th	cused Log/Gama Ray Combo. Cused Log/Gama Ray Combo. Crew. Run 156 JTS 5.5 ,17 # M80 2167 + 4 pps D42 + 0.1 % D 13 21 STAGE. ACCEPTED FOR RECCEPTED FOR
Attach the Bond under which the work will be performed or provide following completion of the involved operations. If the operation rest testing has been completed. Final Abandonment Notices shall be file determined that the site is ready for final inspection.) TD 6606 @ 1:30 AM MDT 12/05/05 TOOH F/ LOGS. RU/LOG WELL. RUN DUEL LATERGED. TI H FOR LAY DOWN. TOOH LAYING DOWN. CASING TO 6606'. CIRC CSG. CMT 5.5 CASING 1st S 1st STAGE 600 SKS 50:50 POZ:CLASS C+2% D20+5% D 1st STAGE PLUG DN @ 12:14 PM MDT, 1/07/05 BUMP CMT 5.5 CASING 2 nd STAG 2nd STAGE 350 SKS 50:50 POZ:C = 10% D20 + 5 % (BW 2 nd STAGE PLUG DN @ 6:00 PM MDT 12/07/05 BUMP NIPPLE DOWN / SET SLIPS / CUT OFF 5.5 CASING. J RIG DOWN RIG RELEASED @ 12:01 AM MDT 12/08. 14. I hereby certify that the foregoing is true and correct Name (Printed/Typed) Linda C. Stiles	the Bond No. on file with BLM/BIA. Requits in a multiple completion or recompletion of recompletion of recompletion of recompletion of recompletion of the second only after all requirements, including recompletion of the second of the secon	cused subsequent reports shall be filed within 30 days on in a new interval, a Form 3160-4 shall be filed once lamation, have been completed, and the operator has cused LOG/GAMA RAY COMBO. CREW. RUN 156 JTS 5.5,17 # M80 P167 + 4 pps D42 + 0.1 % D 13 P167 + 4 pps D42 + 0.1 % D 13 P167 + 4 pps D42 + 0.1 % D 13 P167 + 4 pps D42 + 0.1 % D 13 P168 TAGE. ACCEPTED FOR RECO DEC 1 5 2005 CARY GOURIEY PETROLEUM ENGINEE ch.
Attach the Bond under which the work will be performed or provide following completion of the involved operations. If the operation resistesting has been completed. Final Abandonment Notices shall be file determined that the site is ready for final inspection.) TD 6606 @ 1:30 AM MDT 12/05/05 TOOH F/ LOGS. RU/LOG WELL. RUN DUEL LATERE RD. T I H FOR LAY DOWN. TOOH LAYING DOWN CASING TO 6606'. CIRC CSG. CMT 5.5 CASING 1st S 1st STAGE 600 SKS 50:50 POZ:CLASS C+2% D20+5% D 1st STAGE PLUG DN @ 12:14 PM MDT, 1/07/05 BUMP CMT 5.5 CASING 2 nd STAG 2nd STAGE 350 SKS 50:50 POZ:C = 10% D20 + 5 % (BW 2 nd STAGE PLUG DN @ 6:00 PM MDT 12/07/05 BUMP NIPPLE DOWN / SET SLIPS / CUT OFF 5.5 CASING. J RIG DOWN RIG RELEASED @ 12:01 AM MDT 12/08. 14. Thereby certify that the foregoing is true and correct Name (Printed/Typed) Linda C. Stiles THIS SPACE FOR FE	the Bond No. on file with BLM/BIA. Requits in a multiple completion or recompletion of recompletion of recompletion of recompletion of recompletion of recompletion of the second only after all requirements, including recompletion of the second of the sec	DEC 1 5 2005 CARY GOURLEY PETROLEUM ENGINEE CH. 12/07/2005
Attach the Bond under which the work will be performed or provide following completion of the involved operations. If the operation rest testing has been completed. Final Abandonment Notices shall be file determined that the site is ready for final inspection.) TD 6606 @ 1:30 AM MDT 12/05/05 TOOH F/ LOGS. RU/LOG WELL. RUN DUEL LATERGED. TI H FOR LAY DOWN. TOOH LAYING DOWN. CASING TO 6606°. CIRC CSG. CMT 5.5 CASING 1st STAGE 600 SKS 50:50 POZ:CLASS C+2% D20+5% D 1st STAGE 600 SKS 50:50 POZ:CLASS C+2% D20+5% D 1st STAGE PLUG DN @ 12:14 PM MDT, 1/07/05 BUMF CMT 5.5 CASING 2 nd STAG 2nd STAGE 350 SKS 50:50 POZ:C = 10% D20 + 5 % (BW 2 nd STAGE PLUG DN @ 6:00 PM MDT 12/07/05 BUMP NIPPLE DOWN / SET SLIPS / CUT OFF 5.5 CASING. J RIG DOWN RIG RELEASED @ 12:01 AM MDT 12/08. 14. I hereby certify that the foregoing is true and correct Name (Printed/Typed) Linda C. Stiles Signature	the Bond No. on file with BLM/BIA. Requits in a multiple completion or recompletion of recompl	cused subsequent reports shall be filed within 30 days on in a new interval, a Form 3160-4 shall be filed once lamation, have been completed, and the operator has cused LOG/GAMA RAY COMBO. CREW. RUN 156 JTS 5.5,17 # M80 P167 + 4 pps D42 + 0.1 % D 13 P167 + 4 pps D42 + 0.1 % D 13 P167 + 4 pps D42 + 0.1 % D 13 P167 + 4 pps D42 + 0.1 % D 13 P168 TAGE. ACCEPTED FOR RECO DEC 1 5 2005 CARY GOURIEY PETROLEUM ENGINEE ch.

States any false, fictitious or fraudulent statements or representations as to anymatter within its jurisdiction.