Submit 3 Copies To Appropriate District Office	State of New Mexico Energy, Minerals and Natural Resou	Form C-103 arces May 27, 2004
District I 1625 N. French Dr., Hobbs. NM 88240	2.10.6),	WELL API NO. 30-025-06361
District II 1301 W. Grand Ave., Artesia, NM 88210	OIL CONSERVATION DIVISION DIVISIONI DIV	ON 5. Indicate Type of Lease
District III 1000 Rio Brazos Rd., Aztec, NM 87410	1220 South St. Francis Dr.	STATE X FEE
<u>District IV</u> 1220 S. St. Francis Dr., Santa Fe, NM	Santa Fe, NM 87505	6. State Oil & Gas Lease No. B-1732
87505	ICEC AND DEPONTS ON WELLS	
(DO NOT USE THIS FORM FOR PROPO	ICES AND REPORTS ON WELLS SALS TO DRILL OR TO DEEPEN OR PLUG BACK T CATION FOR PERMIT" (FORM C-101) FOR SUCH	7. Lease Name or Unit Agreement Name Northeast Drinkard Unit
1. Type of Well: Oil Well 🗓	Gas Well Other	8. Well Number 323
2. Name of Operator  Apache Corp	poration	9. OGRID Number 00873
3. Address of Operator 6120 Sou	th Yale, Suite 1500	10. Pool name or Wildcat
Tuisa, Or	X 74136-4224	Eunice; Blinebry-Tubb-Drinkard-North
4. Well Location Unit Letter R:	1980feet from the Southline	and 1980 feet from the East line
Section 2	Township 21S Range 37E	
	11. Elevation (Show whether DR, RKB, RT,	
Pit or Below-grade Tank Application ☐ o	3492' GL	
	vaterDistance from nearest fresh water well	Distance from nearest surface water
Pit Liner Thickness: mil		bbls; Construction Material
12. Check	Appropriate Box to Indicate Nature of	Notice, Report or Other Data
	ITENTION TO:	-
PERFORM REMEDIAL WORK		SUBSEQUENT REPORT OF:  AL WORK   ALTERING CASING
TEMPORARILY ABANDON		NCE DRILLING OPNS. P AND A
PULL OR ALTER CASING	MULTIPLE COMPL ☐ CASING	CEMENT JOB
TOLE ON ALTENOAGING	0/(0)/(0	OCIMEITI GOD
OTHER:	☐ OTHER:	Temporarily Abandon X
OTHER:  13. Describe proposed or comp	OTHER:	Temporarily Abandon   etails, and give pertinent dates, including estimated date
OTHER:  13. Describe proposed or composed we of starting any proposed we	OTHER:	Temporarily Abandon X
OTHER:  13. Describe proposed or comp	OTHER:	Temporarily Abandon   etails, and give pertinent dates, including estimated date
OTHER:  13. Describe proposed or comp of starting any proposed we or recompletion.	OTHER: oleted operations. (Clearly state all pertinent dork). SEE RULE 1103. For Multiple Comple	Temporarily Abandon   etails, and give pertinent dates, including estimated date
OTHER:  13. Describe proposed or compof starting any proposed we or recompletion.  1/6/2006 MIRU. Pull prod tub. 1/7-12/2006 POOH with remaining	OTHER:  oleted operations. (Clearly state all pertinent d ork). SEE RULE 1103. For Multiple Comple ing. Tubing parted.  ng tubing.	Temporarily Abandon   etails, and give pertinent dates, including estimated date tions: Attach wellbore diagram of proposed completion
OTHER:  13. Describe proposed or composed we or recompletion.  1/6/2006 MIRU. Pull prod tub. 1/7-12/2006 POOH with remaining 1/13/2006 Set CIBP @ 5680', d	OTHER:  oleted operations. (Clearly state all pertinent d bork). SEE RULE 1103. For Multiple Comple  ing. Tubing parted.  ing tubing.  ump 35' cement. Circ inhibitor. Test casing to	Temporarily Abandon   etails, and give pertinent dates, including estimated date tions: Attach wellbore diagram of proposed completion   500 psi for 30 mins ok. Secure well for TA.
OTHER:  13. Describe proposed or composed we or recompletion.  1/6/2006 MIRU. Pull prod tub. 1/7-12/2006 POOH with remaining 1/13/2006 Set CIBP @ 5680', d	OTHER:  oleted operations. (Clearly state all pertinent d ork). SEE RULE 1103. For Multiple Comple ing. Tubing parted.  ng tubing.	Temporarily Abandon   etails, and give pertinent dates, including estimated date tions: Attach wellbore diagram of proposed completion   500 psi for 30 mins ok. Secure well for TA.
OTHER:  13. Describe proposed or composed we or recompletion.  1/6/2006 MIRU. Pull prod tub. 1/7-12/2006 POOH with remaining 1/13/2006 Set CIBP @ 5680', d	OTHER:  oleted operations. (Clearly state all pertinent d bork). SEE RULE 1103. For Multiple Comple  ing. Tubing parted.  ing tubing.  ump 35' cement. Circ inhibitor. Test casing to	Temporarily Abandon   etails, and give pertinent dates, including estimated date tions: Attach wellbore diagram of proposed completion   500 psi for 30 mins ok. Secure well for TA.
OTHER:  13. Describe proposed or composed we or recompletion.  1/6/2006 MIRU. Pull prod tub. 1/7-12/2006 POOH with remaining 1/13/2006 Set CIBP @ 5680', d	OTHER:  oleted operations. (Clearly state all pertinent d bork). SEE RULE 1103. For Multiple Comple  ing. Tubing parted.  ing tubing.  ump 35' cement. Circ inhibitor. Test casing to	Temporarily Abandon   etails, and give pertinent dates, including estimated date tions: Attach wellbore diagram of proposed completion   500 psi for 30 mins ok. Secure well for TA.
OTHER:  13. Describe proposed or composed we or recompletion.  1/6/2006 MIRU. Pull prod tub. 1/7-12/2006 POOH with remaining Set CIBP @ 5680', d. 1/18/2006 Run MIT. Witnessed.	OTHER: oleted operations. (Clearly state all pertinent dork). SEE RULE 1103. For Multiple Comple ing. Tubing parted. In the state of th	Temporarily Abandon   etails, and give pertinent dates, including estimated date tions: Attach wellbore diagram of proposed completion   500 psi for 30 mins ok. Secure well for TA.
OTHER:  13. Describe proposed or composed we or recompletion.  1/6/2006 MIRU. Pull prod tub. 1/7-12/2006 POOH with remaining Set CIBP @ 5680', d. 1/18/2006 Run MIT. Witnessed.	OTHER: oleted operations. (Clearly state all pertinent dork). SEE RULE 1103. For Multiple Comple ing. Tubing parted. In the state of th	Temporarily Abandon   etails, and give pertinent dates, including estimated date tions: Attach wellbore diagram of proposed completion   500 psi for 30 mins ok. Secure well for TA.
OTHER:  13. Describe proposed or composed we or recompletion.  1/6/2006 MIRU. Pull prod tub. 1/7-12/2006 POOH with remaining Set CIBP @ 5680', d. 1/18/2006 Run MIT. Witnessed.	OTHER: oleted operations. (Clearly state all pertinent dork). SEE RULE 1103. For Multiple Comple ing. Tubing parted. In the state of th	Temporarily Abandon  etails, and give pertinent dates, including estimated date tions: Attach wellbore diagram of proposed completion  500 psi for 30 mins ok. Secure well for TA.  Received
OTHER:  13. Describe proposed or composed we or recompletion.  1/6/2006 MIRU. Pull prod tub. 1/7-12/2006 POOH with remaining 1/13/2006 Set CIBP @ 5680', d	OTHER: oleted operations. (Clearly state all pertinent dork). SEE RULE 1103. For Multiple Comple ing. Tubing parted. In the state of th	Temporarily Abandon  etails, and give pertinent dates, including estimated date tions: Attach wellbore diagram of proposed completion  500 psi for 30 mins ok. Secure well for TA.  ned.  Received Hobbs
OTHER:  13. Describe proposed or composed we or recompletion.  1/6/2006 MIRU. Pull prod tub. 1/7-12/2006 POOH with remaining Set CIBP @ 5680', d. 1/18/2006 Run MIT. Witnessed.	OTHER: oleted operations. (Clearly state all pertinent dork). SEE RULE 1103. For Multiple Comple ing. Tubing parted. In the state of th	Temporarily Abandon  etails, and give pertinent dates, including estimated date tions: Attach wellbore diagram of proposed completion  500 psi for 30 mins ok. Secure well for TA.  Received
OTHER:  13. Describe proposed or compof starting any proposed we or recompletion.  1/6/2006 MIRU. Pull prod tub. 1/7-12/2006 POOH with remaining Set CIBP @ 5680', d Run MIT. Witnessed  This Approval Abandonment	OTHER:  bleted operations. (Clearly state all pertinent d bork). SEE RULE 1103. For Multiple Comple  ing. Tubing parted.  ing tubing.  ump 35' cement. Circ inhibitor. Test casing to by E. Gonzales with OCD. Signed chart attack  of Temporary  Expires	Temporarily Abandon  etails, and give pertinent dates, including estimated date tions: Attach wellbore diagram of proposed completion  500 psi for 30 mins ok. Secure well for TA.  ned.  2006  Received  Hobbs  OCD
OTHER:  13. Describe proposed or compof starting any proposed we or recompletion.  1/6/2006 MIRU. Pull prod tub. 1/7-12/2006 POOH with remaining 1/13/2006 Set CIBP @ 5680', d 1/18/2006 Run MIT. Witnessed  This Approval Abandonment	OTHER:  oleted operations. (Clearly state all pertinent deprk). SEE RULE 1103. For Multiple Comple  one, Tubing parted.  one tubing.  ump 35' cement. Circ inhibitor. Test casing to by E. Gonzales with OCD. Signed chart attack  of Temporary  Expires	Temporarily Abandon  etails, and give pertinent dates, including estimated date tions: Attach wellbore diagram of proposed completion  500 psi for 30 mins ok. Secure well for TA.  ned.  Received Hobbs
OTHER:  13. Describe proposed or compof starting any proposed we or recompletion.  1/6/2006 MIRU. Pull prod tub. 1/7-12/2006 POOH with remaining 1/13/2006 Set CIBP @ 5680', d 1/18/2006 Run MIT. Witnessed  This Approval Abandonment	OTHER:  oleted operations. (Clearly state all pertinent deprk). SEE RULE 1103. For Multiple Comple  one, Tubing parted.  one tubing.  ump 35' cement. Circ inhibitor. Test casing to by E. Gonzales with OCD. Signed chart attack  of Temporary  Expires	Temporarily Abandon  etails, and give pertinent dates, including estimated date tions: Attach wellbore diagram of proposed completion  500 psi for 30 mins ok. Secure well for TA.  ned.  Received  Hobbs  OCD  cnowledge and belief of further certify that any pit or below- permit or an (attached) alternative OCD-approved plan .
OTHER:  13. Describe proposed or composed we or recompletion.  1/6/2006 MIRU. Pull prod tub. 1/7-12/2006 POOH with remaining 1/13/2006 Set CIBP @ 5680', d. 1/18/2006 Run MIT. Witnessed  This Approval Abandonment  I hereby certify that the information grade tank has been/will be constructed or SIGNATURE	OTHER:  oleted operations. (Clearly state all pertinent deprk). SEE RULE 1103. For Multiple Comple  ing. Tubing parted.  ing tubing.  ump 35' cement. Circ inhibitor. Test casing to by E. Gonzales with OCD. Signed chart attack  of Temporary  Expires  above is true and complete to the best of my kelosed according to NMOCD guidelines , a general true.  TITLE Engineering Temporary	Temporarily Abandon  etails, and give pertinent dates, including estimated date tions: Attach wellbore diagram of proposed completion  500 psi for 30 mins ok. Secure well for TA.  ned.  2006  Received Hobbs 000  nowledge and belief in the certify that any pit or belowpermit or an (attached) alternative OCD-approved plan .  Cechnician  DATE 01/23/2006
OTHER:  13. Describe proposed or composed we or recompletion.  1/6/2006 MIRU. Pull prod tub. 1/7-12/2006 POOH with remaining Set CIBP @ 5680', d. 1/18/2006 Run MIT. Witnessed  This Approval Abandonment  I hereby certify that the information grade tank has been/will be constructed or Callan.	OTHER:  oleted operations. (Clearly state all pertinent deprk). SEE RULE 1103. For Multiple Comple  ing. Tubing parted.  ing tubing.  ump 35' cement. Circ inhibitor. Test casing to by E. Gonzales with OCD. Signed chart attack  of Temporary  Expires  above is true and complete to the best of my kelosed according to NMOCD guidelines , a general true.  TITLE Engineering Temporary	Temporarily Abandon  etails, and give pertinent dates, including estimated date tions: Attach wellbore diagram of proposed completion  500 psi for 30 mins ok. Secure well for TA.  ned.  2006  Received Hobbs 000  nowledge and belief of further certify that any pit or belowpermit or an (attached) alternative OCD-approved plan
OTHER:  13. Describe proposed or composed we or recompletion.  1/6/2006 MIRU. Pull prod tub. 1/7-12/2006 POOH with remaining 1/13/2006 Set CIBP @ 5680', d. 1/18/2006 Run MIT. Witnessed  This Approval Abandonment  I hereby certify that the information grade tank has been/will be constructed or SIGNATURE  Type or print name Elaine Linton  For State Use Only	of Temporary  Expires  above is true and complete to the best of my k closed according to NMOCD guidelines , a general E-mail address: elain	etails, and give pertinent dates, including estimated date tions: Attach wellbore diagram of proposed completion  500 psi for 30 mins ok. Secure well for TA.  1008  Received Hobbs  1009
OTHER:  13. Describe proposed or composed we or recompletion.  1/6/2006 MIRU. Pull prod tub. 1/7-12/2006 POOH with remaining 1/13/2006 Set CIBP @ 5680', d. 1/18/2006 Run MIT. Witnessed  This Approval Abandonment  I hereby certify that the information grade tank has been/will be constructed or SIGNATURE  Type or print name Elaine Linton	OTHER:  oleted operations. (Clearly state all pertinent deprk). SEE RULE 1103. For Multiple Comple  ing. Tubing parted.  ing tubing.  ump 35' cement. Circ inhibitor. Test casing to by E. Gonzales with OCD. Signed chart attack  of Temporary  Expires  above is true and complete to the best of my kelosed according to NMOCD guidelines , a general true.  TITLE Engineering Temporary	Temporarily Abandon  etails, and give pertinent dates, including estimated date tions: Attach wellbore diagram of proposed completion  500 psi for 30 mins ok. Secure well for TA.  ned.  Received Hobbs 000  nowledge and belief in the certify that any pit or belowpermit or an (attached) alternative OCD-approved plan .  Cechnician  DATE 01/23/2006

