Office District I		Mexico		Form C-10
1635 N Franch D 17 11 20 2000	Energy, Minerals and Na	atural Resources	TITTY I THE TOTAL THE TOTA	May 27, 20
District II			WELL API NO.	11000
1301 W. Grand Ave., Artesia, NM 88210	OIL CONSERVATION	ON DIVISION	30-025-07551-00-00 5. Indicate Type of L	7
District III	1220 South St. F	1220 South St. Francis Dr.		74
1000 Rio Brazos Rd., Aztec, NM 87410 District IV		Santa Fe, NM 87505		FEE
1220 S. St. Francis Dr., Santa Fe, NM	Smitt 1 0, 14141	07000	6. State Oil & Gas Le Salt Mining Lease	ase No.
87505 SUNDRY NOTIC	CES AND REPORTS ON WEL	IS	_	1
(DO NOT USE THIS FORM FOR PROPOS	ALS TO DRILL OR TO DEEPEN OR	PLUG BACK TO A	7. Lease Name or Un	Agreement Name
DIFFERENT RESERVOIR. USE "APPLIC	ATION FOR PERMIT" (FORM C-101)	FOR SUCH	Truckers Brine	5494101
PROPOSALS.) 1. Type of Well: Oil Well	Gas Well X Other	•	8. Well Number 2	
2. Name of Operator	Jas Well A Ullici		9. OGRID Number	11
Yale E. Key, Inc. dba Key Energy S	Services, Permian Basin Divisio	n	19797	
3. Address of Operator			10. Pool name or Wil	dcat
Box 99 Eunice, NM 88231			BSW Salado	776
4. Well Location				
	om the South line and 1980 fe	et from the West line		
Section 33 Township 18S	Range 38E	NMPM C	ounty Lea	
	11. Elevation (Show whether L	OR, RKB, RT, GR, etc.,		
Pit or Below-grade Tank Application or	Clasura			
	····	_		
Pit type Depth to Groundwar		··· -	ance from nearest surface w	ater
Pit Liner Thickness: mil	Below-Grade Tank: Volume		nstruction Material	
12. Check A	ppropriate Box to Indicate	Nature of Notice,	Report or Other Dat	a .
NOTICE OF INT		1		
PERFORM REMEDIAL WORK			SEQUENT REPOR	4
- TEMEDIAL WORK				ERING CASING
PULL OR ALTER CASING	—	COMMENCE DRI		NDA 🗆
. SEE ON ALTER CASING [MULTIPLE COMPL	CASING/CEMEN	I JOB 📋 ,	
OTHER: Test Casing	Х	OTHER:		_
13. Describe proposed or comple	eted operations. (Clearly state a	Il pertinent details on	oive pertinent datas in	aludino actionete 2 1
of starting any proposed wor or recompletion.	k). SEE RULE 1103. For Mult	iple Completions: At	tach wellbore diagram o	proposed completi
1/24/06 Diament 11	25	_		
/ 24/06 Rig up pulling unit, install Bo	OP, pull and stand back tubing.	Run casing scraper. R	un packer and pressure u	p casing to 500# fo
1/24/06 Rig up pulling unit, install Boest. OCD will be notified when testing	OP, pull and stand back tubing. g begins.	Run casing scraper. R	un packer and pressure i	p casing to 500# fo
1/24/06 Rig up pulling unit, install Beest. OCD will be notified when testin	OP, pull and stand back tubing. g begins.	Run casing scraper. R	un packer and pressure u	p casing to 500# fo
/ 24/06 Rig up pulling unit, install Be est. OCD will be notified when testin	OP, pull and stand back tubing. g begins.	Run casing scraper. R	un packer and pressure u	p casing to 500# fo
1/24/06 Rig up pulling unit, install Boest. OCD will be notified when testin	OP, pull and stand back tubing. g begins.	Run casing scraper. R	un packer and pressure t	p casing to 500# fo
1/24/06 Rig up pulling unit, install Boest. OCD will be notified when testin	OP, pull and stand back tubing. g begins.	Run casing scraper. R	un packer and pressure u	p casing to 500# fo
1/24/06 Rig up pulling unit, install Beest. OCD will be notified when testin	OP, pull and stand back tubing. g begins.	Run casing scraper. R	un packer and pressure u	p casing to 500# fo
1/24/06 Rig up pulling unit, install Beest. OCD will be notified when testin	OP, pull and stand back tubing. g begins.	Run casing scraper. R	un packer and pressure t	p casing to 500# fo
1/24/06 Rig up pulling unit, install Beest. OCD will be notified when testin	OP, pull and stand back tubing. g begins.	Run casing scraper. R	un packer and pressure t	p casing to 500# fo
1/24/06 Rig up pulling unit, install Boest. OCD will be notified when testin	OP, pull and stand back tubing. g begins.	Run casing scraper. R	un packer and pressure t	p casing to 500# fo
1/24/06 Rig up pulling unit, install Boest. OCD will be notified when testin	OP, pull and stand back tubing. g begins.	Run casing scraper. R	un packer and pressure u	p casing to 500# fo
1/24/06 Rig up pulling unit, install Beest. OCD will be notified when testin	OP, pull and stand back tubing. g begins.	Run casing scraper. R	un packer and pressure u	p casing to 500# fo
l/24/06 Rig up pulling unit, install Beest. OCD will be notified when testin	OP, pull and stand back tubing. g begins.	Run casing scraper. R	un packer and pressure u	p casing to 500# fo
1/24/06 Rig up pulling unit, install Boest. OCD will be notified when testin	OP, pull and stand back tubing. g begins.	Run casing scraper. R	un packer and pressure t	p casing to 500# fo
1/24/06 Rig up pulling unit, install Botest. OCD will be notified when testin	OP, pull and stand back tubing. g begins.	Run casing scraper. R	un packer and pressure t	p casing to 500# fo
est. OCD will be notified when testing	g begins.		Hobbs	
hereby certify that the information al	g begins.	hest of my knowledge	OCD S	
hereby certify that the information al	g begins.	hest of my knowledge	OCD S	
hereby certify that the information at rade tank has been/will be constructed or ck	oove is true and complete to the osed according to NMOCD guidelines	best of my knowledge □, a general permit □ o	and belief. I further certor an (attached) alternative	fy that any pit or below
hereby certify that the information at rade tank has been/will be constructed or chestign.	pove is true and complete to the osed according to NMOCD guidelines	best of my knowledge □, a general permit □ o Area Manager	OCD S	fy that any pit or below
hereby certify that the information abrade tank has been/will be constructed or chestignature. Signature Bob Patterson	oove is true and complete to the osed according to NMOCD guidelines	best of my knowledge □, a general permit □ o Area Manager	and belief. I further certor an (attached) alternative	fy that any pit or below CD-approved plan □./24/06
hereby certify that the information abrade tank has been/will be constructed or che signature. Signature Bob Patterson	pove is true and complete to the osed according to NMOCD guidelines	best of my knowledge □, a general permit □ o Area Manager keyenergy.com Tel	and belief. I further certor an (attached) alternative of DATE ephone No. (505) 631-7	fy that any pit or below CD-approved plan □./24/06
hereby certify that the information abrade tank has been/will be constructed or che signature. Signature Bob Patterson	pove is true and complete to the osed according to NMOCD guidelines	best of my knowledge □, a general permit □ o Area Manager keyenergy.com Tel	and belief. I further certor an (attached) alternative of DATE ephone No. (505) 631-7	fy that any pit or below CD-approved plan □./24/06
hereby certify that the information abrade tank has been/will be constructed or che signature. Signature Bob Patterson	pove is true and complete to the osed according to NMOCD guidelines TITLE E-mail address: bpatterson@	best of my knowledge , a general permit Area Manager keyenergy.com Tel	and belief. I further certor an (attached) alternative of DATE ephone No. (505) 631-7	fy that any pit or below CD-approved plan □./24/06
Type or print name Bob Patterson For State Use Only APPROVED BY:	pove is true and complete to the osed according to NMOCD guidelines TITLE E-mail address: bpatterson@	best of my knowledge , a general permit Area Manager keyenergy.com Tel	and belief. I further certor an (attached) alternative of DATE ephone No. (505) 631-7	fy that any pit or belo CD-approved plan [24/06]
hereby certify that the information abrade tank has been/will be constructed or chestignature. Signature Bob Patterson	pove is true and complete to the osed according to NMOCD guidelines	best of my knowledge , a general permit Area Manager keyenergy.com Tel	and belief. I further certor an (attached) alternative of DATE ephone No. (505) 631-7	fy that any pit or below CD-approved plan □ /24/06 597