

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT

OCD-HOBBS

FORM APPROVED  
OMB NO. 1004-0137  
Expires March 31, 2007

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.

SUBMIT IN TRIPLICATE - Other instructions on reverse side

1. Type of Well

☒ Oil Well ☐ Gas Well ☐ Other

2. Name of Operator

Stephens & Johnson Operating Co.

3a. Address

P.O. Box 2249 Wichita Falls TX 76307-2249

3b. Phone No. (include area code)

(940) 723-2166

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

Sec 26, T14S, R37E 1980' FSL & 460' FEL

5. Lease Serial No.

6. If Indian, Allottee or Tribe Name

7. If Unit or CA/Agreement, Name and/or No.  
8910087370

Denton North Wolfcamp Unit

8. Well Name and No.

Denton North Wolf- Tr 6-28

camp Unit

9. API Well No.

30-025-05155

10. Field and Pool, or Exploratory Area

Denton Wolfcamp

11. County or Parish, State

Lea County NM

12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

☐ Notice of Intent

☐ Subsequent Report

☒ Final Abandonment Notice

TYPE OF ACTION

☐ Acidize

☐ Alter Casing

☐ Casing Repair

☐ Change Plans

☐ Convert to Injection

☐ Deepen

☐ Fracture Treat

☐ New Construction

☒ Plug and Abandon

☐ Plug Back

☐ Production (Start/Resume)

☐ Reclamation

☐ Recomplete

☐ Temporarily Abandon

☐ Water Disposal

☐ Water Shut-Off

☐ Well Integrity

☐ Other

13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recompleate horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompleation in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the final site is ready for final inspection.)

12-8-05 MIRU. RIH with gauge. Cold not get past 5720'. RIH w/bit and scrapper. Could not get past 5953'. Pressured up on well to 500#. Could not pump down hole. Billy Prichard with OCD OK'd RIH open ended. Could not get past 5953'.

12-9-05 Circ. oil out of well.

12-12-05 Spot 25 sx. @ 5922'-5652'. Measured TOC per Billy Prichard. Mix mud circ. 10# MLF from 5652' to surface.

12-13-05 Spot 60 sx. 4891-4513'. Measured TOC. Spot 25 sx. 3150'-3027'. Calc. TOC. Spot 25 sx. 2200'-2077'. Calc. TOC. Spot 125 sx. 493' to surface. POOH w/tbg. Top off well with cmt.

12-14-05 RDMO.

\*\*Note: This well is a State well; however, Tract 1 is Federal. Therefore we respectfully request that the BLM update the well status in their database.

14. I hereby certify that the foregoing is true and correct  
Name (Printed/Typed)

Devire D Crabb

Title

Production Analyst

Date

Jan 10, 2006

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Approved by

Title

Date

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Office

Title 18 U.S.C. Section 1001, and Title 43 U.S.C. Section 1212, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

GWW