Submit 3 Copies To Appropriate District State of New Mexico	F017067103
District I 1625 N. French Dr., Hobbs, NM 88240 Energy, Minerals and Natural Resources	WELL API NO. 30-025-34243
District II 1301 W. Grand Ave., Artesia, NM 88210 OIL CONSERVATION DIVISION	30-025-34243 (*) 5. Indicate Type of Lease FEB 2006
District III 1000 Rio Brazos Rd., Aztec, NM 87410 1220 South St. Francis Dr.	STATE SI FERECEIVED
District IV 1220 S. St. Francis Dr., Santa Fe, NM	6. State Oil & Gas Lease No. Hobbs
87505	6. State Oil & Gas Lease No. Hobbs
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A	7. Lease Name or Unit Agreement Name
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH	Monument 13 State
PROPOSALS.) 1. Type of Well: Oil Well Gas Well Other:	8. Well Number: 17
2. Name of Operator	9. OGRID Number
Chevron USA Inc	
3. Address of OperatorP.O. Box 7139, Midland, Texas 79708	10. Pool name or Wildcat Wildcat (Drinkard)
4. Well Location	
Unit Letter <u>F</u> : 1912 feet from the <u>North</u> line and 172	32 feet from the West line
Section 13 Township 19S Range 36E	NMPM County Lea
11. Elevation (Show whether DR, RKB, RT, GR, etc.)	
3722'	
Pit or Below-grade Tank Application or Closure	
Pit type_STEELDepth to Groundwater_54Distance from nearest fresh water well_over 1000I Pit Liner Thickness: mil Below-Grade Tank: Volume bbls; Con	
	Istruction Material
12. Check Appropriate Box to Indicate Nature of Notice, I	Report or Other Data
	SEQUENT REPORT OF:
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK	
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRIL PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMENT	
FULL OR ALTER CASING IT MULTIPLE COMPLETT TO CASING/CEMENT	
	30B []
OTHER: OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, and	give pertinent dates, including estimated date
	give pertinent dates, including estimated date
OTHER: OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 1103. For Multiple Completions: Atta	give pertinent dates, including estimated date
OTHER: OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 1103. For Multiple Completions: Atta or recompletion.	give pertinent dates, including estimated date ach wellbore diagram of proposed completion
OTHER: OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 1103. For Multiple Completions: Atta or recompletion. 1. Notified NMOCD 24 hrs. prior to MI&RU. 2. Set CIBP @ 6,650' and spotted 25sx of cement on top from 6,650' 3. Displaced hole w/MLF, 9.5 ppg brine w/12.5 gel p/bbl.	give pertinent dates, including estimated date ach wellbore diagram of proposed completion r - 6,450' (Drinkard perfs).
OTHER: OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 1103. For Multiple Completions: Atta or recompletion. 1. Notified NMOCD 24 hrs. prior to MI&RU. 2. Set CIBP @ 6,650' and spotted 25sx of cement on top from 6,650' 3. Displaced hole w/MLF, 9.5 ppg brine w/12.5 gel p/bbl. 4. Perf'd at 4,400', unable to EPIR. Spotted 35sx cement plug from 4	give pertinent dates, including estimated date ach wellbore diagram of proposed completion r - 6,450' (Drinkard perfs).
OTHER: OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 1103. For Multiple Completions: Atta or recompletion. 1. Notified NMOCD 24 hrs. prior to MI&RU. 2. Set CIBP @ 6,650' and spotted 25sx of cement on top from 6,650' 3. Displaced hole w/MLF, 9.5 ppg brine w/12.5 gel p/bbl. 4. Perf'd at 4,400', unable to EPIR. Spotted 35sx cement plug from casing squeeze) WOC Tagged @ 4,095'.	give pertinent dates, including estimated date ach wellbore diagram of proposed completion r - 6,450' (Drinkard perfs).
OTHER: OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 1103. For Multiple Completions: Atta or recompletion. 1. Notified NMOCD 24 hrs. prior to MI&RU. 2. Set CIBP @ 6,650' and spotted 25sx of cement on top from 6,650' 3. Displaced hole w/MLF, 9.5 ppg brine w/12.5 gel p/bbl. 4. Perf'd at 4,400', unable to EPIR. Spotted 35sx cement plug from casing squeeze) WOC Tagged @ 4,095'. 5. Cut and pulled 2,725' of 5-1/2" casing.	give pertinent dates, including estimated date ach wellbore diagram of proposed completion r = 6,450' (Drinkard perfs). 4,450'-4,100' (San Andres, existing
OTHER: OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 1103. For Multiple Completions: Atta or recompletion. 1. Notified NMOCD 24 hrs. prior to MI&RU. 2. Set CIBP @ 6,650' and spotted 25sx of cement on top from 6,650' 3. Displaced hole w/MLF, 9.5 ppg brine w/12.5 gel p/bbl. 4. Perf'd at 4,400', unable to EPIR. Spotted 35sx cement plug from casing squeeze) WOC Tagged @ 4,095'. 5. Cut and pulled 2,725' of 5-1/2" casing. 6. Spotted 115sx plug from 2,775'-2,440' (8-5/8" shoe,5-1/2" stub,B	give pertinent dates, including estimated date ach wellbore diagram of proposed completion r = 6,450' (Drinkard perfs). 4,450'-4,100' (San Andres, existing
OTHER:OTHER:13. Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 1103. For Multiple Completions: Atta or recompletion.1. Notified NMOCD 24 hrs. prior to MI&RU.2. Set CIBP @ 6,650' and spotted 25sx of cement on top from 6,650'3. Displaced hole w/MLF, 9.5 ppg brine w/12.5 gel p/bbl.4. Perf'd at 4,400', unable to EPIR. Spotted 35sx cement plug from casing squeeze) WOC Tagged @ 4,095'.5. Cut and pulled 2,725' of 5-1/2" casing.6. Spotted 115sx plug from 2,775'-2,440' (8-5/8" shoe,5-1/2" stub,B Approved by NMOCD - Buddy Hill.	give pertinent dates, including estimated date ach wellbore diagram of proposed completion r = 6,450' (Drinkard perfs). 4,450'-4,100' (San Andres, existing
OTHER:OTHER:13. Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 1103. For Multiple Completions: Atta or recompletion.1. Notified NMOCD 24 hrs. prior to MI&RU.2. Set CIBP @ 6,650' and spotted 25sx of cement on top from 6,650'3. Displaced hole w/MLF, 9.5 ppg brine w/12.5 gel p/bbl.4. Perf'd at 4,400', unable to EPIR. Spotted 35sx cement plug from casing squeeze) WOC Tagged @ 4,095'.5. Cut and pulled 2,725' of 5-1/2" casing.6. Spotted 115sx plug from 2,775'-2,440' (8-5/8" shoe,5-1/2" stub,B Approved by NMOCD - Buddy Hill.7. Spotted 70sx plug from 1,550'-1,295' (T. salt).	give pertinent dates, including estimated date ach wellbore diagram of proposed completion ? – 6,450' (Drinkard perfs). 4,450'-4,100' (San Andres, existing . salt, Yates) WOC Tagged @ 2,573'.
OTHER:Image: OTHER:13. Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 1103. For Multiple Completions: Atta or recompletion.1. Notified NMOCD 24 hrs. prior to MI&RU.2. Set CIBP @ 6,650' and spotted 25sx of cement on top from 6,650'3. Displaced hole w/MLF, 9.5 ppg brine w/12.5 gel p/bbl.4. Perf'd at 4,400', unable to EPIR. Spotted 35sx cement plug from casing squeeze) WOC Tagged @ 4,095'.5. Cut and pulled 2,725' of 5-1/2" casing.6. Spotted 115sx plug from 2,775'-2,440' (8-5/8" shoe,5-1/2" stub,B Approved by NMOCD - Buddy Hill.7. Spotted 70sx plug from 1,550'-1,295' (T. salt).8. Spotted 70sx plug from 550'-275' (13-3/8 shoe) WOC Tagged @ 4	give pertinent dates, including estimated date ach wellbore diagram of proposed completion ? – 6,450' (Drinkard perfs). 4,450'-4,100' (San Andres, existing . salt, Yates) WOC Tagged @ 2,573'.
OTHER:OTHER:13. Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 1103. For Multiple Completions: Atta or recompletion.1. Notified NMOCD 24 hrs. prior to MI&RU.2. Set CIBP @ 6,650' and spotted 25sx of cement on top from 6,650'3. Displaced hole w/MLF, 9.5 ppg brine w/12.5 gel p/bbl.4. Perf'd at 4,400', unable to EPIR. Spotted 35sx cement plug from casing squeeze) WOC Tagged @ 4,095'.5. Cut and pulled 2,725' of 5-1/2" casing.6. Spotted 115sx plug from 2,775'-2,440' (8-5/8" shoe,5-1/2" stub,B Approved by NMOCD - Buddy Hill.7. Spotted 70sx plug from 1,550'-1,295' (T. salt).8. Spotted 70sx plug from 550'-275' (13-3/8 shoe) WOC Tagged @ from 403' - 313'. Approved by NMOCD - Buddy Hill.	give pertinent dates, including estimated date ach wellbore diagram of proposed completion ? - 6,450' (Drinkard perfs). 4,450'-4,100' (San Andres, existing . salt, Yates) WOC Tagged @ 2,573'. 403'. Re-spotted 25sx cement plug
OTHER: OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 1103. For Multiple Completions: Atta or recompletion. 1. Notified NMOCD 24 hrs. prior to MI&RU. 2. Set CIBP @ 6,650' and spotted 25sx of cement on top from 6,650' 3. Displaced hole w/MLF, 9.5 ppg brine w/12.5 gel p/bbl. 4. Perf'd at 4,400', unable to EPIR. Spotted 35sx cement plug from a casing squeeze) WOC Tagged @ 4,095'. 5. Cut and pulled 2,725' of 5-1/2'' casing. 6. Spotted 115sx plug from 2,775'-2,440' (8-5/8'' shoe,5-1/2'' stub,B Approved by NMOCD - Buddy Hill. 7. Spotted 70sx plug from 1,550'-1,295' (T. salt). 8. Spotted 70sx plug from 550'-275' (13-3/8 shoe) WOC Tagged @ from 403' – 313'. Approved by NMOCD - Buddy Hill. 9. Spotted 30sx plug from 100'-surface. (surface) WOC Tagged @ state and approved approved by NMOCD - Buddy Hill.	give pertinent dates, including estimated date ach wellbore diagram of proposed completion ? - 6,450' (Drinkard perfs). 4,450'-4,100' (San Andres, existing . salt, Yates) WOC Tagged @ 2,573'. 403'. Re-spotted 25sx cement plug urface.
OTHER: OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 1103. For Multiple Completions: Atta or recompletion. 1. Notified NMOCD 24 hrs. prior to MI&RU. 2. Set CIBP @ 6,650' and spotted 25sx of cement on top from 6,650' 3. Displaced hole w/MLF, 9.5 ppg brine w/12.5 gel p/bbl. 4. Perf'd at 4,400', unable to EPIR. Spotted 35sx cement plug from casing squeeze) WOC Tagged @ 4,095'. 5. Cut and pulled 2,725' of 5-1/2" casing. 6. Spotted 115sx plug from 2,775'-2,440' (8-5/8" shoe,5-1/2" stub,B Approved by NMOCD - Buddy Hill. 7. Spotted 70sx plug from 1,550'-1,295' (T. salt). 8. Spotted 70sx plug from 550'-275' (13-3/8 shoe) WOC Tagged @ since 403' - 313'. Approved by NMOCD - Buddy Hill. 9. Spotted 30sx plug from 100'-surface. (surface) WOC Tagged @ since 403' - 313'. Approved by NMOCD - Buddy Hill. 9. Spotted 30sx plug from 100'-surface. (surface) WOC Tagged @ since 403' - 313'. Approved by NMOCD - Buddy Hill.	give pertinent dates, including estimated date ach wellbore diagram of proposed completion ? - 6,450' (Drinkard perfs). 4,450'-4,100' (San Andres, existing . salt, Yates) WOC Tagged @ 2,573'. 403'. Re-spotted 25sx cement plug urface. wed as to plugging of the Well Bore. ity under bond is retained until
OTHER: OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 1103. For Multiple Completions: Atta or recompletion. 1. Notified NMOCD 24 hrs. prior to MI&RU. 2. Set CIBP @ 6,650' and spotted 25sx of cement on top from 6,650' 3. Displaced hole w/MLF, 9.5 ppg brine w/12.5 gel p/bbl. 4. Perf'd at 4,400', unable to EPIR. Spotted 35sx cement plug from casing squeeze) WOC Tagged @ 4,095'. 5. Cut and pulled 2,725' of 5-1/2'' casing. 6. Spotted 115sx plug from 2,775'-2,440' (8-5/8'' shoe,5-1/2'' stub,B Approved by NMOCD - Buddy Hill. 7. Spotted 70sx plug from 1,550'-1,295' (T. salt). 8. Spotted 70sx plug from 550'-275' (13-3/8 shoe) WOC Tagged @ strom 403' - 313'. Approved by NMOCD - Buddy Hill. 9. Spotted 30sx plug from 100'-surface. (surface) WOC Tagged @ strom 403' - 313'. Approved by NMOCD - Buddy Hill. 9. Spotted 30sx plug from 100'-surface. (surface) WOC Tagged @ strom 403' - 313'. Approved by NMOCD - Buddy Hill.	give pertinent dates, including estimated date ach wellbore diagram of proposed completion ? - 6,450' (Drinkard perfs). 4,450'-4,100' (San Andres, existing . salt, Yates) WOC Tagged @ 2,573'. 403'. Re-spotted 25sx cement plug urface. wed as to plugging of the Well Bore. ty under bond is retained until e restoration is completed.
OTHER: OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 1103. For Multiple Completions: Atta or recompletion. 1. Notified NMOCD 24 hrs. prior to MI&RU. 2. Set CIBP @ 6,650' and spotted 25sx of cement on top from 6,650' 3. Displaced hole w/MLF, 9.5 ppg brine w/12.5 gel p/bbl. 4. Perf'd at 4,400', unable to EPIR. Spotted 35sx cement plug from casing squeeze) WOC Tagged @ 4,095'. 5. Cut and pulled 2,725' of 5-1/2" casing. 6. Spotted 115sx plug from 2,775'-2,440' (8-5/8" shoe,5-1/2" stub,B Approved by NMOCD - Buddy Hill. 7. Spotted 70sx plug from 1,550'-1,295' (T. salt). 8. Spotted 70sx plug from 550'-275' (13-3/8 shoe) WOC Tagged @ since 403' - 313'. Approved by NMOCD - Buddy Hill. 9. Spotted 30sx plug from 100'-surface. (surface) WOC Tagged @ since 403' - 313'. Approved by NMOCD - Buddy Hill. 9. Spotted 30sx plug from 100'-surface. (surface) WOC Tagged @ since 403' - 313'. Approved by NMOCD - Buddy Hill.	give pertinent dates, including estimated date ach wellbore diagram of proposed completion ? - 6,450' (Drinkard perfs). 4,450'-4,100' (San Andres, existing . salt, Yates) WOC Tagged @ 2,573'. 403'. Re-spotted 25sx cement plug urface. wed as to plugging of the Well Bore. ty under bond is retained unifili- e restoration is completed. and belief. I further certify that any pit or below-
OTHER: □ OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 1103. For Multiple Completions: Atta or recompletion. 1. Notified NMOCD 24 hrs. prior to MI&RU. 2. Set CIBP @ 6,650' and spotted 25sx of cement on top from 6,650' 3. Displaced hole w/MLF, 9.5 ppg brine w/12.5 gel p/bbl. 4. Perf'd at 4,400', unable to EPIR. Spotted 35sx cement plug from - casing squeeze) WOC Tagged @ 4,095'. 5. Cut and pulled 2,725' of 5-1/2" casing. 6. Spotted 115sx plug from 2,775'-2,440' (8-5/8" shoe,5-1/2" stub,B Approved by NMOCD - Buddy Hill. 7. Spotted 70sx plug from 1,550'-1,295' (T. salt). 8. Spotted 70sx plug from 550'-275' (13-3/8 shoe) WOC Tagged @ so from 403' – 313'. Approved by NMOCD - Buddy Hill. 9. Spotted 30sx plug from 100'-surface. (surface) WOC Tagged @ so 10.Installed dry hole marker on 2/09/2006. Approx 1 hereby certify that the information above is true and complete to the best of my knowledge grade tank has been/will be constructed or closed according to NMOCD guidelines □, a general permit □ o SIGNATURE TITLE Manager	give pertinent dates, including estimated date ach wellbore diagram of proposed completion 7 - 6,450' (Drinkard perfs). 4,450'-4,100' (San Andres, existing 4,450'-4,100' (San Andres, existing 4,450' - 4,100' (San Andres, existing 4,40' - 4,100' (San Andre
OTHER: □ OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 1103. For Multiple Completions: Atta or recompletion. 1. Notified NMOCD 24 hrs. prior to MI&RU. 2. Set CIBP @ 6,650' and spotted 25sx of cement on top from 6,650' 3. Displaced hole w/MLF, 9.5 ppg brine w/12.5 gel p/bbl. 4. Perf'd at 4,400', unable to EPIR. Spotted 35sx cement plug from - casing squeeze) WOC Tagged @ 4,095'. 5. Cut and pulled 2,725' of 5-1/2" casing. 6. Spotted 115sx plug from 2,775'-2,440' (8-5/8" shoe,5-1/2" stub,B Approved by NMOCD - Buddy Hill. 7. Spotted 70sx plug from 1,550'-1,295' (T. salt). 8. Spotted 70sx plug from 550'-275' (13-3/8 shoe) WOC Tagged @ so from 403' – 313'. Approved by NMOCD - Buddy Hill. 9. Spotted 30sx plug from 100'-surface. (surface) WOC Tagged @ so 10.Installed dry hole marker on 2/09/2006. Approx 1 hereby certify that the information above is true and complete to the best of my knowledge grade tank has been/will be constructed or closed according to NMOCD guidelines □, a general permit □ o SIGNATURE TITLE Manager	give pertinent dates, including estimated date ach wellbore diagram of proposed completion 7 - 6,450' (Drinkard perfs). 4,450'-4,100' (San Andres, existing 4,450'-4,100' (San Andres, existing 4,450' - 4,100' (San Andres, existing 4,40' - 4,100' (San Andre
OTHER: □ OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 1103. For Multiple Completions: Atta or recompletion. 1. Notified NMOCD 24 hrs. prior to MI&RU. 2. Set CIBP @ 6,650' and spotted 25sx of cement on top from 6,650' 3. Displaced hole w/MLF, 9.5 ppg brine w/12.5 gel p/bbl. 4. Perf'd at 4,400', unable to EPIR. Spotted 35sx cement plug from - casing squeeze) WOC Tagged @ 4,095'. 5. Cut and pulled 2,725' of 5-1/2" casing. 6. Spotted 115sx plug from 2,775'-2,440' (8-5/8" shoe,5-1/2" stub,B Approved by NMOCD - Buddy Hill. 7. Spotted 70sx plug from 1,550'-1,295' (T. salt). 8. Spotted 70sx plug from 550'-275' (13-3/8 shoe) WOC Tagged @ so from 403' – 313'. Approved by NMOCD - Buddy Hill. 9. Spotted 30sx plug from 100'-surface. (surface) WOC Tagged @ so 10.Installed dry hole marker on 2/09/2006. Approx 1 hereby certify that the information above is true and complete to the best of my knowledge grade tank has been/will be constructed or closed according to NMOCD guidelines □, a general permit □ o SIGNATURE TITLE Manager	give pertinent dates, including estimated date ach wellbore diagram of proposed completion 7 - 6,450' (Drinkard perfs). 4,450'-4,100' (San Andres, existing 4,450'-4,100' (San Andres, existing 4,450' - 4,100' (San Andres, existing 4,40' - 4,100' (San Andre
OTHER: □ OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 1103. For Multiple Completions: Atta or recompletion. 1. Notified NMOCD 24 hrs. prior to MI&RU. 2. Set CIBP @ 6,650' and spotted 25sx of cement on top from 6,650' 3. Displaced hole w/MLF, 9.5 ppg brine w/12.5 gel p/bbl. 4. Perf'd at 4,400', unable to EPIR. Spotted 35sx cement plug from - casing squeeze) WOC Tagged @ 4,095'. 5. Cut and pulled 2,725' of 5-1/2" casing. 6. Spotted 115sx plug from 2,775'-2,440' (8-5/8" shoe,5-1/2" stub,B Approved by NMOCD - Buddy Hill. 7. Spotted 70sx plug from 1,550'-1,295' (T. salt). 8. Spotted 70sx plug from 550'-275' (13-3/8 shoe) WOC Tagged @ so from 403' – 313'. Approved by NMOCD - Buddy Hill. 9. Spotted 30sx plug from 100'-surface. (surface) WOC Tagged @ so 10.Installed dry hole marker on 2/09/2006. Approx 1 hereby certify that the information above is true and complete to the best of my knowledge grade tank has been/will be constructed or closed according to NMOCD guidelines □, a general permit □ o SIGNATURE TITLE Manager	give pertinent dates, including estimated date ach wellbore diagram of proposed completion 7 - 6,450' (Drinkard perfs). 4,450'-4,100' (San Andres, existing 4,450'-4,100' (San Andres, existing 4,450' - 4,100' (San Andres, existing 4,40' - 4,100' (San Andre
OTHER: □ OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 1103. For Multiple Completions: Atta or recompletion. 1. Notified NMOCD 24 hrs. prior to MI&RU. 2. Set CIBP @ 6,650' and spotted 25sx of cement on top from 6,650' 3. Displaced hole w/MLF, 9.5 ppg brine w/12.5 gel p/bbl. 4. Perf'd at 4,400', unable to EPIR. Spotted 35sx cement plug from - casing squeeze) WOC Tagged @ 4,095'. 5. Cut and pulled 2,725' of 5-1/2" casing. 6. Spotted 115sx plug from 2,775'-2,440' (8-5/8" shoe,5-1/2" stub,B Approved by NMOCD - Buddy Hill. 7. Spotted 70sx plug from 1,550'-1,295' (T. salt). 8. Spotted 70sx plug from 550'-275' (13-3/8 shoe) WOC Tagged @ so from 403' – 313'. Approved by NMOCD - Buddy Hill. 9. Spotted 30sx plug from 100'-surface. (surface) WOC Tagged @ so 10.Installed dry hole marker on 2/09/2006. Approx 1 hereby certify that the information above is true and complete to the best of my knowledge grade tank has been/will be constructed or closed according to NMOCD guidelines □, a general permit □ o SIGNATURE TITLE Manager	give pertinent dates, including estimated date ach wellbore diagram of proposed completion ? - 6,450' (Drinkard perfs). 4,450'-4,100' (San Andres, existing 4,450'-4,100' (San Andres, existing . salt, Yates) WOC Tagged @ 2,573'. 403'. Re-spotted 25sx cement plug urface. wed as to plugging of the Well Bore. ty under bond is retained until e restoration is completed. and belief. I further certify that any pit or below- r an (attached) alternative OCD-approved plan □.

A