Office Office	State of New Mexico	Form C-103
District I	Energy, Minerals and Natural Resources	May 27, 2004
1625 N. French Dr., Hobbs, NM 88240 District II		WELL API NO.
1301 W. Grand Ave., Artesia, NM 88210	OIL CONSERVATION DIVISION	30-025-08826 5. Indicate Type of Lease
District III	1220 South St. Francis Dr.	STATE STATE
1000 Rio Brazos Rd., Aztec, NM 87410 District IV	Santa Fe, NM 87505	6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM	3,1,1,1,1,1,1,1,1,1,1,1,1,1,1,1,1,1,1,1	o. State On & Gas Lease No.
87505		
	AND REPORTS ON WELLS O DRILL OR TO DEEPEN OR PLUG BACK TO A	7. Lease Name or Unit Agreement Name
DIFFERENT RESERVOIR. USE "APPLICATION		State A A/G 2
PROPOSALS.)	<u> </u>	State A A/C 2 8. Well Number 20
	Vell 🛛 Other	
2. Name of Operator		9. OGRID Number
Mission Resources		10. Deal name on Wildow
3. Address of Operator 1100 Louisiana, Suite 1455 Houston TX	Z 77002	10. Pool name or Wildcat Jalmat Tansill Yates 7 Ryrs
	X / / 002	Jannat Tansin Tates / Rvis
4. Well Location		
	feet from theSouth line and	
Section 7	Township 22S Range 36I	
11.]	Elevation (Show whether DR, RKB, RT, GR, et	(c.)
	3604' GR	10 pt
Pit or Below-grade Tank Application or Closu	 -	
Pit typeDepth to Groundwater	Distance from nearest fresh water wellD	
Pit Liner Thickness: mil Be	elow-Grade Tank: Volumebbls;	Construction Material
12. Check Appro	priate Box to Indicate Nature of Notice	e, Report or Other Data
••		· · · •
NOTICE OF INTEN		BSEQUENT REPORT OF:
	IG AND ABANDON 🔲 REMEDIAL WO	
	- 	RILLING OPNS. P AND A
	_TIPLE COMPL	NT JOB 🔲
PULL OR ALTER CASING MUL		
, _	_	П
OTHER: Retest for TA Status	— ⊠ OTHER:	
OTHER: Retest for TA Status 13. Describe proposed or completed or	OTHER: operations. (Clearly state all pertinent details, a	and give pertinent dates, including estimated date
OTHER: Retest for TA Status 13. Describe proposed or completed of starting any proposed work). Starting any proposed work.	OTHER: operations. (Clearly state all pertinent details, a	
OTHER: Retest for TA Status 13. Describe proposed or completed or	OTHER: operations. (Clearly state all pertinent details, a	and give pertinent dates, including estimated date
OTHER: Retest for TA Status 13. Describe proposed or completed of starting any proposed work). Starting any proposed work.	OTHER: operations. (Clearly state all pertinent details, a	and give pertinent dates, including estimated date
OTHER: Retest for TA Status 13. Describe proposed or completed of starting any proposed work). Starting any proposed work.	OTHER: operations. (Clearly state all pertinent details, a	and give pertinent dates, including estimated date
OTHER: Retest for TA Status 13. Describe proposed or completed of starting any proposed work). So or recompletion. Test Date: 2-21-2006 7:00 AM	OTHER: operations. (Clearly state all pertinent details, and SEE RULE 1103. For Multiple Completions:	and give pertinent dates, including estimated date
OTHER: Retest for TA Status 13. Describe proposed or completed of starting any proposed work). So or recompletion.	OTHER: operations. (Clearly state all pertinent details, and SEE RULE 1103. For Multiple Completions:	and give pertinent dates, including estimated date
OTHER: Retest for TA Status 13. Describe proposed or completed of starting any proposed work). So or recompletion. Test Date: 2-21-2006 7:00 AM 1. Load casing w/2% KCL and corrosion in	OTHER: operations. (Clearly state all pertinent details, a SEE RULE 1103. For Multiple Completions: onhibitor. (Cmt. Retainer @ 3560')	and give pertinent dates, including estimated date Attach wellbore diagram of proposed completion
OTHER: Retest for TA Status 13. Describe proposed or completed of starting any proposed work). So or recompletion. Test Date: 2-21-2006 7:00 AM 1. Load casing w/2% KCL and corrosion in	OTHER: operations. (Clearly state all pertinent details, and SEE RULE 1103. For Multiple Completions:	and give pertinent dates, including estimated date Attach wellbore diagram of proposed completion
OTHER: Retest for TA Status 13. Describe proposed or completed of of starting any proposed work). So or recompletion. Test Date: 2-21-2006 7:00 AM 1. Load casing w/2% KCL and corrosion in 2. Pressure test csg. Surface to 3560' to 50	OTHER: operations. (Clearly state all pertinent details, a SEE RULE 1103. For Multiple Completions: onhibitor. (Cmt. Retainer @ 3560')	and give pertinent dates, including estimated date Attach wellbore diagram of proposed completion
OTHER: Retest for TA Status 13. Describe proposed or completed of starting any proposed work). So or recompletion. Test Date: 2-21-2006 7:00 AM 1. Load casing w/2% KCL and corrosion in	OTHER: operations. (Clearly state all pertinent details, a SEE RULE 1103. For Multiple Completions: onhibitor. (Cmt. Retainer @ 3560')	and give pertinent dates, including estimated date Attach wellbore diagram of proposed completion
OTHER: Retest for TA Status 13. Describe proposed or completed of of starting any proposed work). So or recompletion. Test Date: 2-21-2006 7:00 AM 1. Load casing w/2% KCL and corrosion in 2. Pressure test csg. Surface to 3560' to 50	OTHER: operations. (Clearly state all pertinent details, a SEE RULE 1103. For Multiple Completions: onhibitor. (Cmt. Retainer @ 3560')	and give pertinent dates, including estimated date Attach wellbore diagram of proposed completion
OTHER: Retest for TA Status 13. Describe proposed or completed of of starting any proposed work). So or recompletion. Test Date: 2-21-2006 7:00 AM 1. Load casing w/2% KCL and corrosion in 2. Pressure test csg. Surface to 3560' to 50	OTHER: operations. (Clearly state all pertinent details, a SEE RULE 1103. For Multiple Completions: onhibitor. (Cmt. Retainer @ 3560')	and give pertinent dates, including estimated date Attach wellbore diagram of proposed completion
OTHER: Retest for TA Status 13. Describe proposed or completed of of starting any proposed work). So or recompletion. Test Date: 2-21-2006 7:00 AM 1. Load casing w/2% KCL and corrosion in 2. Pressure test csg. Surface to 3560' to 50	OTHER: operations. (Clearly state all pertinent details, a SEE RULE 1103. For Multiple Completions: onhibitor. (Cmt. Retainer @ 3560')	and give pertinent dates, including estimated date Attach wellbore diagram of proposed completion
OTHER: Retest for TA Status 13. Describe proposed or completed of of starting any proposed work). So or recompletion. Test Date: 2-21-2006 7:00 AM 1. Load casing w/2% KCL and corrosion in 2. Pressure test csg. Surface to 3560' to 50	OTHER: operations. (Clearly state all pertinent details, a SEE RULE 1103. For Multiple Completions: onhibitor. (Cmt. Retainer @ 3560')	and give pertinent dates, including estimated date Attach wellbore diagram of proposed completion
OTHER: Retest for TA Status 13. Describe proposed or completed of of starting any proposed work). So or recompletion. Test Date: 2-21-2006 7:00 AM 1. Load casing w/2% KCL and corrosion in 2. Pressure test csg. Surface to 3560' to 50	OTHER: operations. (Clearly state all pertinent details, a SEE RULE 1103. For Multiple Completions: onhibitor. (Cmt. Retainer @ 3560')	and give pertinent dates, including estimated date Attach wellbore diagram of proposed completion
OTHER: Retest for TA Status 13. Describe proposed or completed of starting any proposed work). So or recompletion. Test Date: 2-21-2006 7:00 AM 1. Load casing w/2% KCL and corrosion in 2. Pressure test csg. Surface to 3560' to 50 3. TA wellbore for future use.	OTHER: operations. (Clearly state all pertinent details, a SEE RULE 1103. For Multiple Completions: onhibitor. (Cmt. Retainer @ 3560') O psi for 30 minutes. (Record test on chart for	and give pertinent dates, including estimated date Attach wellbore diagram of proposed completion OCD subsequent report)
OTHER: Retest for TA Status 13. Describe proposed or completed of starting any proposed work). So or recompletion. Test Date: 2-21-2006 7:00 AM 1. Load casing w/2% KCL and corrosion in 2. Pressure test csg. Surface to 3560' to 50 3. TA wellbore for future use.	OTHER: operations. (Clearly state all pertinent details, a SEE RULE 1103. For Multiple Completions: onhibitor. (Cmt. Retainer @ 3560') O psi for 30 minutes. (Record test on chart for the state of my knowledge)	and give pertinent dates, including estimated date Attach wellbore diagram of proposed completion OCD subsequent report)
OTHER: Retest for TA Status 13. Describe proposed or completed of starting any proposed work). So or recompletion. Test Date: 2-21-2006 7:00 AM 1. Load casing w/2% KCL and corrosion in 2. Pressure test csg. Surface to 3560' to 50 3. TA wellbore for future use.	OTHER: operations. (Clearly state all pertinent details, a SEE RULE 1103. For Multiple Completions: onhibitor. (Cmt. Retainer @ 3560') O psi for 30 minutes. (Record test on chart for the state of my knowledge)	and give pertinent dates, including estimated date Attach wellbore diagram of proposed completion OCD subsequent report)
OTHER: Retest for TA Status 13. Describe proposed or completed of starting any proposed work). So or recompletion. Test Date: 2-21-2006 7:00 AM 1. Load casing w/2% KCL and corrosion in 2. Pressure test csg. Surface to 3560' to 50 3. TA wellbore for future use.	OTHER: operations. (Clearly state all pertinent details, a SEE RULE 1103. For Multiple Completions: onhibitor. (Cmt. Retainer @ 3560') O psi for 30 minutes. (Record test on chart for a strue and complete to the best of my knowled according to NMOCD guidelines , a general permit	and give pertinent dates, including estimated date Attach wellbore diagram of proposed completion OCD subsequent report) dge and belief. I further certify that any pit or below- or an (attached) alternative OCD-approved plan
OTHER: Retest for TA Status 13. Describe proposed or completed of starting any proposed work). So or recompletion. Test Date: 2-21-2006 7:00 AM 1. Load casing w/2% KCL and corrosion in 2. Pressure test csg. Surface to 3560' to 50 3. TA wellbore for future use.	OTHER: operations. (Clearly state all pertinent details, a SEE RULE 1103. For Multiple Completions: onhibitor. (Cmt. Retainer @ 3560') O psi for 30 minutes. (Record test on chart for the state of my knowledge)	and give pertinent dates, including estimated date Attach wellbore diagram of proposed completion OCD subsequent report) dge-and belief. I further certify that any pit or below- or an (attached) alternative OCD-approved plan
OTHER: Retest for TA Status 13. Describe proposed or completed of starting any proposed work). So or recompletion. Test Date: 2-21-2006 7:00 AM 1. Load casing w/2% KCL and corrosion in 2. Pressure test csg. Surface to 3560' to 50 3. TA wellbore for future use.	OTHER: operations. (Clearly state all pertinent details, a SEE RULE 1103. For Multiple Completions: nhibitor. (Cmt. Retainer @ 3560') opsi for 30 minutes. (Record test on chart for a second to the best of my knowled according to NMOCD guidelines , a general permitation. TITLE Production Formula (Clearly state all pertinent details, a general permitation).	and give pertinent dates, including estimated date Attach wellbore diagram of proposed completion OCD subsequent report) dge and belief. I further certify that any pit or below- or an (attached) alternative OCD-approved plan
OTHER: Retest for TA Status 13. Describe proposed or completed of starting any proposed work). So or recompletion. Test Date: 2-21-2006 7:00 AM 1. Load casing w/2% KCL and corrosion in 2. Pressure test csg. Surface to 3560' to 50 3. TA wellbore for future use. I hereby certify that the information above grade tank has been/will be constructed or closed at SIGNATURE And Same	oTHER: operations. (Clearly state all pertinent details, a see RULE 1103. For Multiple Completions: onhibitor. (Cmt. Retainer @ 3560') opsi for 30 minutes. (Record test on chart for eaccording to NMOCD guidelines, a general permitation of the production for Joel Sisk E-mail address: jsisk@	and give pertinent dates, including estimated date Attach wellbore diagram of proposed completion OCD subsequent report) dge and belief. I further certify that any pit or below- or an (attached) alternative OCD-approved plan remanDATE 2-14-2006 Opetrohawk.com Telephone No.505-390-8936
OTHER: Retest for TA Status 13. Describe proposed or completed of starting any proposed work). So or recompletion. Test Date: 2-21-2006 7:00 AM 1. Load casing w/2% KCL and corrosion in 2. Pressure test csg. Surface to 3560' to 50 3. TA wellbore for future use. I hereby certify that the information above grade tank has been/will be constructed or closed at SIGNATURE Signature. Type or print name For State Use Only	oTHER: operations. (Clearly state all pertinent details, a see RULE 1103. For Multiple Completions: onhibitor. (Cmt. Retainer @ 3560') opsi for 30 minutes. (Record test on chart for eaccording to NMOCD guidelines , a general permitation of the production of the second state of the permitation of the production of	and give pertinent dates, including estimated date Attach wellbore diagram of proposed completion OCD subsequent report) dge and belief. I further certify that any pit or below- or an (attached) alternative OCD-approved plan reman
OTHER: Retest for TA Status 13. Describe proposed or completed of starting any proposed work). So or recompletion. Test Date: 2-21-2006 7:00 AM 1. Load casing w/2% KCL and corrosion in 2. Pressure test csg. Surface to 3560' to 50 3. TA wellbore for future use. I hereby certify that the information above grade tank has been/will be constructed or closed in the state Use Only APPROVED BY:	oTHER: operations. (Clearly state all pertinent details, a see RULE 1103. For Multiple Completions: onhibitor. (Cmt. Retainer @ 3560') opsi for 30 minutes. (Record test on chart for eaccording to NMOCD guidelines, a general permitation of the production for Joel Sisk E-mail address: jsisk@	and give pertinent dates, including estimated date Attach wellbore diagram of proposed completion OCD subsequent report) dge and belief. I further certify that any pit or below- or an (attached) alternative OCD-approved plan remanDATE 2-14-2006 Opetrohawk.com Telephone No.505-390-8936
OTHER: Retest for TA Status 13. Describe proposed or completed of starting any proposed work). So or recompletion. Test Date: 2-21-2006 7:00 AM 1. Load casing w/2% KCL and corrosion in 2. Pressure test csg. Surface to 3560' to 50 3. TA wellbore for future use. I hereby certify that the information above grade tank has been/will be constructed or closed at SIGNATURE Signature. Type or print name For State Use Only	oTHER: operations. (Clearly state all pertinent details, a see RULE 1103. For Multiple Completions: onhibitor. (Cmt. Retainer @ 3560') opsi for 30 minutes. (Record test on chart for eaccording to NMOCD guidelines , a general permitation of the production of the second state of the permitation of the production of	and give pertinent dates, including estimated date Attach wellbore diagram of proposed completion OCD subsequent report) dge and belief. I further certify that any pit or below- or an (attached) alternative OCD-approved plan reman