Submit 3 Copies To Appropriate District Office District I	State of New Mexico Energy, Minerals and Natural Resources		Form C-103 May 27, 2004
1625 N. French Dr., Hobbs, NM 88240 District II			WELL API NO. 30-025-28172
1301 W. Grand Ave., Artesia, NM 88210 OIL CONSERVATION DIVISION			5. Indicate Type of Lease
<u>District III</u> 1000 Rio Brazos Rd., Aztec, NM 87410	1220 South St. Fran		STATE STATE FEE
District IV	Santa Fe, NM 87	7505	6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM 87505			LG-814
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH			7. Lease Name or Unit Agreement Name Woodpecker SY State
PROPOSALS.) 1. Type of Well: Oil Well Gas Well Other			8. Well Number
1. Type of well. On well			6
Name of Operator Yates Petroleum Corporation			9. OGRID Number 025575
3. Address of Operator			10. Pool name or Wildcat
105 S. 4 th Street, Artesia, NM 88210			Saunders Permo Upper Penn
4. Well Location Unit Letter F: 1980 feet from the North line and 1980 feet from the West line			
Section 21		nge 33E	NMPM Lea County
11. Elevation (Show whether DR, RKB, RT, GR, etc.)			
4255.7' GR			
Pit or Below-grade Tank Application			
Pit type <u>Steel</u> Depth to Groundy			
Pit Liner Thickness: N/A n	nil Below-Grade Tank: Volume	N/A bbls;	Construction Material N/A
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data			
	NTENTION TO:	1	SEQUENT REPORT OF:
PERFORM REMEDIAL WORK		REMEDIAL WOR	<u> </u>
COMMILING DRILLING OF NO.			
DE NOTIFIED 24 H	DUMS PRICHME TITE	CASING/CEMEN	
OTHER CHANG OF PLL	IGGING OPERATIONS	OTHER:	П
BE NOTIFIED 24 HOUTE OPERATIONS. OTHER: OTHE			
of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.			
Yates Petroleum Corporation proposes to Plug and Abandon well as follows:			
1) Set 5-1/2" CIBP @ 9751' and dump 35' cement on plug.			
2) RIH w/tubing, circulate plugging mud and spot 100' plug (25 sx) in casing 7781-7681'.			
3) RIH w/wireline and shoot squeeze holes @ 5648'.			
4) RIH w/tubing and packer and spot 100' plug (30 sx) in and out of casing 5648-5548'.			
5) RIH w/wireline and shoot squeeze holes @ 4235'.			
6) RIH w/tubing and packer and set 100' plug (40 sx) in and out of casing 4235-4135'. Tag plug. 7) RIH w/wireline and shoot squeeze holes @ 2716'.			
8) RIH w/tubing and packer and set 100' plug (30 sx) in and out of casing 2716-2616'.			
9) RIH w/wireline and shoot squeeze holes @ 1721'.			
10) RIH w/tubing and packer and set 100' plug (30 sx) in and out of casing 1721-1621'.			
11) RIH w/wireline and shoot squeeze holes @ 520'.			
 12) RIH w/tubing and packer and set 100' plug (30 sx) in and out of casing 520-420'. Tag plug. 13) RIH w/wireline and shoot squeeze holes @ 60'. 			
14) Circulate 15 sx cement in and			
15) Cut off wellhead. Install mark			(Proposed Schematic Attached)
		- 1 - C 1 - 1 - 1	
I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been/will be constructed or closed according to NMOCD guidelines , a general permit or an (attached) alternative OCD-approved plan.			
SIGNATURE TITLE Regulatory Compliance Technician DATE 2-13-06			
Type or print name Stormi Davis E-mail address: stormid@ypcnm.com Telephone No. 505-748-1471			
For State Use Only			
APPROVED BY: Laufe. Wwk Office DREPRESENTATIVE TOTAL DATE FEB 1 7 2006			
Conditions of Approval (if any):			
U			

