Submit 3 Copies to Appropriate District Office

CONDITIONS OF APPROVAL, IF

State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103 Revised 1-1-89

DISTRICTIII 1000 Rio Brazos Rd., Aztec, NM 87410 SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" I. Type of Well: CAS	DIAICI A		a	_	
DISTRICTII P.O. Drawer DD, Artesia, NM 88210 Santa Fe, NM 87505 Sunda Fe, NM 87505 Sindicate Type of Lease State Till (Gal Lease No. 2 28861.75) SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORMC-101) FOR SUCH PROPOSALS.) 1. Type of Well: OKEL IN GAS WELL OTHER OGRID #180387 8. Well No. 27-26 3. Address of Operator 1308 LAKE STREET, SUITE 200, FORT WORTH, TX 76102 Well Location Unit Letter J 1960 Feet From The EAST Line and 1980 Feet From The SOUTH Section 34 Township 20S Range 36E NMPM LEA Section 34 Township 20S Range 36E NMPM LEA NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDON CASING TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMER PULL OR ALTER CASING CHANGE PLANS OTHER: 12. Describe Proposed or Completed Operations Clearly state all pertinent details, and give pertinent dates, including estimated date of starting an work) SEE RULE 1103. 2-2-06 SET CIBP @ 3650 W/ 25 SKS ON TOP W.O.C. & TAG @ 3227' SPOT 25 SKS @ 2000' W.O.C. & TAG @ 1910 2-3-06) Boy 1980 Hobbe NM 88241-1980				
P.O. Drawer DD, Artesia, NM 88210 DISTRICT III 1000 Rio Brazos Rd., Aztec, NM 87410 SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE: "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS. 1. Type of Well: (FORM C-101) FOR SUCH PROPOSALS.) 2. Name of Operator		-		30-025-27220	
DISTRICTIII 1000 Rio Brazos Rd., Aztec, NM 87410 SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" I. Type of Well: CAS		3			
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS. 1. Type of Well:				6. State Oil & Gas Leas	
DIFFERENT RESERVOIR, USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.) 1. Type of Well: WELL	SUNDRY NOTICES	AND REPORTS ON W	ELLS		
1. Type of Well: OLD OTHER	DIFFERENT RESERVOIF	R. USE "APPLICATION FOR PE			Agreement Name
FINLEY RESOURCES INC. 3. Address of Operator 1308 LAKE STREET, SUITE 200, FORT WORTH, TX 76102 4. Well Location Unit Letter J : 1960 Section 34 Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING TEMPORARILY ABANDON CHANGE PLANS CASING TEST AND CEMENT JOB OTHER: 12. Describe Proposed or Completed Operation (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting an work) SEE RULE 1103. 2 - 3 - 06	Type of Well: OIL WELL X GAS WELL WELL	OTHER		OGRID #18038	3 7
1308 LAKE STREET, SUITE 200, FORT WORTH, TX 76102 EUMONT:YATES-7-RIVERS-04 Well Location Unit Letter J	•				
Unit Letter J : 1960 Feet From The EAST Line and 1980 Feet From The SOUTH Section 34 Township 20S Range 36E NMPM LEA CO 10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3,575.4'GL 11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT CASING TEST AND CEMENT JOB OTHER: OTHER: 12. Describe Proposed or Completed Operation Clearly state all pertinent details, and give pertinent dates, including estimated date of starting an work) SEE RULE 1103. 2-2-06 SET CIBP @ 3650 W/ 25 SKS ON TOP W.O.C. & TAG @ 3227' SPOT 25 SKS @ 2000' W.O.C. & TAG @ 1910 2-3-06	08 LAKÊ STREET, SUITE	200, FORT WORT	H, TX 76102		
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMEN PULL OR ALTER CASING OTHER: 12. Describe Proposed or Completed Operation (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting an work) SEE RULE 1103. 2-2-06 SET CIBP @ 3650 W/ 25 SKS ON TOP W.O.C. & TAG @ 3227' SPOT 25 SKS @ 2000' W.O.C. & TAG @ 1910 2-3-06	7 1060	eet From The <u>EAST</u>	Line and 1980	Feet From The	SOUTH Line
Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PULL OR ALTER CASING OTHER: 12. Describe Proposed or Completed Operation Clearly state all pertinent details, and give pertinent dates, including estimated date of starting an work) SEE RULE 1103. 2-2-06 SET CIBP @ 3650 W/ 25 SKS ON TOP W.O.C. & TAG @ 3227' SPOT 25 SKS @ 2000' W.O.C. & TAG @ 1910 2-3-06	Section 34 T	ownship Ka	nige		LEA County
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMER CASING TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMER CASING TEST AND CEMENT JOB OTHER: 12. Describe Proposed or Completed Operation (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting an work) SEE RULE 1103. 2-2-06 SET CIBP @ 3650 W/ 25 SKS ON TOP W.O.C. & TAG @ 3227' SPOT 25 SKS @ 2000' W.O.C. & TAG @ 1910 2-3-06		10. Elevation (Show wheth 3,575.4 'GL	ner DF, RKB, RT, GR, etc	.)	
PERFORM REMEDIAL WORK PLUG AND ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT CASING TEST AND CEMENT JOB OTHER: 12. Describe Proposed or Completed Operation Clearly state all pertinent details, and give pertinent dates, including estimated date of starting an work) SEE RULE 1103. 2-2-06 SET CIBP @ 3650 W/ 25 SKS ON TOP W.O.C. & TAG @ 3227' SPOT 25 SKS @ 2000' W.O.C. & TAG @ 1910 2-3-06	Check Appro	priate Box to Indicat	e Nature of Noti	ce, Report, or O	ther Data
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT CASING TEST AND CEMENT JOB OTHER: 12. Describe Proposed or Completed Operation Clearly state all pertinent details, and give pertinent dates, including estimated date of starting an work) SEE RULE 1103. 2-2-06 SET CIBP @ 3650 W/ 25 SKS ON TOP W.O.C. & TAG @ 3227' SPOT 25 SKS @ 2000' W.O.C. & TAG @ 1910 2-3-06	NOTICE OF INTENT	ΓΙΟΝ ΤΟ:	SUB	SEQUENT REP	ORT OF:
PULL OR ALTER CASING CASING TEST AND CEMENT JOB OTHER: 12. Describe Proposed or Completed Operation Clearly state all pertinent details, and give pertinent dates, including estimated date of starting an work) SEE RULE 1103. 2-2-06 SET CIBP @ 3650 W/ 25 SKS ON TOP W.O.C. & TAG @ 3227' SPOT 25 SKS @ 2000' W.O.C. & TAG @ 1910 2-3-06	FORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK	ALTE	RING CASING
OTHER: 12. Describe Proposed or Completed Operation Clearly state all pertinent details, and give pertinent dates, including estimated date of starting an work) SEE RULE 1103. 2-2-06 SET CIBP @ 3650 W/ 25 SKS ON TOP W.O.C. & TAG @ 3227' SPOT 25 SKS @ 2000' W.O.C. & TAG @ 1910 2-3-06	IPORARILY ABANDON 📙 (CHANGE PLANS	COMMENCE DRILLING	OPNS. 📙 PLUG	AND ABANDONMENT
12. Describe Proposed or Completed Operation Clearly state all pertinent details, and give pertinent dates, including estimated date of starting an work) SEE RULE 1103. 2-2-06 SET CIBP @ 3650 W/ 25 SKS ON TOP W.O.C. & TAG @ 3227' SPOT 25 SKS @ 2000' W.O.C. & TAG @ 1910 2-3-06	L OR ALTER CASING		CASING TEST AND CE	MENT JOB	
work) SEE RULE 1103. 2-2-06 SET CIBP @ 3650 W/ 25 SKS ON TOP W.O.C. & TAG @ 3227' SPOT 25 SKS @ 2000' W.O.C. & TAG @ 1910 2-3-06	IER:		OTHER:		
SET CIBP @ 3650 W/ 25 SKS ON TOP W.O.C. & TAG @ 3227' SPOT 25 SKS @ 2000' W.O.C. & TAG @ 1910 2-3-06	Describe Proposed or Completed Operation work) SEE RULE 1103.	onsClearly state all pertinent de	etails, and give pertinent	dates, including estimat	ed date of starting any prop
	SET CIBP @ 3650 W/ 25 SKS ON SPOT 25 SKS @ 2000' W.O.C. &		27'		200 TO 100 TO 10
INSTALL P&A MARKER CIRCULATE MUD Approved as to plugging of the Well Bore. Caption of the Well Bore.	SPOT 40 SKS 400' TO SURFACE				2 May 2002 1
I hereby certify that the information above is true and complete to the best of my knowledge and belief. SIGNATURE	SPOT 40 SKS 400' TO SURFACE INSTALL P&A MARKER				Z. 29Z9Z VIELLY
TYPE OR PRINT NAME JEFF KESTER / DAVID A. EYLER TELEPHONE NO. 432)687	SPOT 40 SKS 400° TO SURFACE INSTALL P&A MARKER CIRCULATE MUD	surface restoration is com	edge and belief.	GENT	2 2 06
132700	SPOT 40 SKS 400' TO SURFACE INSTALL P&A MARKER CIRCULATE MUD ereby certify that the information above is true an	surface restoration is com	edge and belief.		рате 2-3-06