Submit 3 Copies To Appropriate District Office State of New Mexico	Form C-103
District I Energy, Minerals and Natural Resources	
1625 N. French Dr., Hobbs, NM 88240	WELL API NO.
District II 1301 W. Grand Ave., Artesia, NM 88210 OIL CONSERVATION DIVISION	30-025-09296
District III 1220 South St. Francis Dr.	5. Indicate Type of Lease
1000 Rio Brazos Rd., Aztec, NM 87410	STATE S FEE
District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505	6. State Oil & Gas Lease No.
SUNDRY NOTICES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	State A A/C 1
1. Type of Well: Oil Well Gas Well Other	8. Well Number 86
2. Name of Operator	9. OGRID Number
Mission Resources	
3. Address of Operator	10. Pool name or Wildcat
1100 Louisiana, Suite 1455 Houston TX 77002	Langlie Mattix 7 Rvrs Queen GB
4. Well Location	
Unit LetterF: 1980feet from theNorth line and	1980 feet from the West line
Section 10 Township 23S Range	36E NMPM Lea County
11. Elevation (Show whether DR, RKB, RT, GR,	
3460' GL	ero.
Pit or Below-grade Tank Application or Closure	
Pit typeDepth to GroundwaterDistance from nearest fresh water well	Distance from nearest surface water
	; Construction Material
12. Check Appropriate Box to Indicate Nature of Not	ice, Report or Other Data
NOTICE OF INTENTION TO:	HIRSEOHENT DEDORT OF
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING	
	EDRILLING OPNS. PAND A
PULL OR ALTER CASING MULTIPLE COMPL CASING/CEI	_
OTHER: OTHER:	T/A Test
OTHER: OTHER: OTHER: OTHER:	T/A Test s, and give pertinent dates, including estimated date
OTHER: OTHER: OTHER: OTHER: OTHER: OTHER: OTHER: OTHER: OTHER:	T/A Test s, and give pertinent dates, including estimated date
OTHER: OTHER: OTHER: OTHER:	T/A Test s, and give pertinent dates, including estimated date
OTHER: OTHER: OTHER: OTHER: OTHER: OTHER: OTHER: OTHER: OTHER:	T/A Test s, and give pertinent dates, including estimated date
OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent detail of starting any proposed work). SEE RULE 1103. For Multiple Completions or recompletion. Test Date: 2-21-2006	T/A Test s, and give pertinent dates, including estimated date
OTHER: OTHER: OTHER: OTHER: OTHER: OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent detail of starting any proposed work). SEE RULE 1103. For Multiple Completions or recompletion. Test Date: 2-21-2006 1. Load casing w/ 2% KCL and corrosion inhibitor. (CIBP @ 3600' w/ 35' cmt.)	T/A Test s, and give pertinent dates, including estimated date
OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent detail of starting any proposed work). SEE RULE 1103. For Multiple Completions or recompletion. Test Date: 2-21-2006	T/A Test s, and give pertinent dates, including estimated date
OTHER: OTHER: OTHER: OTHER: OTHER: OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent detail of starting any proposed work). SEE RULE 1103. For Multiple Completions or recompletion. Test Date: 2-21-2006 1. Load casing w/ 2% KCL and corrosion inhibitor. (CIBP @ 3600' w/ 35' cmt.)	T/A Test s, and give pertinent dates, including estimated date
OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent detail of starting any proposed work). SEE RULE 1103. For Multiple Completions or recompletion. Test Date: 2-21-2006 1. Load casing w/ 2% KCL and corrosion inhibitor. (CIBP @ 3600' w/ 35' cmt.) 2. Pressure test csg surface to 3600' to 500 psi for 30 minutes. (See attached chart) 3. Request 90 days to bring well into compliance.	T/A Test s, and give pertinent dates, including estimated date Attach wellbore diagram of proposed completion
OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent detail of starting any proposed work). SEE RULE 1103. For Multiple Completions or recompletion. Test Date: 2-21-2006 1. Load casing w/ 2% KCL and corrosion inhibitor. (CIBP @ 3600' w/ 35' cmt.) 2. Pressure test csg surface to 3600' to 500 psi for 30 minutes. (See attached chart) 3. Request 90 days to bring well into compliance.	T/A Test s, and give pertinent dates, including estimated date Attach wellbore diagram of proposed completion
OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent detail of starting any proposed work). SEE RULE 1103. For Multiple Completions or recompletion. Test Date: 2-21-2006 1. Load casing w/ 2% KCL and corrosion inhibitor. (CIBP @ 3600' w/ 35' cmt.) 2. Pressure test csg surface to 3600' to 500 psi for 30 minutes. (See attached chart) 3. Request 90 days to bring well into compliance.	T/A Test s, and give pertinent dates, including estimated date
OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent detail of starting any proposed work). SEE RULE 1103. For Multiple Completions or recompletion. Test Date: 2-21-2006 1. Load casing w/ 2% KCL and corrosion inhibitor. (CIBP @ 3600' w/ 35' cmt.) 2. Pressure test csg surface to 3600' to 500 psi for 30 minutes. (See attached chart) 3. Request 90 days to bring well into compliance.	T/A Test s, and give pertinent dates, including estimated date Attach wellbore diagram of proposed completion
OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent detail of starting any proposed work). SEE RULE 1103. For Multiple Completions or recompletion. Test Date: 2-21-2006 1. Load casing w/ 2% KCL and corrosion inhibitor. (CIBP @ 3600' w/ 35' cmt.) 2. Pressure test csg surface to 3600' to 500 psi for 30 minutes. (See attached chart) 3. Request 90 days to bring well into compliance.	T/A Test s, and give pertinent dates, including estimated date Attach wellbore diagram of proposed completion
OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent detail of starting any proposed work). SEE RULE 1103. For Multiple Completions or recompletion. Test Date: 2-21-2006 1. Load casing w/ 2% KCL and corrosion inhibitor. (CIBP @ 3600' w/ 35' cmt.) 2. Pressure test csg surface to 3600' to 500 psi for 30 minutes. (See attached chart) 3. Request 90 days to bring well into compliance.	T/A Test s, and give pertinent dates, including estimated date Attach wellbore diagram of proposed completion
OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent detail of starting any proposed work). SEE RULE 1103. For Multiple Completions or recompletion. Test Date: 2-21-2006 1. Load casing w/ 2% KCL and corrosion inhibitor. (CIBP @ 3600' w/ 35' cmt.) 2. Pressure test csg surface to 3600' to 500 psi for 30 minutes. (See attached chart) 3. Request 90 days to bring well into compliance.	T/A Test s, and give pertinent dates, including estimated date Attach wellbore diagram of proposed completion
OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent detail of starting any proposed work). SEE RULE 1103. For Multiple Completions or recompletion. Test Date: 2-21-2006 1. Load casing w/ 2% KCL and corrosion inhibitor. (CIBP @ 3600' w/ 35' cmt.) 2. Pressure test csg surface to 3600' to 500 psi for 30 minutes. (See attached chart) 3. Request 90 days to bring well into compliance. This Approve Abandonment	T/A Test s, and give pertinent dates, including estimated date Attach wellbore diagram of proposed completion To Temporary A Expires
OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent detail of starting any proposed work). SEE RULE 1103. For Multiple Completions or recompletion. Test Date: 2-21-2006 1. Load casing w/ 2% KCL and corrosion inhibitor. (CIBP @ 3600' w/ 35' cmt.) 2. Pressure test csg surface to 3600' to 500 psi for 30 minutes. (See attached chart) 3. Request 90 days to bring well into compliance. This Approvation and the proves the proves the proves and proves the proves	T/A Test s, and give pertinent dates, including estimated date Attach wellbore diagram of proposed completion Temporary Attach Expires Pledge and belief. I further certify that any pit or below-
OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent detail of starting any proposed work). SEE RULE 1103. For Multiple Completions or recompletion. Test Date: 2-21-2006 1. Load casing w/ 2% KCL and corrosion inhibitor. (CIBP @ 3600' w/ 35' cmt.) 2. Pressure test csg surface to 3600' to 500 psi for 30 minutes. (See attached chart) 3. Request 90 days to bring well into compliance. This Approve Abandonment	T/A Test s, and give pertinent dates, including estimated date Attach wellbore diagram of proposed completion Temporary Attach Expires Pledge and belief. I further certify that any pit or below-
OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent detail of starting any proposed work). SEE RULE 1103. For Multiple Completions or recompletion. Test Date: 2-21-2006 1. Load casing w/ 2% KCL and corrosion inhibitor. (CIBP @ 3600' w/ 35' cmt.) 2. Pressure test csg surface to 3600' to 500 psi for 30 minutes. (See attached chart) 3. Request 90 days to bring well into compliance. This Approvation and the information above is true and complete to the best of my know grade tank has been/will be constructed or closed according to NMOCD guidelines , a general permitation and the constructed or closed according to NMOCD guidelines , a general permitation and the constructed or closed according to NMOCD guidelines , a general permitation and the constructed or closed according to NMOCD guidelines , a general permitation and the constructed or closed according to NMOCD guidelines , a general permitation and the constructed or closed according to NMOCD guidelines , a general permitation and the constructed or closed according to NMOCD guidelines .	T/A Test s, and give pertinent dates, including estimated date Attach wellbore diagram of proposed completion Temporary Attach Expires Attach wellbore diagram of proposed completion Temporary Attach Expires Attach Wellbore diagram of proposed completion Temporary Attach wellbore diagram of proposed completion Temporary Attach wellbore diagram of proposed completion Temporary Attach wellbore diagram of proposed completion
OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent detail of starting any proposed work). SEE RULE 1103. For Multiple Completions or recompletion. Test Date: 2-21-2006 1. Load casing w/ 2% KCL and corrosion inhibitor. (CIBP @ 3600' w/ 35' cmt.) 2. Pressure test csg surface to 3600' to 500 psi for 30 minutes. (See attached chart) 3. Request 90 days to bring well into compliance. This Approvation above is true and complete to the best of my know grade tank has been/will be constructed or closed according to NMOCD guidelines , a general perm SIGNATURE	T/A Test s, and give pertinent dates, including estimated date Attach wellbore diagram of proposed completion Temporary It Expires Pledge and belief. I further certify that any pit or belowit or an (attached) alternative OCD-approved plan Temant
OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent detail of starting any proposed work). SEE RULE 1103. For Multiple Completions or recompletion. Test Date: 2-21-2006 1. Load casing w/ 2% KCL and corrosion inhibitor. (CIBP @ 3600° w/ 35° cmt.) 2. Pressure test csg surface to 3600° to 500 psi for 30 minutes. (See attached chart) 3. Request 90 days to bring well into compliance. This Approve Abandonme Signature of the best of my known grade tank has been/will be constructed or closed according to NMOCD guidelines , a general perm SIGNATURE SIGNATURE Joel Sisk E-mail address: jsisk For State Use Only	T/A Test s, and give pertinent dates, including estimated date Attach wellbore diagram of proposed completion Temporary Temporary Attach wellbore diagram of proposed completion Temporary Te
OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent detail of starting any proposed work). SEE RULE 1103. For Multiple Completions or recompletion. Test Date: 2-21-2006 1. Load casing w/ 2% KCL and corrosion inhibitor. (CIBP @ 3600' w/ 35' cmt.) 2. Pressure test csg surface to 3600' to 500 psi for 30 minutes. (See attached chart) 3. Request 90 days to bring well into compliance. This Approvation and the information above is true and complete to the best of my known grade tank has been/will be constructed or closed according to NMOCD guidelines , a general perm SIGNATURE SIGNATURE Joel Sisk E-mail address: jsisk For State Use Only Possible Prepresentation	T/A Test s, and give pertinent dates, including estimated date Attach wellbore diagram of proposed completion Temporary It Expires Attach wellbore diagram of proposed completion Temporary It Expires DATE 2-23-2006 Appetrohawk.com Telephone No. 505-390-8936 WE HYSTAFF MANAGES
OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent detail of starting any proposed work). SEE RULE 1103. For Multiple Completions or recompletion. Test Date: 2-21-2006 1. Load casing w/ 2% KCL and corrosion inhibitor. (CIBP @ 3600° w/ 35° cmt.) 2. Pressure test csg surface to 3600° to 500 psi for 30 minutes. (See attached chart) 3. Request 90 days to bring well into compliance. This Approve Abandonme Signature of the best of my known grade tank has been/will be constructed or closed according to NMOCD guidelines , a general perm SIGNATURE SIGNATURE Joel Sisk E-mail address: jsisk For State Use Only	T/A Test s, and give pertinent dates, including estimated date Attach wellbore diagram of proposed completion Temporary Temporary Attach wellbore diagram of proposed completion Temporary

