State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103 Revised 5-27-2004

FILE IN TRIPLICATE	OIL CONSERVA	ATION DIVISION		
<u>DISTRICT I</u> 1625 N. French Dr. , Hobbs, NM 88240	1220 South St. Francis Dr. Santa Fe, NM 87505		WELL API NO. 30-025-37558	
DISTRICT II	,		5. Indicate Type of Lease	
1301 W. Grand Ave, Artesia, NM 88210			STATE X	FEE
DISTRICT III			6. State Oil & Gas Lease No.	
1000 Rio Brazos Rd, Aztec, NM 87410				
SUNDRY NOTICES AND REPORTS ON WELLS			7. Lease Name or Unit Agreen	nent Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A			NORTH HOBBS (G/SA) UNIT	
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (Form C-101) for such proposals.)			Section 29	
1. Type of Well:			8. Well No. 712	
Oil Well Gas Well Other Injector				
2. Name of Operator			9. OGRID No. 157984	
Occidental Permian Ltd.				
3. Address of Operator			10. Pool name or Wildcat	HOBBS (G/SA)
1017 W. Stanolind Rd., HOBBS, NM 882	40 505/39	7-8200		
4. Well Location				
Unit Letter E : 2378 Feet	From The NORTH	1000	et From The WEST	Line
Section 29	Township 18-S	Range 38-	E NMPM	LEA County
	evation (Show whether DF, RK 'GR	B, RT GR, etc.)		
Pit or Below-grade Tank Application	or Closure			
Pit Type Depth of Ground Water _		earest fresh water well	Distance from nearest si	irface water
				irrace water
Pit Liner Thickness mil Below-	Grade Tank: Volume	bbls; Construction Ma	aterial	
12. Check Appro	miata Pay to Indicate Na	ture of Notice, Report, or	Other Data	
NOTICE OF INTENTIO			SEQUENT REPORT O	F:
PERFORM REMEDIAL WORK PLUG	AND ABANDON	REMEDIAL WORK	ALTERING	G CASING
TEMPORARILY ABANDON CHAN	GE PLANS	COMMENCE DRILLING OF	PNS. PLUG & A	ABANDONMENT
	e Completion	CASING TEST AND CEME	NT JOB	
•	e Completion		<u>—</u>	Tv.
OTHER:		OTHER:	New Well Completion	n X
13. Describe Proposed or Completed Operations proposed work) SEE RULE 1103. For Multiple RULE 1103. For Multiple RULE 1103.	Clearly state all pertinent de iple Completions: Attach w	etails, and give pertinent date rellbore diagram of proposed	s, including estimated date of scompletion or recompletion.	starting any
1. RUPU. Drill out DV tool @3514'. Tag P.	RTD @4326'			
 RUPU. Drill out DV tool @3514'. Tag P. Run HNGS/CNL/CCL/SCMT log from 4 	310 @4320 . 326' to surf w/1500 psi on	rea		
3. Perforate the following intervals; 4124-39	. 4148-51, 4173-76, 4179	-86, 4188-93, 4196-4207, 4	211-14, 4230-39, 4243-46, 4	251-54, 4159-64,
4276, 4281-84, 4288-93, and 4297-4300 t				,
4. Stimulate perfs 4124 to 4300 w/6200 g 1:				
5. RIH w/5.5" G-6 pc pkr, XL on/off tool w			set @4084'.	
6. Circ csg w/90 bbl pkr fluid. Tst csg to 600) psi for 30 min and chart	for the NMOCD.	/A ^V	(N)
7. RDPU. Clean Location.			$\sqrt{2}$	
Rig Up Date: 02/16/2006			2526 ∂26	" The same of the
Rig Down Date: 02/24/2006			/ Z	onbs
I hereby certify that the information above is true and c	omplete to the best of my know	ledge and belief. I further certify	that any pit or below-grade tank	has been/will be
constructed or closed according to NMOCD guidelines	, a general permit	or an (attached) alternative	ve OCD-approved	1 🕠
Closed according to MMOCD guidennes	, a general permit	plan	OS approved	600
SIGNATURE ROPELL Fill	at		mpletion Specialist DAT	E 02/27/2006
TYPE OR PRINT NAME Robert Gilbert	E-mail address:	robert_gilbert@oxy.com	TELEPHONE NO	505/397-8206
For State Use Only				
APPROVED BY	- /	TITLE D	DA	TE MAD A A A

CONDITIONS OF APPROVAL IF ANY:

