

DISTRICT I

P.O. Box 1980, Hobbs, NM 88240

DISTRICT II

P.O. Box Drawer DD, Artesia, NM 88210

DISTRICT III

1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088

Santa Fe, New Mexico 87504-2088

WELL API NO. 30-025-06899
5. Indicate Type of Lease STATE ☐ FEE ☒
6. State Oil/Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT (FORM C-101) FOR SUCH PROPOSALS.

1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Lease Name or Unit Agreement Name CENTRAL DRINKARD UNIT
2. Name of Operator CHEVRON USA INC	8. Well No. 106
3. Address of Operator 15 SMITH RD, MIDLAND, TX 79705	9. Pool Name or Wildcat DRINKARD
4. Well Location Unit Letter <u>B</u> : <u>660'</u> Feet From The <u>NORTH</u> Line and <u>1980'</u> Feet From The <u>EAST</u> Line Section <u>29</u> Township <u>21-S</u> Range <u>37-E</u> NMPM <u>LEA</u> COUNTY	
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	COMMENCE DRILLING OPERATION <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>
OTHER: <input type="checkbox"/>	OTHER: REMOVE WHIPSTOCK <input checked="" type="checkbox"/>
PLUG AND ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
CHANGE PLANS <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

2-02-06: MIRU.
2-03-06: TOH W/165 JTS 2 7/8" TBG. RU SWAB. SWAB TBG DN.
2-06-06: SWAB TBG DAY. TIH W/WHIPSTOCK HOOK, BMPR SUB, JARS, X-OVER, 2 7/8" WS.
2-07-06: TAG WHIPSTOCK. RU REV UNIT & PMP DN TBG. RDRU. LATCH ONTO WHIP & JAR LOOSE.
2-08-06: BREAK APART FISH FROM OVERSHOT. TIH W/164 JTS WS W/BIT. LOAD & PRESSURE CSG WITH FOAM & ESTAB CIRC. BLOW WELL DOWN.
2-09-06: CIRC W/FOAM. TIH & TAG CIBP @ 6473. DRILL W/FOAM ON CIBP. FELL THRU CIBP. PUSH CIBPS TO 6577. PUSH CIBPS TO 6641'.
2-10-06: LD WS.
2-13-06: TIH W/199 JTS 2 7/8" TBG, TAC, SN, PERF SUB, BPMJ.
2-14-06: SET TAC W/15 POINTS PULLED. TIH W/INSERT PUMP & RODS. SPACE OUT PUMP. LOAD & TEST.
2-15-06: UNSEAT PUMP. REL TAC.
2-16-06: TIH W/SN & PROD TBG. RU SWAB LINE.
2-17-06: TIH W/TBG. TAG TD & PULL 1 JT. TIH W/SWAB.
2-20-06: TIH W/MUD JOINT OPEN END W/COLLAR, DESANDER, TBG SUB, SN, TBG & TAC. SET TAC W/15 PTS. TIH W/PMP & RODS. RIG DOWN. FINAL REPORT

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Denise Pinkerton TITLE Regulatory Specialist DATE 2/22/2006
TYPE OR PRINT NAME Denise Pinkerton Telephone No. 432-687-7375

(This space for State Use)

APPROVED Long W. Wink TITLE OC FIELD REPRESENTATIVE II/STAFF MANAGER
CONDITIONS OF APPROVAL IF ANY: DATE

MAR 10 2006